

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 34433

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0341/2020/NS
Date : 30-Mar-20

Vehicle IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

*Hi Adrian,
9 days exclude 1 Sunday and 1 PH
jb 9 Jun 20*

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Loh Shu Ming
Address : Blk 617B Edgefield Plains
#03-351
Singapore 822671
Telephone : HP +65 96493066
Type of Claim : Own Damage Claims
Policy No. : 1900167425
Vehicle No : **SMP 4083 X**
Model Code : Audi A4 Sedan 2.0 TFSI 8W
Model / Year : Sep-19
Engine No : CVK 086442
Chassis No : WAUZZZF42KA104740
Mileage : 12538
Date In : 27-Mar-20
Estimated By : Johnny Boo / Allan Wu
Accident Date : 27-Mar-20
Place of Accident : Woodlands Industries Park E9/E6 Junction

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMP 4083 X

<u>S/N</u>	<u>Nature of Jobs</u>		<u>Estimated Charges</u>		<u>Surveyor's Recommendations</u>
1	To tow back from accident scene.	S/N \$	280.00		
2	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$	480.00	\$	480.00
3	To remove and renew aircond condenser, charged air cooler and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$	1,200.00		
4	To install solar film for lhs front door window glass.	S/N \$	400.00	\$	400.00
5	To renew lhs front wheel suspension assy. To inspect for further damages.	S/N \$	1,800.00	na	
SUB TOTAL LABOUR CHARGES		:	\$ 4,160.00	\$	880.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMP 4083 X

S/N	Nature of Jobs		Estimated Charges		Surveyor's Recommendations
		<i>c/f</i>		\$	880.00
6	To remove and transfer lhs front door's multi-lock system and power window devices. Inspect for damages.	S/N	\$ 280.00	\$	280.00
7	To dismantle lhs front door panel trim.	S/N	\$ 350.00		
8	To dismantle and renew front bumper, bonnet, lhs front fender, lhs headlight and lhs front door. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.		\$ 5,950.00	\$	2,250.00
9	To respray front bumper, lhs front fender, bonnet, hinges, lhs front door, lhs wing mirror cover and lhs sill panel.		\$ 5,300.00	\$	2,350.00
10	To renew lhs front rim. To carry out pre-wheel alignment and post-wheel alignment test.	S/N	\$ 520.00	\$	520.00
11	To carry out diagnostic check.	S/N	\$ 384.00	\$	384.00
TOTAL LABOUR CHARGES			\$ 16,944.00	\$	6,664.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMP 4083 X

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 2,068.00	1654.4
2	FRONT BUMPER FIXING PARTS	\$ 553.00	
3	FRONT BUMPER SECURING STRIP	2 \$ 67.00	
4	FRONT BUMPER GRILLE - CENTRE	\$ 185.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 198.00	158
6	FRONT BUMPER AIR GUIDE - LH	\$ 59.00	
7	RADIATOR GRILLE	\$ 2,058.00	1646.4
8	FRONT BUMPER AIR GUIDE GRILLE - LH	\$ 344.00	275.2
9	FRONT BUMPER CARRIER	\$ 757.00	
10	FRONT BUMPER FOAM FILLER PIECE	\$ 117.00	93.6
11	FRONT BUMPER COVER	\$ 120.00	96
12	FRONT BUMPER GUIDE SECTION - LH	\$ 34.00	27.12
13	FRONT BUMPER BRACKET - LH	\$ 214.00	
14	CAUTION SIGN STICKER	NEC \$ 13.00	10.24
15	AIRCON STICKER	NEC \$ 7.00	5.36
16	LOCK CARRIER BRACKET	\$ 129.00	103.2
17	FRONT BUMPER SUPPORT - LH / RH	2 \$ 54.00	
18	HORN - LH HIGH TONE	\$ 38.00	
19	SPRING SHACKLE - LH	\$ 27.00	
20	FRONT PARKING AID SENSOR - INNER / OUTER	1 \$ 245.50	196.4
SUB TOTAL SPARE PARTS CHARGES		\$ 7,287.50	4265.92

Premium Automobiles55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMP 4083 X

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/Nett	Remarks
		<i>c/f</i>	\$ 4,265.92
21	FRONT PARKING AID SEAL RING	4 \$	14.00
22	FRONT FENDER - LH	\$	722.00 \$ 577.60
23	FRONT FENDER ATTACHMENT PARTS	\$	190.00
24	FRONT FENDER CLOSING ELEMENT - LH	\$	47.00
25	FRONT FENDER BRACKET - LH	\$	33.00 \$ 26.24
26	DEFORMATION ELEMENT BRACKET - LH	\$	46.00 \$ 36.80
27	FRONT FENDER BRACKET	\$	30.00 \$ 23.52
28	FRONT FENDER UPPER BRACKET - LH	\$	32.00 \$ 24.96
29	FRONT FENDER BRACE - LH	\$	112.00 \$ 89.20
30	FRONT FENDER CLOSING ELEMENT - LH	\$	31.00
31	FRONT FENDER COVER - LH	\$	11.00 \$ 8.56
32	WHEEL HOUSING LINER - LH	\$	226.00 \$ 180.40
33	WHEEL HOUSING LINER ATTACHMENT PARTS	\$	219.00
34	WHEEL SPOILER - LH	\$	69.00 \$ 55.04
35	WHEEL SPOILET TRIM - LH	\$	33.00
36	STONE CHIP GUARD - LH	\$	48.00 \$ 37.92
37	BONNET	\$	2,634.00 \$ 2,107.20
38	BONNET ATTACHMENT PARTS	\$	388.00
39	BONNET LID HINGE - LH / RH	2 \$	574.00
40	BONNET IMPACT PROTECTION - CENTRE	\$	26.00 \$ 20.56
SUB TOTAL SPARE PARTS CHARGES		:	\$ 5,485.00 \$ 7,453.92

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMP 4083 X

S/N	Parts Description	Damage Parts & Prices		Remarks
			S/Nett	
		<i>c/f</i>		\$ 7,453.92
41	BONNET IMPACT PROTECTION - LH / RH	2 \$	52.00	\$ 41.36
42	FENDER LEDGE COVER - LH INNER	\$	58.00	
43	FENDER LEDGE COVER - LH	\$	29.00	
44	FENDER LEDGE COVER - LH	\$	21.00	\$ 16.72
45	BONNET GAS FILLED STRUT	2 \$	224.00	
46	BONNET STRIKER - LH / RH	2 \$	94.00	
47	BONNET LID LOCK	2 \$	403.00	
48	BONNET BOWDEN CABLE - CENTRE	\$	54.00	
49	BONNET BOWDEN CABLE	\$	54.00	
50	BONNET RELEASE LEVER	\$	13.00	
51	PLENUM CHAMBER COVER	\$	92.00	
52	BONNET SOUND ABSORBER	\$	323.00	
53	LED HEADLIGHT - LH	\$	7,321.00	\$ 5,856.80
54	MAIN LIGHT ELECTRONICS POWER MODULE	\$	732.00	
55	LIGHT CONTROL SYSTEM CONTROL UNIT	\$	707.00	
56	HEADLAMP HOUSING REPAIR KIT - LH	\$	124.00	
57	HEADLIGHT HOSE - LH	\$	34.00	
58	LIFT CYLINDER - LH	\$	198.00	\$ 158.00
59	LIFT CYLINDER CORRUGATED PIPE	\$	88.00	
60	LOCK CARRIER	\$	956.00	
SUB TOTAL SPARE PARTS CHARGES :		\$	11,577.00	\$ 13,526.80

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMP 4083 X

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
	<i>c/f</i>		\$ 13,526.80
61	COOLANT REGULATOR SUPPORT	2 \$ 71.00	
62	AIRCON CONDENSER	\$ 586.00	
63	REFRIGERANT LINE	\$ 157.00	
64	REFRIGERANT LINE	\$ 320.00	
65	CHARGE AIR COOLER	\$ 552.00	
66	PRESSURE PIPE - LH	\$ 402.00	
67	RADIATOR AIR GUIDE - LH	\$ 27.00	
68	RADIATOR AIR GUIDE - LH	\$ 12.00	
69	RADIATOR AIR GUIDE - LOWER	\$ 21.00	
70	RADIATOR AIR GUIDE - UPPER	\$ 15.00	
71	FRONT DOOR - LH	\$ 2,243.00	\$ 1,794.40
72	FRONT DOOR OUTER SEAL - LH	NEC \$ 193.00	\$ 154.40
73	BONDING AGENT	NEC \$ 46.00	\$ 36.72
74	CLEANING SOLUTION	NEC \$ 64.00	\$ 51.20
75	FRONT DOOR ATTACHMENT PARTS	\$ 828.00	
76	FRONT DOOR CATCH	\$ 99.00	
77	EXTERIOR MIRROR MOUNTING - LH	\$ 1,025.00	\$ 820.00
78	MIRROR CAP - LH	\$ 249.00	\$ 199.20
79	MIRROR GLASS - LH	\$ 1,137.00	\$ 909.60
80	WINDOW SLOT SEAL - LH	\$ 289.00	\$ 230.80
SUB TOTAL SPARE PARTS CHARGES		: \$ 8,336.00	\$ 17,723.12

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMP 4083 X

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
			\$ 17,723.12
	<i>c/f</i>		
81	WINDOW GUIDE TRIM STRIP	\$ 242.00	
82	CORNER TRIM - LH	\$ 43.00	
83	FRONT DOOR WINDOW - LH	\$ 273.00	\$ 218.00
84	FRONT WISHBONE LINK - LH	\$ 507.00	
85	FRONT SUSPENSION GUIDE - LH	\$ 887.00	
86	UPPER CONTROL ARM - LH	\$ 480.00	
87	REAR UPPER CONTROL ARM - LH	\$ 480.00	
88	WHEEL BEARING HOUSING - LH	\$ 912.00	
89	SWIVEL JOINT	\$ 182.00	
90	WHEEL HUB	\$ 460.00	
91	SUSPENSION FORKS - LH	\$ 249.00	
92	COUPLING RODS	\$ 125.00	
93	GAS SHOCK ABSORBER	\$ 284.00	
94	TRACK ROD	\$ 93.00	
95	STEERING GEAR GREASE	\$ 41.00	
96	TIE ROD END	\$ 186.00	
97	DOUBLE ANGLED BALL BEARING	\$ 237.00	
98	FRONT RIM - LH	TBC	
99	FRONT NO PLATE	S/N \$ 60.00	\$ 60.00
100	SUNDRIES	\$ 500.00	\$ 98.72
	TOTAL SPARE PARTS CHARGES	\$ 38,926.50	\$ 18,099.84
	TOTAL LABOUR CHARGES	\$ 16,944.00	\$ 6,664.00
	GRAND TOTAL	\$ 55,870.50	\$ 24,763.84

All charges are not inclusive of GST.

Legend Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant