

Premium Automobiles

11, 12th Road 1, Singapore 406699
Tel: 6356 2322 Fax: 6841 1183

Tel/fax

Material List for Accident Vehicle Regn No. SMP 4083 X

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/Nett		
1	FRONT BUMPER <i>distorted</i>	\$	2,068.00	✓
2	FRONT BUMPER FIXING PARTS	\$	553.00	?
3	FRONT BUMPER SECURING STRIP	2 \$	67.00	?
4	FRONT BUMPER GRILLE - CENTRE <i>new</i>	\$	185.00	+
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$	198.00	?
6	FRONT BUMPER AIR GUIDE - LH	\$	59.00	?
7	RADIATOR GRILLE <i>new</i>	\$	2,058.00	✓
8	FRONT BUMPER AIR GUIDE GRILLE - LH <i>new</i>	\$	344.00	✓
9	FRONT BUMPER CARRIER	\$	757.00	?
10	FRONT BUMPER FOAM FILLER PIECE	\$	117.00	?
11	FRONT BUMPER COVER <i>Dist</i>	\$	120.00	✓
12	FRONT BUMPER GUIDE SECTION - LH <i>Dist</i>	\$	34.00	✓
13	FRONT BUMPER BRACKET - LH	\$	214.00	?
14	CAUTION SIGN STICKER <i>na</i>	NEC \$	13.00	✓
15	AIRCON STICKER <i>na</i>	NEC \$	7.00	✓
16	LOCK CARRIER BRACKET <i>new</i>	\$	129.00	✓
17	FRONT BUMPER SUPPORT - LH / RH	2 \$	54.00	?
18	HORN - LH HIGH TONE	\$	38.00	?
19	SPRING SHACKLE - LH	\$	27.00	?
20	FRONT PARKING AID SENSOR - INNER / OUTER <i>1 piece dem'd.</i>	2	TBC	✓ 2
SUB TOTAL SPARE PARTS CHARGES		:	\$ 7,042.00	

Premium Automobiles
 55 Ubi Road 1, Singapore 408699
 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Reon No. SMP 4083 X

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/Nett		
21	FRONT PARKING AID SEAL RING <i>new</i>	4	S 14.00	✓
22	FRONT FENDER - LH <i>Distorted</i>		S 722.00	✓
23	FRONT FENDER ATTACHMENT PARTS ?		S 190.00	?
24	FRONT FENDER CLOSING ELEMENT - LH ?		S 47.00	-
25	FRONT FENDER BRACKET - LH <i>Bent</i>		S 33.00	✓
26	DEFORMATION ELEMENT BRACKET - LH <i>Distorted</i>		S 46.00	✓
27	FRONT FENDER BRACKET <i>Bent</i>		S 30.00	✓
28	FRONT FENDER UPPER BRACKET - LH <i>new</i>		S 32.00	✓
29	FRONT FENDER BRACE - LH <i>Distorted</i>		S 112.00	✓
30	FRONT FENDER CLOSING ELEMENT - LH ?		S 31.00	-
31	FRONT FENDER COVER - LH <i>new</i>		S 11.00	✓
32	WHEEL HOUSING LINER - LH <i>Dented</i>		S 226.00	✓
33	WHEEL HOUSING LINER ATTACHMENT PARTS ?		S 219.00	?
34	WHEEL SPOILER - LH <i>Cracked</i>		S 69.00	✓
35	WHEEL SPOILET TRIM - LH ?		S 33.00	?
36	STONE CHIP GUARD - LH <i>new</i>		S 48.00	✓
37	BONNET <i>Dented</i>		S 2,634.00	✓
38	BONNET ATTACHMENT PARTS ?		S 388.00	?
39	BONNET LID HINGE - LH / RH <i>new</i>	2	S 574.00	+
40	BONNET IMPACT PROTECTION - CENTRE <i>new</i>		S 26.00	✓
SUB TOTAL SPARE PARTS CHARGES			: \$ 5,485.00	

Premium Automobiles

13 Ubi Road 1, Singapore 408699
Tel: 6386 2373 Fax: 6847 1183

Teletax

Material List for Accident Vehicle Regn No. SMP 4083 X

S/N	Parts Description		S	Damage Parts & Prices	
				S/Nett	Remarks
41	BONNET IMPACT PROTECTION - LH / RH <i>new</i>	2	S	52.00	✓
42	FENDER LEDGE COVER - LH INNER		S	58.00	?
43	FENDER LEDGE COVER - LH		S	29.00	?
44	FENDER LEDGE COVER - LH <i>Ne</i>		S	21.00	✓
45	BONNET GAS FILLED STRUT <i>new</i>	2	S	224.00	+
46	BONNET STRIKER - LH / RH <i>new</i>	2	S	94.00	+
47	BONNET LID LOCK <i>new</i>	2	S	403.00	+
48	BONNET BOWDEN CABLE - CENTRE		S	54.00	+
49	BONNET BOWDEN CABLE		S	54.00	+
50	BONNET RELEASE LEVER		S	13.00	+
51	PLENUM CHAMBER COVER		S	92.00	+
52	BONNET SOUND ABSORBER		S	323.00	+
53	LED HEADLIGHT - LH <i>cond</i>		S	7,321.00	✓
54	MAIN LIGHT ELECTRONICS POWER MODULE ?		S	732.00	?
55	LIGHT CONTROL SYSTEM CONTROL UNIT ?		S	707.00	?
56	HEADLAMP HOUSING REPAIR KIT - LH ?		S	124.00	?
57	HEADLIGHT HOSE - LH <i>new</i>		S	34.00	+
58	LIFT CYLINDER - LH ?		S	198.00	?
59	LIFT CYLINDER CORRUGATED PIPE <i>new</i>		S	88.00	+
60	LOCK CARRIER <i>Not New</i>		S	956.00	+
SUB TOTAL SPARE PARTS CHARGES				: \$ 11,577.00	

SMP4083 X

Front Bumper Closing Element - Lower Centre

cracked. ✓

Front Bumper Foam Filler Piece

cracked ✓

Front Fender Closing Element LH

Deformed ✓

Lift Cylinder LH

Damaged ✓

Adrian King
A.K.

08/04/20.