

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

DAVE TAN TECK BENG
BLK 287 TAMPINES STREET 22
#04-374
S 520287

TP III

Cecilia.

Vehicle No :FBK 9547 Z
Make/Model :HONDA CB400
Accident date :21.03.2020

No	DESCRIPTION	Qty	Amount (\$\$)
List Items			
1	Taillamp <i>cracked</i>	1	\$ 253.00 ✓
2	Rear seat centre garnish @ \$198.00 <i>cracked</i>	2	\$ 644.00 198.
3	Rear seat side garnish @ \$104.50 <i>cracked</i>	1	\$ 414.00 209.
4	Rear wheel fender <i>Not New</i>	1	\$ 201.30 X
5	Rear wheel fender reflector <i>Not New</i>	1	\$ 28.80 X
6	Rear signal lamp @ \$85.80 <i>Not New</i>	2	\$ 179.40 X
			\$ 1720.50
			\$ 172.05
	Less 10% Disc		\$ 1548.45
	Total		\$ 1548.45

Special Nett Items			
1	Rear box <i>cracked</i>		\$ 345.00 ✓
2	Rear box base <i>Not New</i>		\$ 92.00 X
3	Rear box bracket <i>Not New</i>		\$ 138.00 X
4	Rear box reflective stickers <i>New</i>		\$ 57.50 30.
5	Rear camera <i>Not New</i>		\$ 460.00 X 400
6	Rear number plate <i>Bent</i>		\$ 35.00 ✓
			\$ 1127.50
	Total		\$ 1127.50

Labour Cost			
1	To check wiring		\$ 50.00 30
2	Remove & reinstall rear camera		\$ 50.00 30
3	Remove, replace & repair consistent to the accident		\$ 250.00 200
4	Respray painting		\$ 200.00 ✓
			\$ 550.00
	Total		\$ 550.00
	Grand Total		\$ 3225.95

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 1864

1/s 1.5K.

0 3Days.

1.5K.