



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS3/III19021039/Hsd3e2-1

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 13-04-2020



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 7803D	Veh. Inspected	SJB 8433C
Policy No.	MCOM0015	Coverage (\$)	0.00
Claim No.	MCT19110618	Excess (\$)	0.00
Assign From	DERRICK TAN	Assign Date	31/03/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA RUSH	c.c	1495
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	J200E0016640	Colour	BLACK
Odometer	122403	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R17	FALKEN	6 mm
L/H Front Tyre	225/50 R17	FALKEN	6 mm
R/H Rear Tyre	225/50 R17	FALKEN	6 mm
L/H Rear Tyre	225/50 R17	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	25/11/2019	Inspection Date	29/11/2019
Survey held at	AUTOMEDIC-25 KAKI BUKIT ROAD 4# 05-85 SYNERGY		
Repairer	-		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------