

S K AUTO CONSULTAN

Our Reference TP/010/03785C
Vehicle No. SJB 8433C

03/04/20
during

QTY	DESCRIPTION	CONDITION
PARTS (LIST ITEMS)		
1	Rear Tailgate (Back door) ✓ BT	Deep Dent
1	Rear Tailgate inner lock * ✓ Jm	Damaged
1	Rear Tailgate inner lock catch X (R)	Bent
2	Rear Tailgate hinges @98.20 X (SVC)	Bent
1	Rear Tailgate inner trimboard X (SVC)	Deformed
1	Rear Tailgate Rush emblem ✓ Rm	Necessary
1	Rear Tailgate top spoiler X (SVC)	Refix
1	Rear bumper ✓ DD	Deformed
2	Rear bumper reflector X (SVC)	Reuse
1	Rear spare tyre outer cover ✓ CRA	Cracked
1	Rear spare tyre inner cover ✓ CRA	Dented
1	Rear spare tyre bracket (holder) ✓ BT	Bent
*Identified that when tailgate was in closed motion lock was not well secured (noise)		
SPECIAL NETT ITEMS		
1SET	Rear Tailgate inner trimboard clips ✓ Rm	Necessary
1	Rear windscreen sealant ✓ Rm	Necessary
1	Reverse Camera ✓ (SVC)	Refix
1	Rear spare tyre ✓ (SVC)	Reuse
1	Reverse sensor ✓ skm	Damaged
		TOTAL P

1,250.8 +
191.8 +
72. +

830.6 +
1,030.8 +

435.1 +
350.3 +

=
4,161.4 *

4,161.4 x
75. %

3,121.05 *

(\$\$)

1250.80 ✓

191.80 ✓

72.00 ✓

830.60 ✓

1030.80 ✓

435.10 ✓

350.30 ✓

25.00 ✓

40.00 ✓

200.00 ✓

=

5174.18

265.00 ✓

48.00 ✓

80.00 ✓

0.00 ✓

0.00 ✓

250.00 ✓

600.00 ✓

500.00 ✓

100.00 ✓

20.00 ✓

30.00 ✓

=

1,250.00 *

3,121.05 +

265. +

1,250. +

=

4,636.05 *

4,636.05 x

80. %

3,708.84 *

L/s
\$3700/-