



CHEVROLET

LONPAC INS

FINALIZE

Vehicle No: SFB3344G
Chassis No : KL1YA7589HK612693
Engine No: B14NET163570758
Date of accident :27/03/2020

GST Ref. No: 20-0000274-Z

Invoice No:

Invoice Date: _____

DESCRIPTION	AMOUNT	SGD
-------------	--------	-----

Parts

No.	Qty.	Description	Price (SGD)
1	4	FRT FENDER WHEELARCH CLIP	\$ 26.00
2	1	FRT FENDER RH	\$ 1,243.00
3	1	FRT FENDER WHEELARCH GARNISH RH	\$ 152.00
4	1	FRT BUMPER	\$ 1,406.00
5	1	FRT BUMPER LOWER	\$ 516.00
6	4	FRT BUMPER CLIP	\$ 26.00
7	1	FRT BUMPER SIDE RETAINER RH , SUPPORT	\$ 133.00
8	1	FRT BUMPER BRACKET RH , GUIDE	\$ 111.00
9	1	FRT BUMPER SPONGE	\$ 263.00
10	1	FRT BUMPER LOGO	\$ 158.00
11	1	FRT BUMPER FOG LAMP RH	\$ 330.00
12	1	RH HEADLAMP	\$ 983.00
13	1	FRT WHEEL BEARING RH	\$ 587.00
14	1	FRT RIM RH	\$ 898.00

Supplementary

1	1	FRT INTAKE RESONATOR BOX	\$ 145.00
2	1	FRT INTAKE AIR DUCT	\$ 145.00

Total: \$ 7,122.00
Less 10%: \$ 712.20
Parts Total: \$ 6,409.80

Labour

No.	Price (SGD)
1	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIRED / REPLACEMENT PARTS. \$ 1,100.00

2		CARRY OUT SPRAY PAINTING OF ACCIDENT AFFECTED AREA. FRT BUMPER , FRT BONNET , FRT SUPPORT PANEL , FRT WHEELHOUSE PANEL RH , FRT FENDER RH , FRT DOOR RH	\$ 1,500.00
3		TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	\$ 80.00
4		TO REMOVE AND REPLACE RHF UNDER CARRIAGE PARTS	\$ 275.00
5		TO CONDUCT 4 WHEEL ALIGNMENT	\$ 120.00

Labour Total : \$ 3,075.00

Other

<u>No.</u>		<u>Price (SGD)</u>
1	1 FRT TYRE RH	\$ 200.00

Other Total : \$ 200.00

Total : \$ 9,684.80
Excess: \$ 500.00
GST (7%) : \$ 642.94
Grand Total : \$ 9,827.74

Yours Faithfully,

Kelvin Chew
Service Advisor
Tel: 68441985 Fax:68445185

Please check and finalize with me