

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/TMI20004761/FTD3E2  
**Date:** 04/05/2020

#### REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd	Policy No:	MT000878
<b>Claimant Vehicle No :</b> SHC3333J	<b>Insured Vehicle No :</b>	SJC5441T
Date of Loss: 31/03/2020	Nature of Claim:	TP Claim No: M2002246

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHC3333J</b>	Engine No:	G4LEJU167569
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVKU134060
Reg. Date:	01/02/2019 (Man. Year: 2018)	Odometer:	171968 km
Colour:	Blue	Engine Capacity:	1580 cc
Market Value/New Car Price:	N/A	Sum Insured (S\$):	<b>Market Value/New Car Price</b>

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

#### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Davanti 7 mm	Rear Left Side:	Davanti 8 mm
Front Right Side:	Davanti 7 mm	Rear Right Side:	Davanti 8 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,685.73	1,611.00	74.73	4.43
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,150.00	1,040.00	110.00	9.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,846.73</b>	<b>2,662.00</b>	<b>184.73</b>	<b>6.49</b>
<b>+ GST 7.00/7.00% (S\$)</b>	199.27	186.34	12.93	6.49
<b>Nett Amount (S\$)</b>	<b>3,046.00</b>	<b>2,848.34</b>	<b>197.66</b>	<b>6.49</b>

#### INSPECTION

Date of Assignment:	01/04/2020 Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	01/04/2020 Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days	

**Adjuster:** PARASURAM SHANMUGAM

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 04 May 2020)
<b>Parts:</b> 192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC3333J)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRT FENDER RH	Buckled	588.80 FL	-	*588.80 FL
2	1		*FRT FENDER EMBLEM -BLUE DRIVE RH	Necessary	26.60 F	-	*26.60 F
3	1		*RR VIEW MIRROR ASSY RH	Broken	1,391.36 FL	-	*1,391.70 FL
4	1		*FRT DOOR COMFORTDELGRO LOGO RH	Not Necessary	75.00 F	-	*- F

F=Franchise part. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>2,081.76</b>	<b>2,007.10</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	396.03	396.10
<b>Total Parts (S\$)</b>	<b>1,685.73</b>	<b>1,611.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	11.00	11.00
<b>Sub Total (\$\$)</b>			<b>11.00</b>	<b>11.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING ( repair frt WS pillar Rh )	New	500.00	480.00
2	SPRAY PAINTING CHARGE	New	550.00	480.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	50.00	50.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,150.00</b>	<b>1,040.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**