



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 8497E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	CUT	583.59	491.40
1	FRONT BUMPER TOP RUBBER	NOT NECESSARY	45.00	-
1	FRONT BUMPER TOP INNER BRACKET	NOT NECESSARY	56.00	-
2	FRONT BUMPER SIDE RETAINER	NECESSARY	105.80	105.80
1	FRONT BUMPER REINFORCEMENT	BENT	391.00	391.00
1	FRONT BUMPER LOWER GRILLE	NOT DAMAGED	97.75	-
1	FRONT BUMPER LOWER GARNISH RH	BROKEN	105.00	105.00
1	FRONT GRILLE	BROKEN	300.15	300.15
1	FRONT GRILLE EMBLEM	NECESSARY	61.00	53.50
1	FRONT RH HEADLAMP	CUT	488.75	488.75
1	FRONT RH FENDER	TO REPAIR SEE LABOUR	345.18	-
1	AIRCON CONDENSER	NOT DAMAGED	1,231.85	-
1	WIPER TANK	DENTED	120.75	79.80
1	FRONT RH CHASSIS MEMBER	BENT	700.80	582.00
1	FRONT SUPPORT PANEL	NOT DAMAGED	832.23	-
	LESS 25% DISCOUNT		-1,366.21	-649.35
			4,098.64	1,948.05
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	30.00	30.00
1	SET FRONT GRILLE CLIP (SN)	NECESSARY	20.00	20.00
1	FRONT NUMBER PLATE WITH CASING (SN)	BROKEN	80.00	50.00
			130.00	100.00
<u>LABOUR</u>				
	CHECK FRONT WIRING AND LIGHTNING SYSTEM.		60.00	30.00
	REMOVE, RENEW CONDENSER AND TOP UP GAS.	NOT NECESSARY	120.00	-
	MOUNT CHASSIS ON BENCH.	NOT NECESSARY	500.00	-
	PANEL BEATING ON AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF FRONT RH FENDER.		1,000.00	600.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,000.00	600.00

Report Ref No. CS/AGI20004762/Bqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	APPLY ANTI RUST ON AFFECTED AREAS.		100.00	40.00
			2,780.00	1,270.00
GRAND TOTAL			7,008.64	3,318.05
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)				3,318.05

Report Ref No. CS/AGI20004762/Bqd3e2

LIM TEOW GUAN

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.