

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7615A

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

31 MAR 2020

AAD2003-156*Not Authorized
Preserving B4 paint**25239.70***SHB 7615A**

JTDKB3FU603077100

TOYOTA

PRIUS

29.3.2020

FCIL

4/12/2018

	PART
1	FRONT BUMPER
1	FRONT BUMPER SIDE RETAINER LH
1	REINFORCEMENT, FRONT BUMPER
1	REINFORCEMENT, FRONT BUMPER, NO.2
1	ABSORBER, FRONT BUMPER ENERGY
1	ABSORBER, FRONT BUMPER, LOWER
1	COVER SUB-ASSY, ENGINE UNDER, NO.2
1	COVER SUB-ASSY, ENGINE, NO.1
1	EXTENSION, FRONT BUMPER, LH
1	FRONT LED LAMP (LOWER) LH
1	FRONT HEADLAMP LH
1	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1
1	MOTOR, HEADLAMP LEVELING, LH
1	FRONT FENDER LH
1	LINER, FRONT FENDER, LH
1	FRONT FENDER EMBLEM LH
1	PROTECTOR, FRONT FENDER SIDE PANEL, LH
1	SEAL, FENDER APRON MUDGUARD, LH
1	MEMBER SUB-ASSY, FRONT SIDE, INNER LH
1	PLATE, FRONT SIDE MEMBER, OUTER LH
1	GRILLE SUB-ASSY, RADIATOR
1	GRILLE, RADIATOR, LOWER NO.1
1	FRONT BONNET (<i>Aluminium</i>)
1	HINGE ASSY, HOOD, LH
1	INSULATOR, HOOD
1	SUPPORT, RADIATOR, UPPER LH

	LIST	
\$	<i>Bu</i> 516.00	✓
\$	<i>Sn</i> 82.30	X
\$	<i>R</i> 716.60	X
\$	<i>Sn</i> 246.10	X
\$	<i>Sn</i> 79.60	X
\$	<i>Sn</i> 132.70	X
\$	<i>Sn</i> 241.90	X
\$	<i>Sn</i> 472.40	X
\$	<i>Sn</i> 120.10	X
\$	<i>Sn</i> 951.40	X
\$	<i>CM</i> 2,637.60	✓
\$	<i>Sn</i> 960.50	X
\$	<i>Sn</i> 487.50	X
\$	<i>R</i> 977.80	✓
\$	<i>Dir</i> 202.50	✓
\$	<i>me</i> 54.60	✓
\$	<i>Sn</i> 93.90	} X
\$	<i>Sn</i> 51.90	
\$	<i>R</i> 725.60	
\$	<i>Sn</i> 292.10	
\$	<i>Sn</i> 346.00	} X
\$	<i>Sn</i> 170.10	
\$	<i>R</i> 983.10	
\$	<i>R</i> 58.90	} X
\$	<i>Sn</i> 410.90	
\$	<i>Sn</i> 78.90	
TOTAL	\$ 12,091.00	
25%	\$ 3,022.75	
	\$ 9,068.25	

Trans-cab Auto Services Pte Ltd

AAD2003-156

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7615A

Special Nett

1 FRONT WHEEL RIM	\$	sn 1,879.40	X
1 FRONT WHEEL RIM COVER	\$	sn 211.50	X
1 FRONT TYRE 195/65/15	\$	sn 350.00	X
1SET CLIP, FRONT FENDER LINER	\$	sn 35.00	✓
1 FRONT NUMBER PLATE WITH MOULDING	\$	sn 200.00	X
1SET BUMPER CLIP FRT	\$	na 66.00	✓
1SET FRONT BUMPER RETAINER CLIP	\$	na 35.00	X
1SET ROCKER PANEL MOULDING CLIP	\$	na 35.00	X
2 FRONT WINDSCREEN SEALANT	\$	na 120.00	✓
1 FRONT WINDSCREEN INNER SPONGE SEAL	\$	na 100.00	X
1 FRONT WINDSCREEN MOULDING	\$	na 170.00	X
TOTAL	\$	3,201.90	

TOTAL PARTS \$ 12,270.15**LABOUR**

Panel Beating, Knocking And Straightening The Necessary
Portion, Remove And Renewal Of Parts, Adjust And Realign The
Same

\$ 6,000.00 400

To check steering geometry and computer wheel alignment

\$ na 220.00 X

To transfer of Fender fittings, attachments and perform water
seepage test.

\$ na 170.00 X

To transfer of Front Bumper fittings, attachments and perform
water seepage test.

\$ na 170.00 X

Labour charge to mount and dismount vehicle on jig bench, to
facilitate repair.

\$ na 380.00 X

To remove and refit interior fittings, trimings, garnish, fittings
and other, to enable repair.

\$ na 380.00 X

Trans-cab Auto Services Pte Ltd**AAD2003-156**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7615A

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	6601
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To Rust-Proofing Of The Affected Areas.	\$	170.00	301
To transfer of Bonnet fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	nn 170.00	X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	nn 380.00	X
TOTAL	\$	14,550.00	
Over All Total	\$	26,820.15	

(PART-BY-PART) Repair Days~~20 days~~
2 1/2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: