

Lion City Rentals Pte Ltd
CARROS CENTER
 60 JALAN LAM HUAT #04-01 S(737869)
 Main +65 62524991

Ms AIG Asia Pacific Insurance Pte Ltd

Date 1/4/2020

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO: SLK4384R

Chassis No: JM6BN22A8H0135771

MAKE / MODEL : Mazda 3 Sedan 1.5 AT

DATE OF ACCIDENT : 30/03/2020

YOUR INSURED VEHICLE NUMBER :SJJ318M

MILEAGE : 170222 km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	Rear bumper <i>de</i>	1PC	\$ 1,129.00	\$ 1,129.00
2	Rear bumper retainer RH <i>X</i>	1PC	\$ 58.15	\$ 58.15
3	Rear bumper reinforcement <i>?</i>	1PC	\$ 564.20	\$ 564.20
4	Rear bumper lower cover <i>X</i>	1PC	\$ 300.00	\$ 300.00
5	Rear boot <i>X</i>	1PC	\$ 1,005.30	\$ 1,005.30
6	Rear bumper retainer LH <i>X</i>	1PC	\$ 58.15	\$ 58.15
7	Rear boot SKYACTIV emblem <i>X</i>	1PC	\$ 66.80	\$ 66.80
8	Rear boot Mazda logo <i>X</i>	1PC	\$ 78.30	\$ 78.30
9	Rear boot Mazda 3 emblem <i>X</i>	1PC	\$ 56.10	\$ 56.10
10	Rear bumper LH tow cover <i>mis</i>	1PC	\$ 50.00	\$ 50.00
				\$ 3,114.80
20% DISCOUNT S\$:				\$ 622.96
				\$ 2,491.84

S/Nett

Reverse sensor	\$ 240.00	<i>200?</i>
Bumper clips	\$ 150.00	<i>100</i>
Total	\$ 390.00	

LABOUR CHARGES

- To labour charge for removing rear bumper, rear boot, end panel out to facilitate repairs and replacement of damaged parts
- 1 \$ ~~750.00~~ *300*
- 2 To respray rear bumper, rear boot, rear end panel and spare tyre panel \$ ~~900.00~~ *400*

LABOUR TOTAL S\$:	\$ 1,650.00
TOTAL S\$:	\$ 4,531.84
7% GST	\$ 317.23
GRAND TOTAL S\$:	\$ 4,849.07

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Faisal
Hp 90010068
3 days
L/S
01/04/2020 @ 1540
Reg after repair