

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20004772/KEA3Q2

Date: 08/12/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900035947
Claimant
Vehicle No : SHC5549R **Insured Vehicle No :** SMJ9818S
Date of Loss: 25/03/2020 Nature of Claim: TP Claim No: 5355822593SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC5549R**
Make & Model: RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A) Engine No: M9R8839C001879
Reg. Date: 15/09/2014 (Man. Year: 2014) Chassis No: VF1ABL15AUC278886
Colour: Metallic White/Red Odometer: 519233 km
Engine Capacity: 1995 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Sailun 8 mm Rear Left Side: Sailun 8 mm
Front Right Side: Sailun 8 mm Rear Right Side: Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,039.10	3,378.02	12,661.08	78.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,830.00	1,500.00	12,330.00	89.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,869.10	4,878.02	24,991.08	83.67
Approved Total (Overridden) (S\$)		3,900.00		
	(S\$) 29,869.10	3,900.00	25,969.10	86.94
+ GST 7.00/7.00% (S\$)	2,090.84	273.00	1,817.84	86.94
Nett Amount (S\$)	31,959.94	4,173.00	27,786.94	86.94
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$81.13/day) (S\$)		324.52		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		4,705.01		

INSPECTION

Date of Assignment: 31/03/2020

Date Inspected: 31/03/2020 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
2, Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR PANEL REAR RH	Bent	758.70 FL	*758.70 FL
2	1		*DOOR GUIDE REAR RH	Serviceable	136.40 FL	*- FL
3	1		*DOOR HINGE UPPER REAR RH	Repair	241.60 FL	*- FL
4	1		*DOOR HINGE LOWER REAR RH	Repair	169.90 FL	*- FL
5	1		*DOOR CHECK REAR RH	Serviceable	114.90 FL	*- FL
6	1		*DOOR REGULATOR REAR RH	Serviceable	758.10 FL	*- FL
7	1		*DOOR REGULATOR MOTOR REAR RH	Serviceable	450.60 FL	*- FL
8	1		*DOOR SEAL REAR RH	Serviceable	119.80 FL	*- FL
9	1		*DOOR WEATHERSTRIP REAR RH	Serviceable	311.60 FL	*- FL
10	1		*DOOR HANDLE OUTER REAR RH	Serviceable	42.10 FL	*- FL
11	1		*DOOR HANDLE CAP REAR RH	Serviceable	57.90 FL	*- FL
12	1		*DOOR HANDLE MODULE REAR RH	Serviceable	111.00 FL	*- FL
13	1		*DOOR MOULDING REAR RH	Serviceable	100.50 FL	*- FL
14	1		*ROCKER PANEL OUTER RH	Repair	1,184.99 FL	*- FL
15	1		*ROCKER PANEL INNER RH	Repair	1,024.79 FL	*- FL
16	1		*ROCKER PANEL INNER GARNISH RH	Serviceable	466.51 FL	*- FL
17	1		*DOOR PANEL FRONT RH	Bent	2,844.66 FL	*2,844.66 FL
18	1		*DOOR LOCK FRONT RH	Repair	908.75 FL	*- FL
19	1		*DOOR REGULATOR FRT RH	Serviceable	505.19 FL	*- FL
20	1		*DOOR REGULATOR MOTOR FRT RH	Serviceable	796.46 FL	*- FL
21	1		*DOOR REGULATOR GUIDE FRT RH	Serviceable	120.97 FL	*- FL
22	1		*DOOR HANDLE OUTER FRT RH	Serviceable	477.76 FL	*- FL
23	1		*DOOR HANDLE CAP FRT RH	Serviceable	35.52 FL	*- FL
24	1		*DOOR HANDLE MODULE FRT RH	Serviceable	133.60 FL	*- FL
25	1		*DOOR MOULDING FRT RH	Serviceable	176.82 FL	*- FL
26	1		*DOOR WEATHERSTRIP FRT RH	Serviceable	410.27 FL	*- FL
27	1		*DOOR SEAL FRT RH	Serviceable	72.82 FL	*- FL
28	1		*DOOR SEAL LOWER FRT RH	Serviceable	91.17 FL	*- FL
29	1		*DOOR MIRROR ASSY RH	Serviceable	1,483.40 FL	*- FL
30	1		*DOOR HARNESS WIRE RH	Serviceable	2,670.00 FL	*- FL
31	1		*REAR DOOR STICKER 6555-3333	Necessary	100.00 FS	*60.00 FS
32	1		*RH SIDE RENAULT TYRE	Serviceable	300.00 FS	*- FS
33	1		*RH SIDE RENAULT TYRE RIM	Serviceable	380.00 FS	*- FS
34	1		*FRONT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*60.00 FS
35	1		*FRONT DOOR STICKER CLASSIC	Necessary	80.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	17,716.78	3,738.36
- List Item Discount on L Items 10.00/10.00% (\$)	1,677.68	360.34
Total Parts (\$)	16,039.10	3,378.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	6,000.00	800.00
2	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH TO FACILITATE REPAIR	New	380.00	0.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
4	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
5	TO TRANSFER OF REAR DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
6	TO TRANSFER OF FRONT DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
7	TO RUST -PROOFING OF THE AFFECTED AREAS	New	170.00	60.00
8	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
9	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
10	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	500.00
Gross Labour Cost (\$)			13,830.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >