

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5549R**AAD2003-141***Not Authorized
1/15mp @ 3900/h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

31 MAR 2020

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC 5549R

VF1ABL15AUC278886

RENAULT

LATITUDE

25.3.2020

AIG

15/09/2014

PART		LIST	
1	DOOR PANEL REAR RH	\$	758.70 ✓
1	DOOR GUIDE REAR RH	\$	136.40
1	DOOR HINGE UPPER REAR RH	\$	241.60
1	DOOR HINGE LOWER REAR RH	\$	169.90
1	DOOR CHECK REAR RH	\$	114.90
1	DOOR REGULATOR REAR RH	\$	758.10
1	DOOR REGULATOR MOTOR REAR RH	\$	450.60
1	DOOR SEAL REAR RH	\$	119.80
1	DOOR WHEATHESTRIIP REAR RH	\$	311.60
1	DOOR HANDLE OUTER REAR RH	\$	42.10
1	DOOR HANDLE CAP REAR RH	\$	57.90
1	DOOR HANDLE MODULE REAR RH	\$	111.00
1	DOOR MOULDING REAR RH	\$	100.50
1	ROCKER PANEL OUTER RH	\$	1,184.99
1	ROCKER PANEL INNER RH	\$	1,024.79
1	ROCKER PANEL INNER GARNISH RH	\$	466.51
1	DOOR PANEL FRONT RH	\$	2,844.66 ✓
1	DOOR LOCK FRONT RH	\$	908.75
1	DOOR REGULATOR FRT RH	\$	505.19
1	DOOR REGULATOR MOTOR FRT RH	\$	796.46
1	DOOR REGULATOR GUIDE FRT RH	\$	120.97
1	DOOR HANDLE OUTER FRT RH	\$	477.76
1	DOOR HANDLE CAP FRT RH	\$	35.52
1	DOOR HANDLE MODULE FRT RH	\$	133.60
1	DOOR MOULDING FRT RH	\$	176.82
1	DOOR WEATHERSTRIP FRT RH	\$	410.27
1	DOOR SEAL FRT RH	\$	72.82
1	DOOR SEAL LOWER FRT RH	\$	91.17

Trans-cab Auto Services Pte Ltd**AAD2003-141**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5549R

1	DOOR MIRROR ASSY RH	\$	<i>nn</i> 1,483.40	<i>X</i>
1	DOOR HARNESS WIRE RH	\$	<i>nn</i> 2,670.00	<i>X</i>

TOTAL	\$	16,776.78
10%	\$	1,677.68
	\$	15,099.10

Special Nett

1	REAR DOOR STICKER '6555-3333'	\$	<i>nn</i> 100.00	<i>605n</i>
1	RH SIDE RENAULT TYRE	\$	<i>nn</i> 300.00	<i>X</i>
1	RH SIDE RENAULT TYRE RIM	\$	<i>nn</i> 380.00	<i>X</i>
1	FRONT DOOR STICKER "Trans-Cab"	\$	<i>nn</i> 80.00	<i>605n</i>
1	FRONT DOOR STICKER "Classic"	\$	<i>nn</i> 80.00	<i>135n</i>

TOTAL	\$	940.00
--------------	-----------	---------------

TOTAL PARTS	\$	16,039.10
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 6,000.00 *800*

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *nn* 380.00 *X*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 *X*

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 *X*

To transfer of Rear door fittings, attachment and perform water seepage test.

\$ 170.00 *60*

To transfer of Front door fittings, attachment and perform water seepage test.

\$ 170.00 *60*

Trans-cab Auto Services Pte Ltd**AAD2003-141**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5549R

To rust-proofing of the affected areas.	\$	170.00	601
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
Putty and spray painting of the affected portion.	\$	6,000.00	5001
TOTAL	\$	13,830.00	
Over All Total	\$	29,869.10	

LUMP SUM (REPAIR DAY)**20 DAYS****3 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: