

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 518Y**AAD2003-157***Not Authored
C/Sing & 3700k*

Vehicle No.:

31 MAR 2020

Chassis No.:

SHF 518Y

VF1ABL15AUC278263

Vehicle Make:

RENAULT

Vehicle Model:

LATITUDE

Date of Accident :

29.3.2020

Third Party Insurer :

FCIL

Date of Registration:

13/6/2014

PART

- | | |
|---|---------------------------------|
| 1 | BUMPER COVER FRT |
| 1 | BUMPER SPOILER FRT |
| 1 | BUMPER ABSORBER FRT |
| 1 | BUMPER RETAINER FRT LH |
| 1 | BUMPER SUPPORT FRT |
| 1 | BUMPER UNDERTRAY FRT |
| 1 | BUMPER GRILLE LOWER FRT |
| 1 | BUMPER FOG LAMP GRILLE LH |
| 1 | BUMPER BEAM FRT |
| 1 | HEADLAMP LH |
| 1 | HEADLAMP PANEL FRT LH |
| 1 | FENDER PANEL FRT LH |
| 1 | WHEELARCH FRT LH |
| 1 | FENDER BRACKET FRT LH |
| 1 | FENDER BRACKET LOWER LH |
| 1 | FENDER INSULATOR LH |
| 1 | FRONT BRACE PANEL |
| 1 | BONNET |
| 1 | BONNET INSULATOR |
| 1 | BONNET STRUT LH |
| 1 | BONNET HINGE LH |
| 1 | BONNET LOCK |
| 1 | RADIATOR GRILLE |
| 1 | RADIATOR GRILLE BADGE 'RENAULT' |
| 1 | RADIATOR GRILLE FRAME |
| 1 | FRAME FULL SUPPORT PANEL |

LIST

\$	mgom	747.20	✓
\$	Sm	344.70	X
\$	Sm	394.68	X
\$	Dist	101.40	✓
\$	Sm	10.70	X
\$	Sm	292.50	X
\$	Sm	147.00	X
\$	Sm	207.21	X
\$	R	663.70	X
\$	mgim	743.60	✓
\$	R	127.70	X
\$	B ₁	414.40	✓
\$	Sm	112.30	X
\$	Sm	38.90	X
\$	Sm	11.80	X
\$	Sm	65.50	X
\$	R	177.22	X
\$	R	1,312.70	X
\$	Sm	294.30	X
\$	Sm	53.30	X
\$	R	236.50	X
\$	R	152.80	X
\$	mgom	969.90	—
\$	na	225.36	—
\$	cm	686.00	✓
\$	Sm	592.70	X

Trans-cab Auto Services Pte Ltd**AAD2003-157**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 518Y

1	FRAME FULL SUPPORT BRACKET	\$	41.60	}	X
1	AIR CLEANER BOX	\$	464.20		
1	AIR CLEANER HOSE	\$	175.85		
1	AIR CLEANER LOWER	\$	271.26		
1	ROCKER PANEL INNER GARNISH LH	\$	466.51		
1	ROCKER PANEL INNER LH	\$	1,024.79		
1	ROCKER PANEL OUTER LH	\$	1,184.99		
1	AUTO COMPUTER	\$	1,287.30		
1	INJECTION COMPUTER	\$	2,706.30		
1	RHD HYDRAULIC POWER(RACK&PINION)	\$	3,765.30		
1	STEERING PUMP ELECTRIC L70Y	\$	2,026.70		
1	A/C CONDENSER	\$	1,537.80		
1	SUBFRAME OUTER FRT	\$	1,094.20		
1	SUBFRAME BRACKET OUTER LH	\$	49.00		
1	SUBFRAME BRACKET OUTER RH	\$	49.00		
1	DOOR PANEL FRT LH	\$	2,844.66		
1	DOOR HINGE UPPER LH	\$	274.50		
1	DOOR HINGE LOWER LH	\$	300.55		
1	DOOR CHECK FRONT LH	\$	90.90		
1	DOOR MIRROR ASSY LH	\$	727.90		
1	DOOR HARNESS WIRE LH	\$	2,670.00		
1	DOOR REGULATOR FRT LH	\$	758.10		
1	DOOR REGULATOR MOTOR FRT LH	\$	501.40		
1	DOOR REGULATOR GUIDE FRT LH	\$	69.00		

TOTAL	\$	33,505.87
10%	\$	3,350.59
	\$	30,155.29

Special Nett

1	BUMPER CLIP FRT	\$	66.00	✓
1	BUMPER BRACKET CLIP FRT LH	\$	12.00	X
1	BUMPER SUPPORT CLIP FRT LH	\$	10.50	X
1	BUMPER GRILLE LOWER CLIP	\$	69.00	X

Trans-cab Auto Services Pte Ltd**AAD2003-157**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 518Y

1	WHEELARCH CLIP FRT LH	\$	nn	30.50	}	X	
1	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00			
1SET	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00			
2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00			
1SET	RADIATOR GRILLE SCREW	\$	nn	16.00			
1SET	RADIATOR GRILLE FRAME CLIP	\$	nn	52.00			
1	FRONT LEFT TYRE	\$	sn	330.00			
1	FRONT LEFT TYRE RIM	\$	sn	380.00			
1SET	Front licence plate with holder	\$	sn	80.00			
1	FRONT DOOR STICKER 'Trans-Cab'	\$	nn	80.00			
1	FRONT DOOR STICKER 'Classic'	\$	nn	80.00			
1	Windscreen moulding	\$	nn	160.00			
2	FRONT WINDSCREEN SEALANT	\$	nn	120.00			
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00			
TOTAL		\$		1,706.00			

TOTAL PARTS	\$	31,861.29
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$	6,500.00	5001
----	----------	------

To transfer of front bumper fittings, attachment and perform water seepage test.

\$	nn	170.00	X
----	----	--------	---

To transfer of front fender fittings, attachment and perform water seepage test.

\$	nn	170.00	X
----	----	--------	---

To transfer of tire, rim and on wheel balancing.

\$	nn	170.00	X
----	----	--------	---

To check steering geometry and computer wheel alignment

\$	nn	220.00	X
----	----	--------	---

Trans-cab Auto Services Pte Ltd**AAD2003-157**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 518Y

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i> 380.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	<i>X</i>
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	170.00	<i>X</i>
Putty and spray painting of the affected portion.	\$	6,500.00	<i>4401</i>
To rust-proofing of the affected areas.	\$	170.00	<i>301</i>
To transfer of door fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00	<i>X</i>
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	<i>na</i> 380.00	<i>X</i>
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>na</i> 170.00	<i>X</i>
Towing Fees	\$	150.00	<i>* 501</i>
TOTAL	\$	15,870.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price must be subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

LUMP SUM (REPAIR DAY)

Acknowledged by Repairer
Signature:
Date:

Over All Total \$**47,731.29***20 days**3 days*