



Case Details

Case Reference Number : TAX/03/20/2088
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB340M

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-11018-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : India International Insurance Pte Ltd
 Accident Date and Time : 28/03/2020 05:35 AM
 Vehicle Age(In Months) : 66

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Quantity	Surveyor Approval		Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)			Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			DOOR FRT/LH	1	894.40	894.40	25.00	670.80	Replace	0	Repair		
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	Replace		
One Time Key In	Main			HINGE LOWER LHF, DOOR	1	90.10	90.10	25.00	67.57	Replace	0	Not Give		
One Time Key In	Main			HINGE UPPER LHF, DOOR	1	80.50	80.50	25.00	60.38	Replace	0	Not Give		
One Time Key In	Main			MIRROR ASSY,LH	1	1,224.90	1,224.90	25.00	918.68	Replace	0	Not Give		
One Time Key In	Main			MIRROR LAMP LH	1	65.30	65.30	10.00	58.77	Replace	1	Replace		
One Time Key In	Main			COVER, OUTER MIRROR, LH	1	107.40	107.40	25.00	80.55	Replace	1	Repair		
One Time Key In	Main			FENDER FRT/LH	1	723.40	723.40	25.00	542.55	Replace	1	Replace		
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	Replace		
One Time Key In	Main			FENDER PROTECTOR FRT/LH UPPER	1	46.10	46.10	25.00	34.58	Replace	0	Not Give		

Total Spare Part Cost 7,420.06

Surveyor Total 700.24

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 5,936.05

Final Sur Total 560.19

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation								Surveyor Approval		
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			PROTECTOR, FRONT FENDER SIDE PANEL LH	1	114.50	114.50	25.00	85.88	Replace	0	0	Not Give	
One Time Key In	Main			FENDER LINER FRT/LH	1	171.70	171.70	25.00	128.77	Replace	0	0	Not Give	
One Time Key In	Main			FENDER LINER PAD, FR WHEEL. LH	1	49.30	49.30	25.00	36.97	Replace	0	0	Not Give	
One Time Key In	Main			FENDER APRON SUB FRT/LH	1	637.80	637.80	25.00	478.35	Replace	0	0	Not Give	
One Time Key In	Main			WHEEL DISC. FRONT	1	1,484.20	1,484.20	25.00	1,113.15	Replace	1	0	Repair	
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	
One Time Key In	Main			HEAD LAMP LH	1	945.20	945.20	10.00	850.68	Replace	0	0	Not Give	
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	0	Repair	
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	0	0	Not Give	
One Time Key In	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	0	0	Not Give	
One Time Key In	Main			BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	0	0	Not Give	
One Time Key In	Main			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	0	0	Not Give	
One Time Key In	Main			BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	0	0	Not Give	
One Time Key In	Main			ARM SUB-ASSY,FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Give	
One Time Key In	Main			ARM SUB-ASSY,FR BUMPER RH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Give	
One Time Key In	Main			BUMPER GRILLE SUB-ASSY,LOWER	1	311.10	311.10	25.00	233.33	Replace	0	0	Not Give	
Total Spare Part Cost									7,420.06	Surveyor Total		700.24		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									5,936.05	Final Sur Total		560.19		

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER LIP FRT	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give	
One Time Key In	Main			BUMPER FRT ABSORBER LOWER	1	127.70	127.70	25.00	95.78	Replace	0	0	Not Give	
One Time Key In	Main			UNDER COVER CENTER	1	448.30	448.30	25.00	336.23	Replace	0	0	Not Give	
Total Spare Part Cost									7,420.06	Surveyor Total		700.24		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									5,936.05	Final Sur Total		560.19		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR LH PORTION	507.00	300	
Total:			507.00	300.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0	
3	Main	TO RESPRAY FRONT DOOR LH	378.00	200	
4	Main	RESPRAY MIRROR COVER LH	180.00	100	
5	Main	TO RESPRAY FRONT FENDER LH	378.00	200	
6	Main	TO RESPRAY RIM	180.00	50	
Total:			1,674.00	750.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	30	
2	Main	TO REMOVE AND REFIX WING MIRROR	120.00	70	
Total:			896.88	456.88	


S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
3	Main	TO REPLACE SUNDRY PARTS	100.00	0	
4	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	
5	Main	TO WASH AND VACUUM	60.00	0	
6	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	296.88	
7	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60	
Total:			896.88	456.88	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	5,936.05	560.19
Total Labour Cost	507.00	300.00
Total Spray Painting	1,674.00	750.00
Other	896.88	456.88
Overall Total	9,013.93	2,067.07
Lump Sum Repair Option		<input checked="" type="checkbox"/>
Lump Sum Total	9,000.00	2,050.00
Surveyor Approved Amount		2,050.00
No of Repair Days*	5	4

Remarks - resurvey after paint

Surveyor Name Rasul

Signature 

Survey Date

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray **01/04/2020**
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Save Clear