

# S9 MOTOR TRADING PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg\_motor\_enterprise@yahoo.com.sg

Date: 3 April 2020

To : LKK

By Fax: 6256-4315

Attn : Bryan Ang

Tel: 97237799

VEHICLE NO : FBP 1228X

Honda PCX 150

ACCIDENT DATE: 17 March 2020

| <u>Description</u>                               | <u>Qty</u> | <u>Quotation \$</u> |
|--------------------------------------------------|------------|---------------------|
| 1 Handle Bar <i>HH</i>                           | 1          | 105.00 X            |
| 2 Visor <i>Cut</i>                               | 1          | 280.00 ✓            |
| 3 Head Lamp Assy <i>Crack</i>                    | 1          | 850.00 ✓            |
| 4 Head Lamp Panel - Front <i>Cut</i>             | 1          | 105.00 ✓            |
| 5 Front Side Panel L/RH <i>N/S Cut o/s crack</i> | 2          | 260.00 ✓            |
| 6 Front Mudguard <i>broken/cut</i>               | 1          | 350.00 ✓            |
| 7 Lower Panel - Belly Pan <i>Cut</i>             | 1          | 150.00 ✓            |
| 8 LH Step Board Panel <i>cut</i>                 | 1          | 150.00 X ✓          |
| 9 Mirror <i>cut N/S</i>                          | 1 set      | 78.00 ✓ 39.00       |
| 10 Exhaust Guard <i>HH</i>                       | 1          | 120.00 X            |
| 11 Initiation Switch Cover RH <i>HH</i>          | 1          | 150.00 X            |
| 12 Fork Tube <i>distorted</i>                    | 1 set      | 560.00 ✓            |
| 13 Fork Tube Bracket Under <i>HH</i>             | 1          | 250.00 X            |
| Sub-Total                                        |            | 3,408.00            |
| Less 10%                                         |            | 340.80              |
| Sub-Total                                        |            | 3,067.20            |

2744.00

10% 2469.60

VEHICLE NO : FBP 1228X

Honda PCX 150

Nett Items

- 1 Towing fee *NH*
- 2 Remove & replace necessary parts, align & etc
- 3 Remove & change fork tube, top up fork oil seal - re-align
- 4 Putty & touch up paint work

40.00 X  
~~280.00~~ 200/-  
~~150.00~~ 80/-  
~~320.00~~ 150/-

430.00

Sub-Total

790.00

Nett Total

3,857.20

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion.  
Thank you

02/14/2020 11:00h

Nut Antenna

4/sum 3 days

2899.60

4/5 2300/-

S9 MOTOR TRADING PTE LTD

:LG

*ngan*

2 KLC Antenna

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: