



KT GARAGE PTE LTD UEN: 201906115R
Auto Bay@ Kaki Bukit Entrance A
BLK 1 Kaki Bukit Ave 6 #01-04 Singapore 417883

Handwritten: Walter Joseph

Not Authorized
Handwritten: 4/s @ 6750 / 4 days.
1/4/20

Date : 2/1/2020

Total Pages : 1

TO: AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way Singapore 079120

Our Customer : Global Advance Leasing
Vehicle No : **SLL1992A**
Model : LAND ROVER DISCOVERY
Manufacture Year : 2016
Date of Accident : 3/23/2020

Handwritten: SALCMA

Total Estimate Repair Days : 8

Attn : Motor Claim Department
Email :

Re: Repair Estimate For Third Party Claim against : SDD8989B

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Rear bumper	1	\$1,650.00	\$1,650.00	Dis ✓
2	Rear bumper side retainer	2	\$96.00	\$192.00	11 X
3	Rear bumper lower garnish	1	\$590.00	\$590.00	cut/trim ✓
4	Rear bumper reflector <i>315.72</i>	2	\$346.00	\$692.00	o/sena 1pc
5	Rear bumper lower bracket	2	\$214.00	\$428.00	11 X
6	Rear bumper reverse sensor	1	\$340.00	\$340.00	short 200 s. Netf
7	Rear bumper tow hook cover	1	\$23.00	\$23.00	11 X
8	Rear bumper reinforcement	1	\$620.00	\$620.00	Beut ✓
9	Tailgate assembly <i>3012.39</i>	1	\$3,055.00	\$3,055.00	Body 20 ✓
10	Tailgate lock	1	\$256.00	\$256.00	twi/shld ✓
11	Tailgate actuator	1	\$445.00	\$445.00	11 X
12	Tailgate outer switch	1	\$173.00	\$173.00	11 X
13	Tailgate inner switch (close)	1	\$145.00	\$145.00	11 X
14	Tailgate keyless sensor	1	\$230.00	\$230.00	11 X
15	Tailgate hinges	2	\$42.00	\$84.00	11 X
16	Tailgate damper	2	\$1,808.00	\$3,616.00	11 X
17	Tailgate reflector	2	\$250.00	\$500.00	11 X
18	Tailgate inner trim board	1	\$525.00	\$525.00	pa/cra ✓
19	Tailgate inner trim board side cover	2	\$47.00	\$94.00	11 X
20	Taillamp	2	\$701.00	\$1,402.00	11 X
21	Taillamp clips	4	\$37.00	\$148.00	11 X
22	Rear number plate lamp	1	\$38.00	\$38.00	11 X
23	Reverse camera	1	\$883.00	\$883.00	11 X
24	DISCOVERY' emblem	1	\$168.00	\$168.00	rec ✓
25	LAND ROVER emblem	1	\$9.00	\$9.00	rec ✓
26	Sport emblem	1	\$20.00	\$20.00	rec ✓
27	Si4 Emblem	1	\$90.00	\$90.00	rec ✓
28	Rear number plate	1	\$50.00	\$50.00	11 X
29	End panel	1	\$185.00	\$185.00	11 X
30	End panel top garnish	1	\$1,176.00	\$1,176.00	11 X
31	End panel weatherstrip	1	\$305.00	\$305.00	twi ✓
32	End panel catch	1	\$766.00	\$766.00	11 X
33	Exhaust heatshield	2	\$210.00	\$420.00	11 X
	Sub Total			\$19,318.00	
	Less 10%			\$1,931.80	
	Sub Total 1			\$17,386.20	
B.	Spare parts (S/Nett)				
1	Rear windscreen glass primer	1	\$50.00	\$50.00	11 X
2	Rear windscreen sealant	2	\$25.00	\$50.00	rec 40
3	Rear windscreen inner seal	1	\$25.00	\$25.00	rec ✓



KT GARAGE PTE LTD UEN: 201906115R
Auto Bay@ Kaki Bukit Entrance A
BLK 1 Kaki Bukit Ave 6 #01-04 Singapore 417883

4	Sundries	1	\$40.00	\$40.00	11 X
			Sub Total 2	\$165.00	
			Total for Parts	\$17,551.20	
C.	Labour				
1	To knock and straighten necessary portion. To remove and renew damaged panel. To adjust and realign the same		\$1,200.00		500
2	To rust proof all affected areas		\$180.00		30
3	To check all lighting and wiring		\$160.00		20
4	Labour to install reverse sensor		\$180.00		50
5	Labour to install reverse camera		\$180.00		120
6	To remove and refit tailgate windscreen glass		\$180.00		60
7	To remove and trsnefr mechanical parts		\$280.00		11 X
8	To do a water seepage and wind noise test		\$120.00		11 X
9	To reset default code		\$280.00		✓
10	To spray paint all affected areas		\$600.00		
			Total Labour	\$3,360.00	
			Total Repair Cost	\$20,746.20	
			* The above quoted are exclusive of GST.		

Yours faithfully,

Darla
f KT Garage Pte Ltd

Surveyor's Details	
Name	Marcus Elka
Contact	90096608
Survey Date	11/4/20
Recommend	Authorize / Not Authorize
Before Paint	Yes / No
Signature	

DATE	Remark From Mr Tan
	Please arrange for survey asap

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 7561.11
102
P- 6804.99
S.N- 265.00
L- 1380.00
8049.99
202
6759.



KT GARAGE PTE LTD UEN: 201906115R

Auto Bay@ Kaki Bukit Entrance A

BLK 1 Kaki Bukit Ave 6 #01-04 Singapore 417883

Date : 01/02/2020

Total Pages : 1

Our Customer : Global Advance Leasing

Vehicle No : SLL1992A

Model : LAND ROVER DISCOVERY

Manufacture Year : 2016

Date of Accident : 23/03/2020

Total Estimate Repair Days : 8

Attn : Motor Claim Department

Email :

Re: Repair Estimate For Third Party Claim against : SDD8989B

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Rear bumper <i>DRS ✓</i>	1			
2	Rear bumper side retainer <i>an x</i>	2			
3	Rear bumper lower garnish <i>an x / 200 ✓</i>	1			
4	Rear bumper reflector <i>al/cra 1pc</i>	2			
5	Rear bumper lower bracket <i>an x</i>	2			
6	Rear bumper reverse sensor <i>shab ✓</i>	1			
7	Rear bumper tow hook cover <i>an x</i>	1			
8	Rear bumper reinforcement <i>3an ✓</i>	1			
9	Tailgate assembly <i>3.6500 ✓</i>	1			
10	Tailgate lock <i>twi/shab ✓</i>	1			
11	Tailgate actuator <i>an x</i>	1			
12	Tailgate outer switch <i>an x</i>	1			
13	Tailgate inner switch (close) <i>an x</i>	1			
14	Tailgate keyless sensor <i>an x</i>	1			
15	Tailgate hinges <i>an x</i>	2			
16	Tailgate damper <i>an x</i>	2			
17	Tailgate reflector <i>an x</i>	2			
18	Tailgate inner trim board <i>ae/cue ✓</i>	1			
19	Tailgate inner trim board side cover <i>an x</i>	2			
20	Taillamp <i>an x</i>	2			
21	Taillamp clips <i>an x</i>	4			
22	Rear number plate lamp <i>an x</i>	1			
23	Reverse camera <i>an x</i>	1			
24	DISCOVERY' emblem <i>an ✓</i>	1			
25	LAND ROVER emblem <i>an ✓</i>	1			
26	Sport emblem <i>an ✓</i>	1			
27	Si4 Emblem <i>an ✓</i>	1			
28	Rear number plate <i>an x</i>	1			
29	End panel <i>an x</i>	1			
30	End panel top garnish <i>an x</i>	1			
31	End panel weatherstrip <i>an ✓</i>	1			
32	End panel catch <i>an x</i>	1			
33	Exhaust heatshield <i>an x</i>	2			
	Sub Total			\$0.00	
	Less 35%			\$0.00	
	Sub Total 1			\$0.00	
B.	Spare parts (\$/Nett)				
1	Rear windscreen glass primer <i>an x</i>	1			
2	Rear windscreen sealant <i>an 40</i>	2			
3	Rear windscreen inner seal <i>an 30</i>	1			
4	Sundries <i>an x</i>	1	\$40.00	\$40.00	
	Sub Total 2			\$40.00	
	Total for Parts			\$40.00	
C.	Labour				
1	To knock and straighten necessary portion. To remove and renew damaged panel. To adjust and realign the same			\$1,200.00	500

wh

not Anthony
dine

1/58
of Long S.

11/4/20

Take the other
net