

22/03/2020

ASS. REC. BY:

REF: CS/SMO20004787/EVD3

Special Instruction: ☒

Surveyor:

ASSIGNMENT (Office)

From (Person): Grace Teo

of

SMO

Date/Time: 4pm 1/4/2020

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SJN7560L

Insured:

SJ 1101P

at Workshop m/s

Auburn Auto

Tel:

9787 5558

of

176 Sn Ming Drive #04-18

Policy No:

Claim No:

CMTD 2001300/RUC

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/03/2020

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

4:11pm 1/4/2020

Person Contacted:

Sam

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate	Ins: 3AMK st. 62 #01-45
	SJN7560L - CVI/VAL 11015900/Kal	DOA: -	
	SJ 1101P-X		
3/4/20	Email preli revised to Ruth		
14/4/20	LS \$750 confirmed by email (Red 7925, 919)		

Steve,

Pls check parts prices.



8/4

AUBURN AUTO PTE LTD

176 Sin Ming Drive #04-18 Sin Ming Autocare, Singapore 575721

Tel : +65 9787 5558

Email: samuel.auburnauto@gmail.com

Vehicle No: SJN7506L

Model: Toyota Wish

QTY	Description	Repairer's Estimate
Spare Parts - List Items		
1	Rear L/H Panel X NN	\$ 1,100.00
1	Rear L/H Panel Mechanism X NN	\$ 600.00
1	Rear L/H Door Lock X NN	\$ 280.00
1	Rear L/H Panel Windscreen Seal X NN	\$ 105.00
1	Rear L/H Panel Bumper / 00	\$ 1,200.00
1	Rear L/H Panel Bumper Side Retainers / BR	\$ 250.00
1	Rear L/H Panel Bumper Reflectors X NN	\$ 720.00
1	Rear L/H Panel Garnish X NN	\$ 260.00
1	Rear L/H Panel Inner Garnish X NN	\$ 350.00
1	Rubber Moulding X NN	\$ 120.00
1	Rear L/H Head Light X NN	\$ 750.00

500.30
144.20

\$ 5,735.00

Page 1 of 3

c/f: \$

\$ 5,735.00

Special Nett Items		AMT S\$
1	Rear L/H Windscreen Sealant <i>NH</i>	\$ 120.00 <i>X</i>
1	Rear L/H Panel bumper clip	\$ 150.00 <i>30/</i>
		\$ 270.00
S/N.	Labour Charges	
1	Remove and refit rear R/H Panel	\$ 500.00 <i>X</i>
2	Remove and refit rear R/H Panel bumper	\$ 300.00 <i>300</i>
3	Remove, refit and replaced damage and check up rear electrical wiring	\$ 150.00 <i>30</i>
4	Remove and refit inner garnishes trim to assist repair	\$ 200.00 <i>X</i>
5	To apply undercoating on replaced panel	\$ 120.00 <i>X</i>
6	To Respray Painting.	\$ 1,400.00 <i>300</i>
		\$ 2,670.00
GRAND TOTAL		\$ 8,675.00

Page 2 of 3

Survey:

1st / 2nd / 3rd

(delete accordingly)

Surveyor Details:

(Name)

Steve (LKK)

(Contact)

8322 8813

(Email)

(Signature)



(Date/Time)

2 / 4 / 20, 3-30pm

W/L M/L

L/S

My AC sy

2 dys

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- subject to final approval from Insurance Company

As acknowledged by Repairer

Signature:

Date: