

TPEQ Xiew Chen.

H/PHONE: 97236654

FAX: 68425778

HENG KEE WORKSHOP

BLK 103 BUNOL AVE SA FONG SINGAPORE 40703
HP: 8136 2761

GBJ 964 3

JTFA135770K212138

FRONT BUMPER \$683.90 Distorted ✓
02 PCS FRONT BUMPER BRACKET \$211.60 X 2 = \$423.20 ^{211.60} RH Bent ✓
FRONT DOOR RH \$1349.30 Dented ✓
02 PCS FRONT DOOR HINGE \$85.20 X 2 = \$170.40 Bent ✓
FRONT DOOR STICKER \$28 New ✓
FRONT SIDE PANEL \$316.10 ^{Dented} Missing ✓
FRONT SIDE PANEL BRACKET \$48.40 Bent ✓
FRONT GRILLER \$424.10 ^{crackd.} Missing ✓
FRONT GRILLER LOGO \$70.40 New ✓
FRONT PANEL \$1286.20 Rep. X.
FRONT PANEL DYNA LOGO \$60.80 New ✓
FRONT AIR SWITCH \$104.20 New X
FRONT WINDSCREEN RUBBER \$288.60 New X
02 PCS FRONT HEADLAMP ~~\$2,358.80~~ ^{1463.80} ~~PA~~ ^{crackd.} ✓
LABOUR COST 4826.80
WIRING CHECKING \$120.00 30 ^{Len 25% 3620.10}
REMOVE & INSTALL DASHBOARD PANEL \$380.00 X
REMOVE & INSTALL AIR - CONDITIONER SYSTEM }
INCLUDING REFILLING OF LIQUIFIED GAS } \$220.00 X 1530
SPRAY PAINTING \$1,200.00 800
LABOUR CHARGE \$950.00 700
10,482.40#

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj

W/S 07/04/20.

06 Days.

total: 5150.10

W/S: 4.1K.