

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 34211

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0343/2020/NS
Date	:	30-Mar-20

Vehicle NOT IN workshop. Kindly arrange for survey.

NTUC Income Insurance Co - Claims Department

73 Bras Basah Road

#05-01 NTUC Trade Union House

Singapore 189556

Attn: Motor Claims Dept

Tel: Fax 6338 1504

Owner's Name	:	Ms Li Ou
Address	:	412 Upper East Coast Road #05-10 Singapore 466488
Telephone	:	(HP) 91913450
Type of Claim	:	Third Party Claims 00
Policy No.	:	1700070039-02
Vehicle No	:	SLS 2376 K
Model Code	:	Audi A5 SB 2.0 TFS
Model / Year	:	14/9/2017
Engine No	:	CVK 043513
Chassis No	:	WAUZZZF50JA022089
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	26-Mar-20
Place of Accident	:	Newton Circus

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLS 2376 K

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N	\$ 360.00 ✓	
2	To renew 1/4 glass to facilitate fender renewal.	S/N	\$ 300.00 ✗	
3	To install solar film for 1/4 glass.	S/N	\$ 400.00 ✗	
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N	\$ 1,400.00 ✗	
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N	\$ 1,400.00 ✗	
SUB TOTAL LABOUR CHARGES		:	<u>\$ 3,860.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLS 2376 K

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
6	To remove and trf rhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$	280.00 ✓	
7	To dismantle and renew rear bumper, rhs rear door and rhs sill panel trim. Cut out and weld rhs rear fender. Re-organise crash management components. Reinstall all parts removed.	\$	7,200.00	1750
8	To respray rear bumper, rhs rear door, door handle, rhs rear fender, rhs sill panel, door entrances, roof channel, drain panel, rhs sill panel trim and end panelling. To carry out stone chip treatment and joint sealer works.	\$	7,300.00	2575
9	To renew rhs rear rim and carry out wheel alignment.	S/N \$	280.00 ✓	
10	To carry out diaqnostic check.	S/N \$	192.00 ✓	
TOTAL LABOUR CHARGES		:	\$ 19,112.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 2376 K

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER X R	\$	2,385.00
2	REAR BUMPER FIXING PARTS ?	\$	156.00
3	REAR BUMPER SECURING STRIP ?	\$	210.00
4	TRIM MOLDING X NN	\$	958.00
5	REAR LIGHT REFLECTOR - RH X NN	\$	39.00
6	REAR BUMPER GUIDE SECTION - RH X NN	\$	41.00
7	SIDE PANEL - RH X R	\$	2,354.00
8	SIDE WINDOW - RH X NN	\$	676.00
9	WHEEL HOUSING LINER - RH X NN	\$	259.00
10	WHEEL HOUSING LINER ATTACHMENT PARTS X NN	\$	86.00
11	REAR DOOR - RH / 00	\$	2,946.00
12	REAR DOOR OUTER SEAL - RH / M	NEC \$	209.00
13	BONDING AGENT - M	NEC \$	46.00
14	CLEANING SOLUTION - M	NEC \$	64.00
15	REAR DOOR ATTACHMENT PARTS ?	\$	122.00
16	REAR DOOR CATCH ?	\$	113.00
17	DOOR HANDLE TRIM PLATE - RH / MJS	\$	83.00
18	HANDLE BEZEL TRIM - RH / M	\$	128.00
19	DOOR HANDLE SENSOR - RH ?	\$	215.00
20	EXTERIOR DOOR HANDLE - RH ?	\$	40.00
SUB TOTAL SPARE PARTS CHARGES		\$	<u>11,130.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 2376 K

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	MOUNTING BAR - RH X NN	\$	154.00
22	SILL PANEL TRIM ATTACHMENT PARTS / M	\$	123.00
23	SILL PANEL TRIM ADHESIVE TAPES / M	\$	200.00
24	SIDE MEMBER TRIM - RH X R	\$	778.00
25	REAR ALUMINIUM RIM - RH / M	\$	964.00
26	ACRYLIC SEALANT X NN	S/N \$	180.00
27	CAVITY WAX X NN	S/N \$	140.00
28	STONE CHIP X NN	S/N \$	180.00
29	METAL FILLER POWDER X NN	S/N \$	280.00
30	1/4 GLASS SEALANT X NN	S/N \$	100.00
31	SUNDRIES	\$	400.00
TOTAL SPARE PARTS CHARGES		\$	14,629.00
TOTAL LABOUR CHARGES		:	\$ 19,112.00
GRAND TOTAL		\$	33,741.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

:

Steve (LKK)

Surveyed Date

:

7 dys

Authorised Date

:

Excess Cost

:

EXCESS - ?

Liability

:

P/P

Remarks

:

My BL sy

Please Note

: This estimate is based on visual inspection of the affected vehicle.

Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant