

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 07 Apr 2020

Preliminary Advice

Insured Vehicle No	: SMN6888M		
TP Vehicle No	: SHD7198B	Accident Date	: 31/03/2020
Make	: HYUNDAI I40	Assignment Date	: 01/04/2020
Date of Inspection	: 02/04/2020	Est. Duration of Repair	: 6.00
Inspection At	: BIFROST AUTO PTE LTD (SIN MING) (HQ) BLK 9 SECTOR C, #01-42 SIN MING INDUSTRIAL ESTATE SINGAPORE 575644		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	30,853.68
Revised Amount	:S\$	11,930.56
Check Items (Estimated)	:S\$	249.28
Total	:S\$	12,179.84

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks,

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.