

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CTI20004795/Uqf3

ASSIGNMENT

From: Date:

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

G/A / PR Seen:

Consistent? : Yes or No

Est. Repairs:

10

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

21/4/20 2/5 @ 9000 confirmed with Tony (Red \$7718.45, 46%)

Veh No:

GBH 4337L

Yr Regn:

5, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Dyna

c.c

2982

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

33903

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFAT35/40K 210477

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/75 R15

R:

155- R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

0/6

mm

L/Bal.

6

mm

L/Bal.

0/6

mm

D.O.A.

27/3/20

D.O.I.

2/4/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & all.

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1) 22/04 Typist

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

10

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

) ___ S + RS ___ SI

) Photos

) Others

Report Format : MER-TP

Lump Sum ~~118.1~~ (\$ 9000)

TOTAL



Tony Automotive Pte Ltd

8 Kaki Bukit Ave 4 #04-07 Premier @ KB Singapore 415875

Tel: 69763261 Fax: 69763271

Email: tony07auto@gmail.com

Co. Reg No.: 201939168R

Model : **TOYOTA DYNA**

Veh No: **GBH4337L**

Qty

List Items

Amount S\$

1	FRT PANEL	Body	1150.6	✓
1	FRT PANEL DYNA LOGO	neu	65	✓
1	WIPER PANEL	328.10	515.6	✓
1	FRT GRILLE	Cm	550.8	✓
1	GRILLE TOP SEAL	11	35	X
1	GRILLE TOYOTA LOGO	neu	75	✓
2	HEADLAMP L/R	Cm	1960.4	✓
1	FRT BUMPER	525.10	785.4	✓
2	FRT BUMPER STAY L/R	245 x 25490	620.4	✓
1	FRT BUMPER REINFORCEMENT	NS	451.2	X
1	HEADLAMP LOWER SEAL	11	60	X
1	FRT LH SIDE MIRROR BRACKET	11	915.1	X
1	REAR TAIL BOARD	1/2 set	1367.9	✓
1	REAR TAIL BOARD DYNA STICKER	neu	35	✓
4	TAIL BOARD HINGE	11	660.8	X
1	REAR TAIL BOARD TOYOTA STICKER	neu	225	✓
2	REAR TAIL BOARD SIDE BRACKET	115.00	388.4	1/2 C
2	TAIL LAMP L/R	296.90	900.4	1/2 C
2	TAIL LAMP BRACKET L/R	110.20	220	1/2 C
1	REAR NUMBER PLATE BRACKET	set	165	✓
1	REAR NUMBER PLATE LAMP	11	70	X
2	REAR REVERSE SENSOR	shld	682	200 S.N
1	REAR TOYOTA STICKER	Repair	150	X
1	REAR DYNA STICKER	Repair	40	X
1	AIRCON BLOWER	Cm	1218.2	✓
1	AIRCON UNIT heater unit	1919.40	2021.8	✓
1	WASHER TANK	255.10	568.4	✓

Parts Total 15897.4

Less 25% 3974.35

11923.05

Special Nett Items

Qty

List Items

Amount S\$

1	70KM/H STICKER	neu	30	10 S.N
1	13 PAX STICKER	neu	30	10 S.N
1 SET	GRILLE CLIP	11	35.4	X
Sub Total			95.4	

Not Authorized
nhan

2/4/20
1/5 9000/
10 days.

Take photo. Author 11/1

Labour charges

REMOVE AND REFIT WINDSHIELD	200	80
REMOVE AND REFIT DASHBOARD	350	200
REFILL AIRCON GAS	80	✓
CHECK ELECTRICAL WIRING FRONT AND BACK	300	30
CHECK WHEEL ALIGNMENT	120	X
RESPRAY UNDERCOATING	350	80
RESPRAY PAINTING	1500	1300
PANEL BEATING, REMOVE AND REPLACE PARTS ETC	1800	150
Sub Total	4700	

ESTIMATE PARTS AND LABOUR GRAND TOTAL S\$

16718.45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p-10842.50
252
p-8139.37
S.u-220.00
h-2920.00
11279.37
202
9023.49