

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 34609

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0348/2020/KK
Date : 31-Mar-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Mohamed Hazriq Bin Hamzah Surattee
Address : 253 Wak Hassan Drive
Singapore 757532
Telephone : HP +65 86069998
Type of Claim : Own Damage Claims
Policy No. : 1900148156
Vehicle No : **SJB 9998 H**
Model Code : Audi Q2 1.0 TFSI S TRONIC
Model / Year : Aug-19
Engine No : CHZ C32402
Chassis No : WAUZZZGA9KA081249
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 30-Mar-20
Place of Accident : Watercove At Wak Hassan Drive

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJB 9998 H

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor S/N and headlight washer assy.	\$ 360.00	✓
2	To dismantle and renew front bumper, lhs front fender and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,800.00 <i>500 x 1.5</i>	1000 500 750 ✓
3	To respray front bumper and lhs front fender.	\$ 2,200.00 <i>550 x 2</i>	1100 ✓
4	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: <u>\$ 5,552.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJB 9998 H

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
1	FRONT BUMPER / CUT	\$ 1,763.00	1410.40
2	FRONT BUMPER FIXING PARTS ? X NN	\$ 326.00	
3	FRONT BUMPER GRILLE - CENTRE X NN	\$ 186.00	
4	FRONT BUMPER AIR GUIDE GRILLE - LH / OR	\$ 159.00	127.20
5	FRONT BUMPER END CAP - LH ? ✓ CRA	\$ 32.00	25.44
6	FRONT BUMPER SPOILER - ✓ CRA	\$ 282.00	225.20
7	FRONT BUMPER CLOSING ELEMENT ? X NN	\$ 147.00	
8	WHEEL SPOILER - LH / CUT	\$ 32.00	25.44
9	FRONT BUMPER ADAPTER - LH ? ✓ NEC	\$ 34.00	26.72
10	RADIATOR GRILLE ? X NN	\$ 1,328.00	
11	RADIATOR GRILLE STRIKER PLATE X NN	\$ 117.00	
12	FRONT BUMPER CARRIER ? ✓ BT	\$ 646.00	516.80
13	FRONT BUMPER COVER ? X NN	\$ 95.00	
14	FRONT BUMPER FOAM FILLER PIECE ? X NN	\$ 73.00	
15	FRONT BUMPER GUIDE SECTION - LH ? X NN	\$ 34.00	
16	CAUTION SIGN STICKER X NN	NEC \$ 13.00	
17	AIRCON STICKER X NN	NEC \$ 7.00	
18	HORN - LH LOW TONE ? X NN	\$ 270.00	
19	SPRING SHACKLE - LH X NN	\$ 30.00	
20	FRONT FENDER - LH X R	\$ 1,079.00	
SUB TOTAL SPARE PARTS CHARGES		: \$ 6,653.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJB 9998 H

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
21	FRONT FENDER ATTACHMENT PARTS X NN	\$ 38.00	
22	FRONT FENDER BRACKET - LH X NN	\$ 45.00	
23	FRONT FENDER BRACKET - LH X NN	\$ 15.00	
24	FRONT FENDER BRACE - LH X NN	\$ 35.00	
25	WHEEL HOUSING LINER - LH X NN	\$ 185.00	
26	WHEEL HOUSING LINER ATTACHMENT PARTS X NN	\$ 54.00	
27	FRONT WHEEL COVER - (LH)/(RH) / MC 2	\$ 606.00	484
28	HEADLIGHT MOUNTING - LH 1 x NN	\$ 112.00	
29	LED HEADLIGHT - LH / CVT	\$ 4,627.00	3701.60
30	LIFT CYLINDER - LH 1 x NN	\$ 134.00	
31	LIFT CYLINDER HOSE 1 x NN	\$ 172.00	
32	WASH WATER RESERVOIR 1 x NN	\$ 158.00	
33	RADIATOR AIR GUIDE - LH 1 x NN	\$ 29.00	
34	RADIATOR AIR GUIDE - UPPER CENTRE 1 x NN	\$ 21.00	
35	FRONT NO PLATE X NN S/N	\$ 60.00	
36	SUNDRIES 1 x NN	\$ 300.00	
TOTAL SPARE PARTS CHARGES		: \$ 13,244.00	
TOTAL LABOUR CHARGES		: \$ 5,552.00	
GRAND TOTAL		: \$ 18,796.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :

Surveyed Date :

Authorised Date :

Excess Cost :

Liability :

Remarks :

2/4/19, 11.15 am
Steve (LKK) 00 - NH ATL (Pnl)
54 dgs
P/P
my Pol my
Excess - ?

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9823 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant