



Case Details

Case Reference Number :

TAX/03/20/2097

Type of Repair : Accident Repair

Vehicle Registration Number :

SHB5261A

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-11045-ID

Assigned By : Taxi Claims Manager
Team

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd

Accident Date and Time : 31/03/2020 01:10 AM

Vehicle Age(In Months) : 29

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	371.63	Replace ▾	
One Time Key In	Main			SUPPORT, FR BUMPER RH	1	76.90	76.90	25.00	57.68	Replace	1	57.68	Replace ▾	
One Time Key In	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	1	61.72	Replace ▾	
One Time Key In	Main			COVER, FR BUMPER RH	1	28.10	28.10	25.00	21.08	Replace	1	21.08	Replace ▾	
One Time Key In	Main			COVER, FR BUMPER LH	1	28.10	28.10	25.00	21.08	Replace	1	21.08	Replace ▾	
One Time Key In	Main			BRACKET, FR BUMPER	1	99.80	99.80	25.00	74.85	Replace	1	74.85	Replace ▾	
One Time Key In	Main			SEAL, HOOD TO FR END	1	24.40	24.40	25.00	18.30	Replace	1	18.30	Replace ▾	
One Time Key In	Main			EMBLEM ASSY FRONT	1	87.10	87.10	25.00	65.32	Replace	1	65.32	Replace ▾	
One Time Key In	Main			GRILLE, RADIATOR	1	165.00	165.00	25.00	123.75	Replace	1	123.75	Replace ▾	
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace ▾	
Total Spare Part Cost									36,363.15					
Lump Sum Discount (%)									0.00					
Final Spare Part Cost									36,363.15					
											Surveyor Total	15,012.97		
											Lump Sum Dis (%)	0		
											Final Sur Total	15,012.97		

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			RETAINER, FR BUMPER, LH & RH	1	8.50	8.50	25.00	6.38	Replace	1	6.38	Replace	
One Time Key In	Main			COVER ASSY, ENGINE	1	180.10	180.10	25.00	135.07	Replace	0	0	Not Give	
One Time Key In	Main			COVER ASSY, ENGINE UNDER CENTER SET	1	452.80	452.80	25.00	339.60	Replace	0	0	Check	
One Time Key In	Main			COVER, ENGINE UNDER CENTER	1	94.50	94.50	25.00	70.88	Replace	1	70.88	Replace	
One Time Key In	Main			COVER, ENGINE UNDER SIDE RH	1	76.90	76.90	25.00	57.68	Replace	1	57.68	Replace	
One Time Key In	Main			COVER, ENGINE UNDER SIDE LH	1	76.90	76.90	25.00	57.68	Replace	0	0	Check	
One Time Key In	Main			COVER, ENGINE UNDER, REAR	1	36.50	36.50	25.00	27.38	Replace	0	0	Not Give	
One Time Key In	Main			GRILLE SUB-ASSY	1	335.60	335.60	25.00	251.70	Replace	1	251.70	Replace	
One Time Key In	Main			REINFORCEMENT FRONT UPPER	1	691.10	691.10	25.00	518.33	Replace	1	518.33	Replace	
One Time Key In	Main			ABSORBER, FR BUMPER	1	70.30	70.30	25.00	52.72	Replace	1	52.72	Replace	
One Time Key In	Main			EXTENSION SUB-ASSY, LH	1	116.30	116.30	25.00	87.22	Replace	1	87.22	Replace	
One Time Key In	Main			EXTENSION SUB-ASSY, RH	1	116.30	116.30	25.00	87.22	Replace	1	87.22	Replace	
One Time Key In	Main			REINFORCEMENT FRONT LOWER	1	238.50	238.50	25.00	178.88	Replace	1	178.88	Replace	
One Time Key In	Main			ABSORBER, FR BUMPER LOWER	1	117.00	117.00	25.00	87.75	Replace	1	87.75	Replace	
One Time Key In	Main			FRONT REINFORCEMENT SIDE RH	1	128.20	128.20	25.00	96.15	Replace	0	0	Check	
One Time Key In	Main			FRONT REINFORCEMENT SIDE LH	1	129.30	129.30	25.00	96.98	Replace	0	0	Check	
Total Spare Part Cost									36,363.15			Surveyor Total	15,012.97	
Lump Sum Discount (%)									0.00			Lump Sum Dis (%)	0	
Final Spare Part Cost									36,363.15			Final Sur Total	15,012.97	

SMRT Recommendation												Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			FRONT PLATE, FR SUSPENSION	1	9.40	9.40	25.00	7.05	Replace	0	0	Check	
One Time Key In	Main			FENDER SUB-ASSY, FR , RH	1	933.10	933.10	25.00	699.83	Replace	1	0	Repair	
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	1	39.67	Replace	
One Time Key In	Main			FENDER SUB-ASSY, FR , LH	1	933.10	933.10	25.00	699.83	Replace	1	699.83	Replace	
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	1	39.67	Replace	
One Time Key In	Main			LINER, FR FENDER, RH	1	198.40	198.40	25.00	148.80	Replace	1	148.80	Replace	
One Time Key In	Main			LINER, FR FENDER, LH	1	194.30	194.30	25.00	145.73	Replace	1	145.73	Replace	
One Time Key In	Main			HOOD SUB-ASSY	1	938.40	938.40	25.00	703.80	Replace	1	703.80	Replace	
One Time Key In	Main			INSULATOR, HOOD	1	393.90	393.90	25.00	295.42	Replace	1	295.42	Replace	
One Time Key In	Main			INSULATOR, HOOD CLIP	6	2.30	13.80	25.00	10.35	Replace	6	10.35	Replace	
One Time Key In	Main			SEAL SUB-ASSY, RH	1	50.20	50.20	25.00	37.65	Replace	1	37.65	Replace	
One Time Key In	Main			SEAL SUB-ASSY, LH	1	50.20	50.20	25.00	37.65	Replace	1	37.65	Replace	
One Time Key In	Main			RETAINER, FR WHEEL LH	1	3.10	3.10	25.00	2.33	Replace	1	2.33	Replace	
One Time Key In	Main			RETAINER, FR WHEEL RH	1	3.10	3.10	25.00	2.33	Replace	1	2.33	Replace	
One Time Key In	Main			PROTECTOR, FR FENDER LH	1	90.40	90.40	25.00	67.80	Replace	0	0	Check	
One Time Key In	Main			PROTECTOR, FR FENDER RH	1	90.40	90.40	25.00	67.80	Replace	0	0	Check	
Total Spare Part Cost									36,363.15	Surveyor Total 15,012.97				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									36,363.15	Final Sur Total 15,012.97				

SMRT Recommendation												Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			RETAINER, FR FENDER NO. 2	1	16.80	16.80	25.00	12.60	Replace	1	12.60	Replace ▼	
One Time Key In	Main			RETAINER, FR FENDER NO. 1	1	4.90	4.90	25.00	3.68	Replace	1	3.68	Replace ▼	
One Time Key In	Main			PAD, FR WHEEL RH	1	57.70	57.70	25.00	43.28	Replace	0	0	Check ▼	
One Time Key In	Main			PAD, FR WHEEL LH	1	57.70	57.70	25.00	43.28	Replace	0	0	Check ▼	
One Time Key In	Main			HINGE ASSY, HOOD, RH	1	57.00	57.00	25.00	42.75	Replace	1	42.75	Replace ▼	
One Time Key In	Main			HINGE ASSY, HOOD, LH	1	57.00	57.00	25.00	42.75	Replace	1	42.75	Replace ▼	
One Time Key In	Main			CABLE ASSY, HOOD	1	53.20	53.20	25.00	39.90	Replace	0	0	Check ▼	
One Time Key In	Main			LOCK ASSY, HOOD	1	131.10	131.10	25.00	98.32	Replace	1	98.32	Replace ▼	
One Time Key In	Main			COVER, RADIATOR	1	227.80	227.80	25.00	170.85	Replace	1	170.85	Replace ▼	
One Time Key In	Main			SUPPORT S/A UPPER,	1	364.90	364.90	25.00	273.67	Replace	1	273.67	Replace ▼	
One Time Key In	Main			SUPPORT S/A RH	1	237.00	237.00	25.00	177.75	Replace	1	177.75	Replace ▼	
One Time Key In	Main			SUPPORT S/A LH	1	237.00	237.00	25.00	177.75	Replace	1	177.75	Replace ▼	
One Time Key In	Main			SUPPORT SUB-ASSY LOWER	1	397.40	397.40	25.00	298.05	Replace	0	0	Check ▼	
One Time Key In	Main			SUPPORT, RADIATOR UPPER RH	1	76.70	76.70	25.00	57.53	Replace	1	57.53	Replace ▼	
One Time Key In	Main			SUPPORT, RADIATOR UPPER LH	1	76.70	76.70	25.00	57.53	Replace	1	57.53	Replace ▼	
One Time Key In	Main			GUIDE, RADIATOR AIR,	1	93.90	93.90	25.00	70.43	Replace	1	70.43	Replace ▼	
Total Spare Part Cost									36,363.15	Surveyor Total 15,012.97				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									36,363.15	Final Sur Total 15,012.97				

SMRT Recommendation												Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SEAL, RADIATOR GRILLE	1	40.70	40.70	25.00	30.53	Replace	1	30.53	Replace	
One Time Key In	Main			BRACE, HOOD LOCK SUPPORT	1	76.20	76.20	25.00	57.15	Replace	1	57.15	Replace	
One Time Key In	Main			APRON SUB-ASSY, FRONT FENDER, RH	1	944.20	944.20	25.00	708.15	Replace	0	0	Not Give	
One Time Key In	Main			APRON SUB-ASSY, FRONT FENDER, LH	1	944.20	944.20	25.00	708.15	Replace	0	0	Not Give	
One Time Key In	Main			MEMBER SUB-ASSY, FR RH	1	2,012.70	2,012.70	25.00	1,509.53	Replace	1	0	Repair	
One Time Key In	Main			MEMBER SUB-ASSY, FR LH	1	1,959.50	1,959.50	25.00	1,469.63	Replace	1	0	Repair	
One Time Key In	Main			HINGE ASSY, FRONT DOOR, UPPER LH	1	82.10	82.10	25.00	61.57	Replace	0	0	Not Give	
One Time Key In	Main			HINGE ASSY, FRONT DOOR, LOWER LH	1	92.10	92.10	25.00	69.07	Replace	0	0	Not Give	
One Time Key In	Main			PANEL SUB-ASSY, FRONT DOOR LH	1	1,249.60	1,249.60	25.00	937.20	Replace	0	0	Not Give	
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	0	0	Not Give	
One Time Key In	Main			UNIT, HEADLAMP, LH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	1	2,303.0	Replace	
One Time Key In	Main			UNIT, HEADLAMP, RH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	1	2,303.0	Replace	
One Time Key In	Main			COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	1	486.40	486.40	10.00	437.76	Replace	0	0	Check	
One Time Key In	Main			COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	1	486.40	486.40	10.00	437.76	Replace	0	0	Not Give	
One Time Key In	Main			LAMP ASSY, FOG, RH	1	910.20	910.20	10.00	819.18	Replace	1	819.18	Replace	
One Time Key In	Main			LAMP ASSY, FOG, LH	1	910.20	910.20	10.00	819.18	Replace	1	819.18	Replace	
Total Spare Part Cost									36,363.15	Surveyor Total 15,012.97				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									36,363.15	Final Sur Total 15,012.97				

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BATTERY	1	1,584.90	1,584.90	10.00	1,426.41	Replace	0	0	Check	
One Time Key In	Main			BLOCK ASSY, FUSIBLE LINK	1	99.80	99.80	10.00	89.82	Replace	0	0	Check	
One Time Key In	Main			WIRE, ENGINE ROOM MAIN	1	6,138.00	6,138.00	10.00	5,524.20	Replace	0	0	Check	
One Time Key In	Main			WIRE, ENGINE, NO.3	1	260.40	260.40	10.00	234.36	Replace	0	0	Check	
One Time Key In	Main			COVER, FUSIBLE LINK	1	28.30	28.30	25.00	21.23	Replace	0	0	Check	
One Time Key In	Main			BLOCK, JUNCTION	1	15.80	15.80	10.00	14.22	Replace	0	0	Check	
One Time Key In	Main			INVERTER WATER PUMP ASSY	1	432.00	432.00	10.00	388.80	Replace	0	0	Check	
One Time Key In	Main			HOSE, HV WATER PUMP OUTLET	1	29.60	29.60	25.00	22.20	Replace	0	0	Check	
One Time Key In	Main			HOSE, HV WATER PUMP INLET	1	37.90	37.90	25.00	28.42	Replace	0	0	Check	
One Time Key In	Main			TANK ASSY, INVERTER RESERVE	1	371.30	371.30	25.00	278.48	Replace	0	0	Check	
One Time Key In	Main			HOSE, INVERTER COOLING OUTLET	1	29.60	29.60	25.00	22.20	Replace	0	0	Check	
One Time Key In	Main			HOSE, INVERTER RADIATOR INLET	1	40.70	40.70	25.00	30.53	Replace	0	0	Check	
One Time Key In	Main			HOSE, INVERTER COOLING INLET	1	43.10	43.10	25.00	32.33	Replace	0	0	Check	
One Time Key In	Main			COOLER, MOTOR COOLING	1	249.10	249.10	10.00	224.19	Replace	0	0	Check	
One Time Key In	Main			WIPER WASHER INLET	1	55.40	55.40	25.00	41.55	Replace	0	0	Check	
One Time Key In	Main			WIPER WASHER JAR	1	183.60	183.60	25.00	137.70	Replace	0	0	Not Give	
Total Spare Part Cost									36,363.15	Surveyor Total 15,012.97				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									36,363.15	Final Sur Total 15,012.97				

SMRT Recommendation												Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			MOTOR AND PUMP ASSY, WINDSHIELD WASHER	1	245.00	245.00	10.00	220.50	Replace	0	0	Check	
One Time Key In	Main			NOZZLE, FRONT WASHER	1	34.10	34.10	25.00	25.58	Replace	0	0	Not Give	
One Time Key In	Main			HOSE, WINDSHIELD WASHER	1	14.00	14.00	25.00	10.50	Replace	0	0	Not Give	
One Time Key In	Main			JOINT, WINDSHIELD WASHER HOSE, NO.3	1	4.70	4.70	25.00	3.53	Replace	1	3.53	Replace	
One Time Key In	Main			HORN ASSY, HIGH	1	112.80	112.80	25.00	84.60	Replace	0	0	Check	
One Time Key In	Main			HORN ASSY, LOW	1	112.80	112.80	25.00	84.60	Replace	0	0	Check	
One Time Key In	Main			BRACKET, HORN	1	7.80	7.80	25.00	5.85	Replace	0	0	Check	
One Time Key In	Main			HORN ASSY, SECURITY	1	112.80	112.80	25.00	84.60	Replace	0	0	Check	
One Time Key In	Main			TUBE & ACCESSORY	1	574.40	574.40	25.00	430.80	Replace	0	0	Check	
One Time Key In	Main			AIR CON CONDENSER ASSY	1	1,317.70	1,317.70	25.00	988.28	Replace	1	988.28	Replace	photo
One Time Key In	Main			HOSE SUB-ASSY, DISCHARGE	1	337.10	337.10	25.00	252.83	Replace	0	0	Check	
One Time Key In	Main			HOSE SUB-ASSY, SUCTION	1	541.90	541.90	25.00	406.42	Replace	0	0	Check	
One Time Key In	Main			PIPE SUB-ASSY, SUCTION	1	389.60	389.60	25.00	292.20	Replace	0	0	Check	
One Time Key In	Main			BRACKET, COOLER REFRIGERANT HOSE, NO.1	1	13.20	13.20	25.00	9.90	Replace	0	0	Not Give	
One Time Key In	Main			BRACKET, COOLER REFRIGERANT HOSE, NO.2	1	18.70	18.70	25.00	14.02	Replace	0	0	Not Give	
One Time Key In	Main			SEAL, RADIATOR TO RH	1	24.80	24.80	25.00	18.60	Replace	0	0	Check	
Total Spare Part Cost									36,363.15	Surveyor Total 15,012.97				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									36,363.15	Final Sur Total 15,012.97				

SMRT Recommendation												Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SEAL, RADIATOR TO LH	1	24.80	24.80	25.00	18.60	Replace	0	0	Check	
One Time Key In	Main			GUIDE, RADIATOR AIR , RH	1	54.60	54.60	25.00	40.95	Replace	0	0	Check	
One Time Key In	Main			GUIDE, RADIATOR AIR , LH	1	58.80	58.80	25.00	44.10	Replace	0	0	Not Give	
One Time Key In	Main			GROMMET (FOR RADIATOR LOWER SUPPORT)	1	12.70	12.70	25.00	9.52	Replace	1	9.52	Replace	
One Time Key In	Main			CUSHION, (FOR RADIATOR UPPER SUPPORT)	1	9.80	9.80	25.00	7.35	Replace	1	7.35	Replace	
One Time Key In	Main			GUIDE, RADIATOR AIR , UPPER	1	44.70	44.70	25.00	33.53	Replace	0	0	Check	
One Time Key In	Main			RADIATOR ASSY	1	1,841.10	1,841.10	25.00	1,380.82	Replace	1	1,380.8	Replace	photo
One Time Key In	Main			FAN RADIATOR , RH	1	233.00	233.00	25.00	174.75	Replace	0	0	Check	
One Time Key In	Main			FAN RADIATOR , LH	1	181.80	181.80	25.00	136.35	Replace	0	0	Check	
One Time Key In	Main			FAN SHROUD RADIATOR	1	219.30	219.30	25.00	164.48	Replace	0	0	Check	
One Time Key In	Main			MOTOR, COOLING FAN , RH	1	443.40	443.40	10.00	399.06	Replace	0	0	Check	
One Time Key In	Main			MOTOR, COOLING FAN , LH	1	543.50	543.50	10.00	489.15	Replace	0	0	Check	
One Time Key In	Main			CLIP, HOSE RADIATOR , NO .2	2	3.30	16.60	25.00	12.45	Replace	0	0	Not Give	
One Time Key In	Main			HOSE, RADIATOR , NO.2	1	40.20	40.20	25.00	30.15	Replace	0	0	Check	
One Time Key In	Main			HOSE, WATER BY-PASS , NO.2	1	37.40	37.40	25.00	28.05	Replace	0	0	Check	
One Time Key In	Main			CLIP , (FOR WATER BY-PASS HOSE NO.2)	4	6.80	27.20	25.00	20.40	Replace	0	0	Not Give	
Total Spare Part Cost									36,363.15	Surveyor Total 15,012.97				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									36,363.15	Final Sur Total 15,012.97				

SMRT Recommendation												Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			PIPE, WATER BY-PASS , NO.2	1	11.00	11.00	25.00	8.25	Replace	0	0	Check	
One Time Key In	Main			CLIP, (FOR WATER BY-PASS HOSE NO.4)	1	7.50	7.50	25.00	5.63	Replace	0	0	Not Give	
One Time Key In	Main			HOSE, WATER BY-PASS , NO.4	1	13.20	13.20	25.00	9.90	Replace	0	0	Check	
One Time Key In	Main			HOSE, WATER BY-PASS , NO.1	1	37.40	37.40	25.00	28.05	Replace	0	0	Check	
One Time Key In	Main			CLIP, (FOR WATER BY-PASS HOSE NO.1)	2	7.30	14.60	25.00	10.95	Replace	0	0	Not Give	
One Time Key In	Main			INLET, AIR CLEANER, NO 3	1	35.30	35.30	25.00	26.47	Replace	0	0	Check	
One Time Key In	Main			INLET, AIR CLEANER, NO 2	1	93.90	93.90	25.00	70.43	Replace	0	0	Check	
One Time Key In	Main			INLET, AIR CLEANER, NO 1	1	130.50	130.50	25.00	97.88	Replace	0	0	Check	
One Time Key In	Main			AIR CLEANER ASSY	1	956.20	956.20	25.00	717.15	Replace	1	717.15	Replace	
One Time Key In	Main			CLAMP (FOR AIR CLEANER INLET , NO.1)	1	7.10	7.10	25.00	5.32	Replace	0	0	Not Give	
One Time Key In	Main			HOSE, AIR CLEANER , NO.1	1	62.10	62.10	25.00	46.58	Replace	0	0	Check	
One Time Key In	Main			CLAMP (FOR AIR CLEANER HOSE , NO.1)	1	7.10	7.10	25.00	5.32	Replace	0	0	Not Give	
One Time Key In	Main			CLAMP (FOR AIR CLEANER HOSE , NO.2)	1	9.00	9.00	25.00	6.75	Replace	0	0	Not Give	
One Time Key In	Main			TUBE, UNION (FOR AIR CLEANER HOSE)	1	19.40	19.40	25.00	14.55	Replace	0	0	Not Give	
One Time Key In	Main			RESONATOR, INTAKE AIR	1	14.90	14.90	25.00	11.18	Replace	0	0	Check	
One Time Key In	Main			CLAMP (FOR RESONATOR INTAKE AIR)	1	7.10	7.10	25.00	5.32	Replace	0	0	Not Give	
Total Spare Part Cost									36,363.15					
Lump Sum Discount (%)									0.00					
Final Spare Part Cost									36,363.15					
Surveyor Total												15,012.97		
Lump Sum Dis (%)												0		
Final Sur Total												15,012.97		

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace Remarks
One Time Key In	Main			BRACKET, AIR CLEANER	1	26.90	26.90	25.00	20.17	Replace	0	0	Check
One Time Key In	Main			PILLAR, FRONT BODY, RH	1	339.40	339.40	25.00	254.55	Replace	0	0	Not Give
One Time Key In	Main			PILLAR, FRONT BODY, LH	1	339.40	339.40	25.00	254.55	Replace	0	0	Not Give
Total Spare Part Cost									36,363.15	Surveyor Total 15,012.97			
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0			
Final Spare Part Cost									36,363.15	Final Sur Total 15,012.97			

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT PORTION	1,352.00	800	
Total:			1,352.00	800.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0	
3	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	100	
4	Main	TO RESPRAY FRONT FENDER LH	378.00	200	
5	Main	TO RESPRAY FRONT FENDER RH	378.00	200	
6	Main	TO RESPRAY APRON PANEL LH	180.00	0	
7	Main	TO RESPRAY APRON PANEL RH	180.00	0	
8	Main	TO REPSRAY FRONT HOOD	378.00	200	
9	Main	TO RESPRAY FRONT DOOR LH	378.00	0	
10	Main	TO RESPRAY FRT MEMBER,RH	180.00	100	
11	Main	TO RESPRAY FRT MEMBER,LH	180.00	100	
Total:			3,330.00	1,100.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
12	Main	TO RESPRAY FRONT PILLAR RH	180.00	0	
13	Main	TO RESPRAY FRONT PILLAR LH	180.00	0	
Total:			3,330.00	1,100.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	60	
2	Main	TO TOP UP A/C GAS	120.00	100	
3	Main	TO REMOVE AND REFIT WIRE HARDESS	120.00	0	
4	Main	TO REMOVE AND REFIT ENGINE WIRE ROOM	120.00	0	
5	Main	TO REPLACE SUNDRY PARTS	100.00	0	
6	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	60	
7	Main	TO WASH AND VACUUM	60.00	0	
8	Main	TOWING CHARGE	56.00	56	
9	Main	CHASSIS ALIGNMENT	350.00	200	
Total:			1,106.00	476.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	36,363.15	15,012.97
Total Labour Cost	1,352.00	800.00
Total Spray Painting	3,330.00	1,100.00
Other	1,106.00	476.00
Overall Total	42,151.15	17,388.97
Lump Sum Repair Option		
Lump Sum Total	0.00	17,388.97
Surveyor Approved Amount		17,388.97
No of Repair Days*	11	10

Estimator Assessment(\$)

Surveyor Assessment(\$)

Remarks

resurvey before paint

Surveyor Name

Rasul

Signature

Rasul

Save

Clear

Survey Date

01/04/2020

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: