

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-33/34/36 AUTOBAY SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

14-05-20

Date Of Accident : 31-03-2020

OUR REF : GBB 1637Y/T/20

MILLENIUM PARTNERS PTE LTD
280 Woodlands Industrial Park E5
#04-18
Singapore 757322

24th Cecilia

LKK - Mercedes

Date In/out: 01/04/20 to 08/04/20

Not Authorized
LKK

21/4/20

4/5 2000/
5 days.

ESTIMATE BILL ON VEH. NO. : GBB 1637Y

MODEL : TOYOTA DYNA

CHASSIS NO: JTFAT35Y803001947

LIST ITEM

Tail Lamp	2pcs @ 288.40	o/s sca	576.80	IPC
Tail Lamp Bracket	2pcs @ 181.70	o/s sca	363.40	IPC
Tail Gate Sticker 'Toyota'		rec	160.75	✓
Tail Gate Rubber Stopper	2pcs @ 45.90	o/s sca	91.80	IPC
Tail Gate Rubber Stopper Bracket	2pcs @ 151.50	o/s sca	303.00	IPC
Tail Gate Side Lock	2pcs @ 181.75	o/s sca	363.50	IPC
Tail Gate Side Lock Bracket	2pcs @ 161.10	ns	322.20	X
Rear Number Plate Lamp	2pcs @ 121.00	ns	242.00	X
Rear Number Plate Bracket		Bert	182.55	✓
Spare Tyre Carrier		o/s sca	263.10	✓
			2,869.10	
			717.28	
			2,151.83	

Less Discount 25%:

SPECIAL NETT ITEM

Reverse Sensor	shold	380.00	200
Rear Number Plate	Bert	45.00	15
70 Km/h Sticker	rec	15.00	10
13 Pax Sticker	rec	15.00	10

LABOUR CHARGE

To Check Wiring System.		80.00	20
To Tuff Coat Affected Areas.	ns	120.00	X

To Remove & Refix Spare Tyre Carrier.

11 120.00X

To Respray Affected Areas.

650.00SB0

To Renew Damaged Parts, Straighten & Repair Tail Gate, Tail Gate Lower Panel & Aligned All Parts.

700.00SB0

To Remove & Refix Reverse Sensor.

120.00SB0

GST 7% :
TOTAL AMOUNT :

4,396.83
307.78
4,704.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 1455.65
25.02
P- 1071.73
S.W 235.00
A - 1230.00
2586.73
2045.38