



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date: 1/4/2020
Vehicle: SMG6023D
Make / Model: TOYOTA PRIUS
Chassis: JTDZS3EUX0J034858

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	REAR BUMPER		\$ 610.40	\$ 610.40
2	REAR BUMPER SIDE RETAINER LH		\$ 113.60	\$ 113.60
3	REAR BUMPER SIDE RETAINER RH		\$ 113.60	\$ 113.60
4	REAR BUMPER REINFORCEMENT		\$ 310.50	\$ 310.50
5	REAR BUMPER BRACKET LH		\$ 115.30	\$ 115.30
6	REAR BUMPER BRACKET RH		\$ 115.30	\$ 115.30
7	REAR BUMPER LIP		\$ 718.50	\$ 718.50
8	REAR BUMPER REFLECTOR LH		\$ 80.60	\$ 80.60
9	REAR BUMPER REFLECTOR RH		\$ 80.60	\$ 80.60
				\$ 2,258.40
			Less 25%	\$ 564.60
			Total	\$ 1,693.80
S/Nett items:				
1	REAR REVERSE SENSOR	1 SET	\$ 250.00	\$ 250.00
2	REAR BUMPER CLIP	1 SET	\$ 80.00	\$ 80.00
3	REAR END PANEL GARNISH CLIP	1 SET	\$ 30.00	\$ 30.00
4	FLOOR PANEL SEALANT	1 SET	\$ 50.00	\$ 50.00
5	END PANEL SEALANT	1 SET	\$ 50.00	\$ 50.00
				\$ 460.00
Labour to:				
40	TO CHECK ELECTRICAL WIRING	1	\$ 50.00	\$ 50.00
41	TO REMOVE AND REFIT REVERSE SENSOR	1	\$ 150.00	\$ 150.00
43	TO RESPRAY UNDERCOATING	1	\$ 100.00	\$ 100.00
44	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 120.00	\$ 120.00
45	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 600.00	\$ 600.00
46	PANEL BEATING ON AFFECTED AREAS	1	\$ 600.00	\$ 600.00
				\$ 1,620.00
			Parts Replacement Amount	\$ 2,153.80
			Total Amount for Labour	\$ 1,620.00
			Total Amount	\$ 3,773.80

CUT ✓ 523.90
NECV ✓ 98.00
DDV ✓ 98.00

NDX
NDX

NDX

1030.40
257.60
772.80

SC ✓
NECV ✓

NNX

230.00

✓
✓
✓
✓
✓

570.00

1592.80
318.56

1274.24

TG Lim
15/5/2020