

TRANS EUROKARS PTE LTD

(4) EUROKARS GROUP

ESTIMATE COST OF REPAIRS

INDIA INTERNATIONAL INSURANCE P/L 25032 NAME: Ms Tang Jing Jing 64 CECIL STREET ADDRESS: No, 27A Jalan Chengkek #04-#05 IOB BUILDING 23-Mar-20 Singapore 369249 SINGAPORE 049711 ATTN.: MOTOR CLAIMS TEL: 98211047 FAX: VEH NO: DATE IN: SJJ1121G Ronald 63957875 **CONTACT PERSON: CHASSIS NO:** JM6GL1031H0124169 MILEAGE: TYPE OF CLAIM: THIRD PARTY CLAIM MODEL: MAZDA6 **DATE REG.: POLICY NO.:** 29-Sep-17 **NATURE OF WORKS** Parts Description **REVISED PRICES** NO QTY FRONT BUMPER Cun 1 MGMV8-50-031CBB 1,211.90 RETAINER RHS 11 \$ 2 17.10 1 MGHP9-50-0T1B \$ CHROME RHS, FOGLAMP 101.90 3 11 1 MG46L-50-C12 CLIP, FRONT BUMPER 6 \$ 22.20 4 121 MC274-50-133 NU \$ FASTENER, FRONT BUMPER 2 MB45A-56-146A 6.00 ru. 2 MGHP9-50-0Z5 \$ 5.80 GROMMET, FRONT BUMPER 6 6 MGD7A-50-EA1 \$ 19.20 7 FASTENER, FRONT BUMPER nu \$ 6 8 RIVET, FRONT BUMPER MGHP9-50-355 29.40 NU RIVET, FRONT BUMPER ALL 8 MS51S-51-833 \$ 32.00 9 1 M9965-20-7590 FRONT WHEEL RIM RHS \$ 1,497,80 10 **TOTAL PARTS** \$ 2,943.30 **TOTAL PARTS COST** 2,943.30 **Labour Description** TO REPLACE FRONT BUMPER. TO REPAIR FRONT FENDER RH AND ALL AREAS AFFECTED \$ 1,320.00 1 MZ-BR-FRONT1 BY THE ACCIDENT. MZ-SP-SFRT07 TO RESPRAY FRONT BUMPER AND FRONT FENDER RH. \$ 1,260.00 2 TO TRANSFER FRONT PEDESTRIAN SENSORS. NETT \$ 330.00 3 MZ-BR-FRTSEN TO SUPPLY 1 PC TIRE. \$ 480.00 4 MZ-BR-WHEBAL TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING. \$ NETT 120.00 5

6	MZ-BR-WHEALI	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEE	L ALIGNMENT.	NETT	\$	560.00
7	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	11×	1 2 3 3	\$	250.00
8	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONII	NG. /20	 1	\$	250.00
9	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	150		\$	350.00
10	MZ-BR-SUNDRI	SUNDRIES.	nu 20	NETT	\$	100.00
			TOTAL LABOUR	\$ -	\$	5,020.00
			TOTAL PARTS	\$	\$	2,943.30
			TOTAL	\$ -	\$	7,963.30
			LESS EXCESS	\$ ·	\$	·
			TOTAL AFTER EXCESS	\$ -	7.	A STATE OF THE PARTY.
			GST 7%	\$	\$	
		· · · · · · · · · · · · · · · · · · ·	GRAND TOTAL	\$ _	Ś	7,0

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: