



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre

Hilton Auto Trading

Dealing in New/Used Cars, Hire Purchase & Insurance.



(SUPPLEMENTARY)

INSURER: **Lonpac Insurance Bhd (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	Z/19/VC00/105187	Date of Loss:	27/03/2020
Vehicle Reg. No.:	XD7979A	Driveable?	
Driver Age/Info:	36 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	FONG SHENG LOGISTIC PTE LTD		
Driver:	RAMASAMY VIDUTHALAIPULI		
Make/Model:	MITSUBISHI FUSO, 12.0 D FV51SJD2DEA (M)	Vehicle Reg. Date:	23/10/2014
Vehicle Colour:	GREEN		
Engine No:	OM457LA457972C0284755	Chassis No:	FV51SJA10033
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	20		
Description of Accident/Loss	PLEASE REFER TO STATEMENT ON THE SKETCH PLAN.		
Remarks:	SUPPLEMENTARY ITEMS : 1. FRONT UNDERCARRIAGE LIFT SPRING SUSPENSION ASSY X 2 SETS : \$1800 X 2 (S.N.) 2. LIFT SPRING U BOLT 11" X 4 PCS : \$100 X 4 (S.N) 3. FRONT TIE ROD ASSY : \$800 4. DPF MUFFLER ASSY : \$11,500 5. FRONT TIE ROD END LH : \$450 LABOUR : 1. TO REMOVE & RENEW FRONT BOTH UNDERCARRIAGE DAMAGED PARTS : \$600 2. TO CHECK ALL WHEELS ALIGNMENT : \$200		
Present Location:	MOVA AUTOMOTIVE PTE LTD (FAN YOONG)		

COST OF CLAIMS	Amount
Parts	18,662.50
Miscellaneous Items	0.00
Labour	800.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	19,462.50
+ GST 7.00% (\$\$)	1,362.38
Nett Amount (\$\$)	20,824.88
+ Previous Estimates (\$\$)	42,242.10
Claim Total (\$\$)	63,066.98

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: (Last Synchronised: 22 Apr 2020)

Parts: N/A MITSUBISHI FUSO 12.0 D FV51SJD2DEA (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for XD7979A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	2		*FRONT UNDERCARRIAGE LIFT SPRING SUSPENSION ASSY (SET) <i>bt ✓</i>	0	0.00	*3,600.00 FS
2	4		*LIFT SPRING U BOLT 11 <i>new ✓</i>	0	0.00	*400.00 FS } F
3	1		*FRONT TIE ROD ASSY <i>bt ✓</i>	0.00	0.00	*800.00 F
4	1		*DPF MUFFLER ASSY <i>bt ✓</i>	0.00	0.00	*11,500.00 F
5	1		*FRONT TIE ROD END LH <i>can ✓</i>	0.00	0.00	*450.00 F
						<i>bt ✓</i>
Sub Total (\$\$)						16,750.00
+ Margin on L,N Items 15.00% (\$\$)						1,912.50
Total Parts (\$\$)						18,662.50

F=Franchise part S=SpcNett

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Supplementary Peng

1) Gearbox u support bracket

*X2 = \$1300 x 2 = \$2600 *bt ✓**

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REMOVE & RENEW FRONT BOTH UNDERCARRIAGE DAMAGED PARTS	New	600.00 ⁴⁰⁰
2	TO CHECK ALL WHEELS ALIGNMENT	New	200.00 ¹⁵⁰
Gross Labour Cost (S\$)			800.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LC-550

P-99,424
+ P-19,350-supply

P-39,774
- 150

P-H 51,740.10
SH-830
LC-H330
+ LC-550-supply

51,450.10
- 206168

41,160



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/05/08/116, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088964-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading

Dealing In New/Used Cars, Hire Purchase & Insurance.



(SUPPLEMENTARY)

INSURER: Lonpac Insurance Bhd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	Z/19/VC00/105187	Date of Loss:	27/03/2020
Vehicle Reg. No.:	XD7979A	Driveable?	
Driver Age/Info:	36 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	FONG SHENG LOGISTIC PTE LTD		
Driver:	RAMASAMY VIDUTHALAIPULI		
Make/Model:	MITSUBISHI FUSO, 12.0 D FV51SJD2DEA (M)	Vehicle Reg. Date:	23/10/2014
Vehicle Colour:	GREEN	Chassis No:	FV51SJA10033
Engine No:	OM457LA457972C0284755		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	20		
Description of Accident/Loss	PLEASE REFER TO STATEMENT ON THE SKETCH PLAN.		
Present Location:	MOVA AUTOMOTIVE PTE LTD (FAN YOONG)		

COST OF CLAIMS

	Amount
Parts	2,990.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	2,990.00
+ GST 7.00% (\$\$)	209.30
Nett Amount (\$\$)	3,199.30
+ Previous Estimates (\$\$)	63,066.98
Claim Total (\$\$)	66,266.28

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 15 May 2020)**Parts:** N/A MITSUBISHI FUSO 12.0 D FV51SJD2DEA (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Movia Automotive Pte Ltd/XD7979A/15/05/2020 14:40**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	2		*GEARBOX U SUPPORT BRACKET cra	0.00	0.00	*2,600.00 F
						Sub Total (\$\$)
						2,600.00
						+ Margin on L,N Items 15.00% (\$\$)
						390.00
						Total Parts (\$\$)
						2,990.00

F=Franchise part.

Movia Automotive Pte Ltd/XD7979A/15/05/2020 14:40. Not valid without Reference section.
Generated using Merimen e-Claims IEAS



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088664-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre

Hilton Auto Trading

Dealing In New/Used Cars, Hire Purchase & Insurance.



INSURER:

Lonpac Insurance Bhd (HQ)

Alan 96869276

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	Z/19/VC00/105187	Date of Loss:	27/03/2020
Vehicle Reg. No.:	XD7979A	Driveable?	
Driver Age/Info:	36 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	FONG SHENG LOGISTIC PTE LTD		
Driver:	RAMASAMY VIDUTHALAIPULI		
Make/Model:	MITSUBISHI FUSO, 12.0 D FV51SJD2DEA (M)	Vehicle Reg. Date:	23/10/2014
Vehicle Colour:	GREEN		
Engine No:	OM457LA457972C0284755	Chassis No:	FV51SJA10033
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	20		
Description of Accident/Loss	PLEASE REFER TO STATEMENT ON THE SKETCH PLAN.		
Present Location:	MOVA AUTOMOTIVE PTE LTD (FAN YOONG)		

COST OF CLAIMS	Amount
Parts	34,678.60
Miscellaneous Items	0.00
Labour	4,800.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	39,478.60
+ GST 7.00% (\$)	2,763.50
Nett Amount (\$)	42,242.10

This claim is handled by: ALAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 02 Apr 2020)

Parts: N/A MITSUBISHI FUSO 12.0 D FV51SJD2DEA (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for XD7979A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT WINDSCREEN GLASS <i>bro</i>	0.00	0.00	*1,500.00 F
2	1		*FRONT WINDSCREEN MOULDING <i>rec</i>	0.00	0.00	*350.00 F
3	2 pcs		*WIPER ARM <i>bt</i>	0.00	0.00	*750.00 F 500
4	1		*WIPER LINKAGE ASSY <i>X SVC</i>	0.00	0.00	*850.00 F
5	1		*WIPER PANEL <i>bt repair</i>	0.00	0.00	*480.00 F
6	1		*FRONT PANEL <i>bt</i>	0.00	0.00	*2,800.00 F
7	2		*FRONT PANEL HINGE <i>X SVC</i>	0.00	0.00	*140.00 F
8	1		*FRONT PANEL (FUSO) EMBLEM <i>rec</i>	0.00	0.00	*180.00 F
9	2		*FRONT PANEL GRILLE <i>SCB</i> <i>X SVC</i>	0.00	0.00	*1,200.00 F
10	1		*FRONT BUMPER TOP <i>bro</i>	0.00	0.00	*250.00 F
11	1		*FRONT BUMPER LOWER <i>bt</i>	0.00	0.00	*1,300.00 F
12	2 ipl		*FRONT BUMPER LH & RH <i>LH-bro/RH-X SVC</i>	0.00	0.00	*300.00 F <i>150</i>
13	2 ipl		*FRONT BUMPER COVER LH & RH <i>LH-bro/RH-X SVC</i>	0.00	0.00	*300.00 F <i>150</i>
14	1		*FRONT BUMPER CENTER BRACKET <i>X SVC</i>	0.00	0.00	*1,050.00 F
15	2 ipl		*FRONT BUMPER LH & RH BRACKET <i>LH-bt/RH-X SVC</i>	0.00	0.00	*600.00 F 300
16	1		*HEADLAMP LH <i>bro</i>	0.00	0.00	*800.00 F
17	1		*SMALL LAMP LH <i>bro</i>	0.00	0.00	*300.00 F
18	1		*SIGNAL LAMP LH <i>bro</i>	0.00	0.00	*160.00 F
19	1		*FRONT CORNER PANEL LH <i>cm</i>	0.00	0.00	*550.00 F
20	1		*FRONT CORNER PANEL BRACKET LH <i>X SVC</i>	0.00	0.00	*140.00 F
21	1		*FRONT SIDE MIRROR BRACKET LH <i>bt</i>	0.00	0.00	*1,100.00 F
22	2 ipl		*FRONT SIDE MIRROR BRACKET SUPPORT <i>bt</i>	0.00	0.00	*600.00 F 300
23	2		*FRONT SIDE MIRROR <i>cm</i>	0.00	0.00	*360.00 F
24	1		*FRONT SIDE ROUND MIRROR LH <i>cm</i>	0.00	0.00	*110.00 F
25	1		*FRONT WHEEL ARCH LH <i>de</i>	0.00	0.00	*210.00 F
26	1		*FRONT WHEEL ARCH BLADE GARNISH LH <i>bro</i>	0.00	0.00	*950.00 F
27	1		*FRONT STEP PANEL LH <i>bro</i>	0.00	0.00	*750.00 F
28	1		*FRONT STEP PANEL BOTTOM LH <i>bro</i>	0.00	0.00	*600.00 F
29	3		*FRONT STEP PLATE <i>bro</i>	0.00	0.00	*714.00 F
30	1		*FRONT STEP SUPPORT BAR LH <i>bt</i>	0.00	0.00	*780.00 F
31	1		*CONDENSER <i>bt</i>	0.00	0.00	*1,340.00 F
32	1		*CONDENSER BRACKET <i>bt</i>	0.00	0.00	*580.00 F
33	2		*CONDENSER AIR CON PIPE <i>bt</i>	0.00	0.00	*400.00 F
34	1		*CONDENSER FAN MOTOR <i>bt</i>	0.00	0.00	*900.00 F
35	1		*CONDENSER FAN BLADE <i>bro</i>	0.00	0.00	*220.00 F
36	1		*CONDENSER FAN COWLING <i>bro</i>	0.00	0.00	*190.00 F
37	1		*LH FRONT DOOR PILLAR <i>repair</i>	0.00	0.00	*2,800.00 F R x
38	1		*FRONT BUMPER CENTER STEP GARNISH <i>bro</i>	0.00	0.00	*160.00 F
39	1		*DASHBOARD TOP <i>cm</i>	0.00	0.00	*2,500.00 F
40	1		*TOWING TO FAN YOONG	0	0.00	*350.00 FS 300
41	1		*LH FRONT TYRE <i>punctured</i>	0	0.00	*600.00 FS 702
42	1		*FRONT NUMBER PLATE <i>SI</i>	0	0.00	*50.00 FS 35
43	1		*FRONT IU BRACKET <i>cm</i>	0	0.00	*25.00 FS
F=Franchise part, S=Spec Net						
3) DPF Muffler <i>any</i> \$11,500						Sub Total (\$\$)
4) front tie rod end LH \$450						+ Margin on L,N Items 15.00% (\$\$)
						Total Parts (\$\$)

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Supplementary parts.

1) front undercamber lift spring SIN
 Suspension *any* x 2 sets \$1800 x 2 = \$3600

2) lift spring U Bolt 11" x 4 pcs \$100 x 4 = \$400

3) front tie rod *any* \$800

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO INSPECT FRONT LIGHTING WATER & LEAKAGE TEST	New	40.00
2	TO REMOVE & INSTALL FRONT WINDSCREEN	New	160.00
3	TO REMOVE & INSTALL DASHBOARD	New	300.00
4	TO REMOVE & INSTALL CARPET, GARNISH, SEAT & ETC IN ORDER TO CUT OFF LH FRONT DOOR PILLAR & STRAIGHTEN AFFECTED AREAS	New	400.00
5	TO CUT OFF WIPER PANEL, LH FRONT DOOR PILLAR, STRAIGHTEN AFFECTED AREAS AND RENEW DAMAGED PARTS	New	1500 2,400.00
6	TO SPRAY PAINT ON REPLACED, REPAIRED AREAS	New	1,500.00
Gross Labour Cost (S\$)			4,800.00

Report was unsubmitted during this print-out.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Supplementary labours
To remove & replace front
both undercarriage, damages
panels = \$ 600

To check all wheels
alignment = \$ 200

Rasul
Hp 90010068
8 days
HS

EXCESS: 2000

REVERT

02/04/2020 @ 1635

Resurvey after repair

P- 29424
SIN-830
LC-4330

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Mova Automotive Pte Ltd/XD7979A/15/05/2020 14:40. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >