

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Apr 2020 Edit Reg		02 Apr 2020 00:00 Edit Adj Rpt	S\$17,800.00 Edit Estimates	S\$17,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: CHEONG HUI TING ELIZABETH (ZHANG HUITING) , Co. Reg. No.: *									
Main Claimant: BIS MOTORING PTE LTD , Co. Reg. No.: 201735055D									
Vehicle Reg. No.: SMJ1849E		Date of Loss: 02/04/2020 09:00 - :59 [13 Months and 8 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 6908709626SG		Policy/Cover Note No.: 1800086489 (Comprehensive)							
Vehicle Reg. No. (Insured): SME130C		Policy No. (Claimant): M0015130							
		Excess:							
Repairer: Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6, 539365 Defu Lane - Tel: 6858 5151									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com									
Claimant's Insurer: Etiqa Insurance Pte Ltd (HQ) - Tel: 63360477									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 14/04/2020]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (12/08/2020): Alert - Adj Mandate Approved (S\$19048.00) - SMJ1849E - Claim Handler: MdNoor, No... - AIG_SG (03/04/2020): Request to upload TP GIA Report - AIG_SG (03/04/2020): No OI GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMJ1849E (6908709626SG)**
[SME130C]

TP

BIS MOTORING PTE LTD

Apr 2 2020 9:00AM

[CHEONG HUI TING ELIZABETH (ZHANG HUITING)]

Tan Lim Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video															1 per page			☒		
No	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)													Thumbnail		Print		
1	15/04/20 15:40		Video - Accident													Load MP4				
Letters/Correspondences															1 per page			☒		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print		
1	(Draft)		Third Party Express Settlement – Payment Breakdown													Edit				
Photos/Images															3 per page			☒		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print		
1	02/04/20 18:49		Chassis Number													Load JPG		☒		
2	02/04/20 18:50		Odometer Reading													Load JPG		☒		
3	02/04/20 18:53		General View													Load JPG		☒		
4	02/04/20 18:53		General View													Load JPG		☒		
5	02/04/20 18:53		General View													Load JPG		☒		
6	02/04/20 18:53		General View													Load JPG		☒		
7	02/04/20 18:53		General View													Load JPG		☒		
8	02/04/20 18:53		General View													Load JPG		☒		
9	02/04/20 18:53		General View													Load JPG		☒		
10	02/04/20 18:53		General View													Load JPG		☒		
11	02/04/20 18:53		General View													Load JPG		☒		
12	02/04/20 18:53		General View													Load JPG		☒		
13	02/04/20 18:53		General View													Load JPG		☒		
14	02/04/20 18:53		General View													Load JPG		☒		
15	02/04/20 18:53		General View													Load JPG		☒		
16	02/04/20 18:53		General View													Load JPG		☒		
17	02/04/20 18:53		General View													Load JPG		☒		
18	02/04/20 18:53		General View													Load JPG		☒		
19	02/04/20 18:53		General View													Load JPG		☒		
20	02/04/20 18:53		General View													Load JPG		☒		
21	02/04/20 18:53		General View													Load JPG		☒		
22	02/04/20 18:53		General View													Load JPG		☒		
23	02/04/20 18:53		General View													Load JPG		☒		
24	02/04/20 18:53		General View													Load JPG		☒		
25	02/04/20 18:53		General View													Load JPG		☒		
26	02/04/20 18:53		General View													Load JPG		☒		
27	02/04/20 18:53		General View													Load JPG		☒		
28	02/04/20 18:53		General View													Load JPG		☒		
29	02/04/20 18:53		General View													Load JPG		☒		
30	02/04/20 18:53		General View													Load JPG		☒		
31	02/04/20 18:53		General View													Load JPG		☒		
32	02/04/20 18:53		General View													Load JPG		☒		
33	02/04/20 18:53		General View													Load JPG		☒		
34	02/04/20 18:53		General View													Load JPG		☒		

Video				1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
35	02/04/20 18:53	General View		Load JPG	☒
36	02/04/20 18:53	General View		Load JPG	☒
37	02/04/20 18:53	General View		Load JPG	☒
38	02/04/20 18:53	General View		Load JPG	☒
39	02/04/20 18:53	General View		Load JPG	☒
40	02/04/20 18:53	General View		Load JPG	☒
41	02/04/20 18:53	General View		Load JPG	☒
42	02/04/20 18:53	General View		Load JPG	☒
43	02/04/20 18:53	General View		Load JPG	☒
44	02/04/20 18:53	General View		Load JPG	☒
45	02/04/20 18:53	General View		Load JPG	☒
46	02/04/20 18:53	General View		Load JPG	☒
47	02/04/20 18:53	General View		Load JPG	☒
48	02/04/20 18:53	General View		Load JPG	☒
49	02/04/20 18:53	General View		Load JPG	☒
50	02/04/20 18:53	General View		Load JPG	☒
51	02/04/20 18:53	General View		Load JPG	☒
52	02/04/20 18:53	General View		Load JPG	☒
53	02/04/20 18:53	General View		Load JPG	☒
54	02/04/20 18:53	General View		Load JPG	☒
55	02/04/20 18:53	General View		Load JPG	☒
56	02/04/20 18:53	General View		Load JPG	☒
57	02/04/20 18:53	General View		Load JPG	☒
58	02/04/20 18:53	General View		Load JPG	☒
59	02/04/20 18:53	General View		Load JPG	☒
60	02/04/20 18:53	General View		Load JPG	☒
61	02/04/20 18:53	General View		Load JPG	☒
62	02/04/20 18:53	General View		Load JPG	☒
63	02/04/20 18:53	General View		Load JPG	☒
64	02/04/20 18:53	General View		Load JPG	☒
65	02/04/20 18:53	General View		Load JPG	☒
66	02/04/20 18:53	General View		Load JPG	☒
67	02/04/20 18:53	General View		Load JPG	☒
68	02/04/20 18:53	General View		Load JPG	☒
69	02/04/20 18:54	General View		Load JPG	☒
70	02/04/20 18:54	General View		Load JPG	☒
71	02/04/20 18:54	General View		Load JPG	☒
72	02/04/20 18:54	General View		Load JPG	☒
73	02/04/20 18:54	General View		Load JPG	☒
74	02/04/20 18:54	General View		Load JPG	☒
75	02/04/20 18:54	General View		Load JPG	☒
76	02/04/20 18:54	General View		Load JPG	☒
77	02/04/20 18:54	General View		Load JPG	☒
78	02/04/20 18:54	General View		Load JPG	☒
79	02/04/20 18:54	General View		Load JPG	☒
80	02/04/20 18:54	General View		Load JPG	☒
81	02/04/20 18:54	General View		Load JPG	☒
82	02/04/20 18:54	General View		Load JPG	☒
83	02/04/20 18:54	General View		Load JPG	☒
84	02/04/20 18:54	General View		Load JPG	☒
85	02/04/20 18:54	General View		Load JPG	☒
86	02/04/20 18:54	General View		Load JPG	☒
87	02/04/20 18:54	General View		Load JPG	☒

Video				1 per page ▾	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
88	02/04/20 18:54	General View		Load JPG	☒
89	02/04/20 18:54	General View		Load JPG	☒
90	02/04/20 18:54	General View		Load JPG	☒
91	02/04/20 18:54	General View		Load JPG	☒
92	02/04/20 18:54	General View		Load JPG	☒
93	02/04/20 18:54	General View		Load JPG	☒
94	02/04/20 18:54	General View		Load JPG	☒
95	02/04/20 18:54	General View		Load JPG	☒
96	02/04/20 18:54	General View		Load JPG	☒
97	02/04/20 18:54	General View		Load JPG	☒
98	02/04/20 18:54	General View		Load JPG	☒
99	02/04/20 18:54	General View		Load JPG	☒
100	02/04/20 18:54	General View		Load JPG	☒
101	02/04/20 18:54	General View		Load JPG	☒
102	02/04/20 18:58	Reinspection Photo		Load JPG	☒
103	02/04/20 18:58	Reinspection Photo		Load JPG	☒
104	02/04/20 18:58	Reinspection Photo		Load JPG	☒
105	02/04/20 18:58	Reinspection Photo		Load JPG	☒
106	02/04/20 18:58	Reinspection Photo		Load JPG	☒
107	02/04/20 18:58	Reinspection Photo		Load JPG	☒
108	02/04/20 18:58	Reinspection Photo		Load JPG	☒
109	02/04/20 18:58	Reinspection Photo		Load JPG	☒
110	02/04/20 18:58	Reinspection Photo		Load JPG	☒
111	02/04/20 18:58	Reinspection Photo		Load JPG	☒
112	02/04/20 18:58	Reinspection Photo		Load JPG	☒
113	02/04/20 18:58	Reinspection Photo		Load JPG	☒
114	02/04/20 18:58	Reinspection Photo		Load JPG	☒
115	02/04/20 18:58	Reinspection Photo		Load JPG	☒
116	02/04/20 18:58	Reinspection Photo		Load JPG	☒
117	02/04/20 18:58	Reinspection Photo		Load JPG	☒
118	02/04/20 18:58	Reinspection Photo		Load JPG	☒
119	02/04/20 18:58	Reinspection Photo		Load JPG	☒
120	02/04/20 18:58	Reinspection Photo		Load JPG	☒
121	02/04/20 18:58	Reinspection Photo		Load JPG	☒
122	02/04/20 18:58	Reinspection Photo		Load JPG	☒
123	02/04/20 18:58	Reinspection Photo		Load JPG	☒
124	02/04/20 18:58	Reinspection Photo		Load JPG	☒
125	02/04/20 18:58	Reinspection Photo		Load JPG	☒
126	02/04/20 18:58	Reinspection Photo		Load JPG	☒
127	02/04/20 18:58	Reinspection Photo		Load JPG	☒
128	02/04/20 18:58	Reinspection Photo		Load JPG	☒
129	02/04/20 18:58	Reinspection Photo		Load JPG	☒
130	02/04/20 18:58	Reinspection Photo		Load JPG	☒
131	02/04/20 18:58	Reinspection Photo		Load JPG	☒
132	02/04/20 18:58	Reinspection Photo		Load JPG	☒
133	02/04/20 18:58	Reinspection Photo		Load JPG	☒
134	02/04/20 18:58	Reinspection Photo		Load JPG	☒
135	02/04/20 18:58	Reinspection Photo		Load JPG	☒
136	02/04/20 18:58	Reinspection Photo		Load JPG	☒
137	02/04/20 18:58	Reinspection Photo		Load JPG	☒
138	02/04/20 18:58	Reinspection Photo		Load JPG	☒
139	02/04/20 18:58	Reinspection Photo		Load JPG	☒
140	02/04/20 18:58	Reinspection Photo		Load JPG	☒

Video				1 per page ▾	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
141	02/04/20 18:58	Reinspection Photo		Load JPG	☒
142	02/04/20 18:58	Reinspection Photo		Load JPG	☒
143	02/04/20 18:58	Reinspection Photo		Load JPG	☒
144	02/04/20 18:58	Reinspection Photo		Load JPG	☒
145	02/04/20 18:58	Reinspection Photo		Load JPG	☒
146	02/04/20 18:58	Reinspection Photo		Load JPG	☒
147	02/04/20 18:58	Reinspection Photo		Load JPG	☒
148	02/04/20 18:58	Reinspection Photo		Load JPG	☒
149	02/04/20 18:58	Reinspection Photo		Load JPG	☒
150	02/04/20 18:58	Reinspection Photo		Load JPG	☒
151	02/04/20 18:58	Reinspection Photo		Load JPG	☒
152	02/04/20 18:58	Reinspection Photo		Load JPG	☒
153	02/04/20 18:58	Reinspection Photo		Load JPG	☒
154	02/04/20 18:58	Reinspection Photo		Load JPG	☒
155	02/04/20 18:58	Reinspection Photo		Load JPG	☒
156	02/04/20 18:58	Reinspection Photo		Load JPG	☒
157	02/04/20 18:58	Reinspection Photo		Load JPG	☒
158	02/04/20 18:58	Reinspection Photo		Load JPG	☒
159	02/04/20 18:58	Reinspection Photo		Load JPG	☒
160	02/04/20 18:58	Reinspection Photo		Load JPG	☒
161	02/04/20 18:58	Reinspection Photo		Load JPG	☒
162	02/04/20 18:58	Reinspection Photo		Load JPG	☒
163	02/04/20 18:58	Reinspection Photo		Load JPG	☒
164	02/04/20 18:58	Reinspection Photo		Load JPG	☒
165	02/04/20 18:58	Reinspection Photo		Load JPG	☒
166	02/04/20 18:58	Reinspection Photo		Load JPG	☒
167	02/04/20 18:58	Reinspection Photo		Load JPG	☒
168	02/04/20 18:58	Reinspection Photo		Load JPG	☒
169	02/04/20 18:58	Reinspection Photo		Load JPG	☒
170	02/04/20 18:58	Reinspection Photo		Load JPG	☒
171	02/04/20 18:58	Reinspection Photo		Load JPG	☒
172	02/04/20 18:58	Reinspection Photo		Load JPG	☒
173	02/04/20 18:58	Reinspection Photo		Load JPG	☒
174	02/04/20 18:58	Reinspection Photo		Load JPG	☒
175	02/04/20 18:58	Reinspection Photo		Load JPG	☒
176	02/04/20 18:58	Reinspection Photo		Load JPG	☒
177	02/04/20 18:58	Reinspection Photo		Load JPG	☒
178	02/04/20 18:58	Reinspection Photo		Load JPG	☒
179	02/04/20 18:58	Reinspection Photo		Load JPG	☒
180	02/04/20 18:58	Reinspection Photo		Load JPG	☒
181	02/04/20 18:58	Reinspection Photo		Load JPG	☒
182	02/04/20 18:58	Reinspection Photo		Load JPG	☒
183	02/04/20 18:58	Reinspection Photo		Load JPG	☒
184	02/04/20 18:58	Reinspection Photo		Load JPG	☒
185	02/04/20 18:58	Reinspection Photo		Load JPG	☒
186	02/04/20 18:58	Reinspection Photo		Load JPG	☒
187	02/04/20 18:58	Reinspection Photo		Load JPG	☒
188	02/04/20 18:58	Reinspection Photo		Load JPG	☒
189	02/04/20 18:58	Reinspection Photo		Load JPG	☒
190	02/04/20 18:58	Reinspection Photo		Load JPG	☒
191	02/04/20 18:58	Reinspection Photo		Load JPG	☒
192	02/04/20 18:58	Reinspection Photo		Load JPG	☒
193	02/04/20 18:58	Reinspection Photo		Load JPG	☒

Video				1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
194	02/04/20 18:58	Reinspection Photo		Load JPG	☒
195	02/04/20 18:58	Reinspection Photo		Load JPG	☒
196	02/04/20 18:58	Reinspection Photo		Load JPG	☒
197	02/04/20 18:58	Reinspection Photo		Load JPG	☒
198	02/04/20 18:58	Reinspection Photo		Load JPG	☒
199	02/04/20 18:58	Reinspection Photo		Load JPG	☒
200	02/04/20 18:58	Reinspection Photo		Load JPG	☒
201	02/04/20 18:58	Reinspection Photo		Load JPG	☒
202	02/04/20 18:58	Reinspection Photo		Load JPG	☒
203	02/04/20 18:58	Reinspection Photo		Load JPG	☒
204	02/04/20 18:58	Reinspection Photo		Load JPG	☒
205	02/04/20 18:58	Reinspection Photo		Load JPG	☒
206	02/04/20 18:58	Reinspection Photo		Load JPG	☒
207	02/04/20 18:58	Reinspection Photo		Load JPG	☒
208	02/04/20 18:58	Reinspection Photo		Load JPG	☒
209	02/04/20 18:58	Reinspection Photo		Load JPG	☒
210	02/04/20 18:58	Reinspection Photo		Load JPG	☒
211	02/04/20 18:58	Reinspection Photo		Load JPG	☒
212	02/04/20 18:58	Reinspection Photo		Load JPG	☒
213	17/04/20 18:16	Reinspection Photo		Load JPG	☒
214	17/04/20 18:16	Reinspection Photo		Load JPG	☒
215	17/04/20 18:16	Reinspection Photo		Load JPG	☒
216	17/04/20 18:16	Reinspection Photo		Load JPG	☒
217	17/04/20 18:16	Reinspection Photo		Load JPG	☒
218	17/04/20 18:16	Reinspection Photo		Load JPG	☒
219	17/04/20 18:16	Reinspection Photo		Load JPG	☒
220	27/04/20 14:57	After Repair Photo		Load JPG	☒
221	27/04/20 14:57	After Repair Photo		Load JPG	☒
222	27/04/20 14:57	After Repair Photo		Load JPG	☒
223	27/04/20 14:57	After Repair Photo		Load JPG	☒
224	27/04/20 14:57	After Repair Photo		Load JPG	☒
225	27/04/20 14:57	After Repair Photo		Load JPG	☒
226	27/04/20 14:57	After Repair Photo		Load JPG	☒
227	27/04/20 14:57	After Repair Photo		Load JPG	☒
228	27/04/20 14:57	After Repair Photo		Load JPG	☒
229	27/04/20 14:57	After Repair Photo		Load JPG	☒
230	27/04/20 14:57	After Repair Photo		Load JPG	☒
231	27/04/20 14:57	After Repair Photo		Load JPG	☒
232	27/04/20 14:57	After Repair Photo		Load JPG	☒
233	27/04/20 14:57	After Repair Photo		Load JPG	☒
234	27/04/20 14:57	After Repair Photo		Load JPG	☒
235	27/04/20 14:57	After Repair Photo		Load JPG	☒
236	27/04/20 14:57	After Repair Photo		Load JPG	☒
237	27/04/20 14:57	After Repair Photo		Load JPG	☒
238	27/04/20 14:57	After Repair Photo		Load JPG	☒
239	27/04/20 14:57	After Repair Photo		Load JPG	☒
240	27/04/20 14:57	After Repair Photo		Load JPG	☒
241	27/04/20 14:57	After Repair Photo		Load JPG	☒
242	27/04/20 14:57	After Repair Photo		Load JPG	☒
243	27/04/20 14:57	After Repair Photo		Load JPG	☒
244	27/04/20 14:57	After Repair Photo		Load JPG	☒
245	27/04/20 14:57	After Repair Photo		Load JPG	☒
246	27/04/20 14:57	After Repair Photo		Load JPG	☒

Video			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
247	27/04/20 14:57	After Repair Photo	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/04/20 11:39	TP GIA REPORT	Load PDF	
2	03/04/20 17:56	NON-REPORTING LETTER	Load PDF	
3	11/05/20 16:02	TP ESTIMATE - MARKED	Load PDF	
4	27/05/20 11:27	LETTER TO OI	Load PDF	
5	24/06/20 15:18	GIA SEARCH	Load PDF	
6	24/06/20 15:18	LOD	Load PDF	
7	21/08/20 10:56	Authorisation to Act	Load PDF	
8	21/08/20 10:56	Release Voucher	Load PDF	
9	21/08/20 10:56	WORKSHOP INVOICE	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	15/04/20 15:39	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SME130C (Insd veh)	Model:	OPEL INSIGNIA GRANDSPORT
	SMJ1849E (TP veh)		B16DTH 1.6 TURBO (A)
Date of Accident:	02/04/2020		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	:\$	32,149.61	
Final Repair Cost	:\$	19,046.00	
Loss of Use	:\$	days at \$0.00 per day	
Rental (if any)	:\$	days	
LTA / GIA Search Fee	:\$	2.00	
Others:	:\$		
	:\$		
Final Settlement Sum	:\$	19,048.00	
Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ 100 _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Tan Lim Motor Pte Ltd	:\$	19,048.00
2)		:\$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

21 Aug
2020

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG20004834/UEA3S2**Date:** 21/08/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800086489
Claimant Vehicle No :	SMJ1849E	Insured Vehicle No :	SME130C
Date of Loss:	02/04/2020	Nature of Claim:	TP
		Claim No:	6908709626SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ1849E		
Make & Model:	OPEL INSIGNIA GRANDSPORT B16DTH, 1.6 Turbo (A)	Engine No:	A3183138JSUX0141
Reg. Date:	25/02/2019 (Man. Year: 2019)	Chassis No:	W0VZM6EF2K1034214
Colour:	White	Odometer:	40593 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,906.36	19,012.74	5,893.62	23.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,140.00	3,250.00	1,890.00	36.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,046.36	22,262.74	7,783.62	25.91
Approved Total (Overridden) (S\$)		17,800.00		
(S\$)	30,046.36	17,800.00	12,246.36	40.76
+ GST 7.00/7.00% (S\$)	2,103.25	1,246.00	857.25	40.76
Nett Amount (S\$)	32,149.61	19,046.00	13,103.61	40.76
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		19,048.00		

INSPECTION

Date of Assignment:	02/04/2020	
Date Inspected:	02/04/2020	Inspected At: Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	18.0 days	

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,327.20 FL	*1,327.20 FL
2	10		*REAR BUMPER CLIPS	Necessary	45.00 FL	*45.00 FL
3	1		*REAR BUMPER LOWER	Distorted	309.60 FL	*309.60 FL
4	2		*REAR BUMPER REFLECTORS	Cracked	57.60 FL	*57.60 FL
5	2		*REAR BUMPER RETAINER	Not Necessary	163.20 FL	*- FL
6	2		*REAR BUMPER REVERSE SENSOR	Shorted	492.00 FL	*492.00 FL
7	2		*REAR BUMPER REVERSE SENSOR OUTER RING	Necessary	12.00 FL	*12.00 FL
8	1		*REAR BUMPER REVERSE SENSOR WIRE HARNESS	Cracked	326.40 FL	*326.40 FL
9	1		*REAR BUMPER REVERSE SENSOR CONTROL BOX	O/s Cracked	1,310.40 FL	*655.20 FL
10	1		*REAR BUMPER REVERSE CAMERA	Shorted	448.80 FL	*448.80 FL
11	2		*REAR LICENCE PLATE LAMP	Cracked	76.00 FL	*76.00 FL
12	1		*BOOTLID	Buckled	1,858.80 FL	*1,858.80 FL
13	2		*BOOTLID LATCH STOPPER	Not Necessary	40.80 FL	*- FL
14	1		*BOOTLID INNER GARNISH	Deformed / Cracked	200.40 FL	*200.40 FL
15	1		*BOOTLID EMBLEM BADGE	Necessary	98.40 FL	*98.40 FL
16	1		*BOOTLID INSIGNIA BADGE	Necessary	85.20 FL	*85.20 FL
17	1		*BOOTLID TURBO BADGE	Necessary	78.00 FL	*78.00 FL
18	1		*BOOTLID LOCK	Twisted	300.00 FL	*300.00 FL
19	2		*BOOTLID LAMP	Not Necessary	756.00 FL	*- FL
20	1		*BOOTLID WEATHERSTRIP	Twisted	134.40 FL	*134.40 FL
21	1		*REAR END PANEL	Badly Dented	493.20 FL	*493.20 FL
22	1		*REAR END PANEL TOP GARNISH	Twisted	109.20 FL	*109.20 FL
23	2		*TAILLAMP, BODY	Cracked	1,230.00 FL	*1,230.00 FL
24	8		*TAILLAMP CLIPS	Not Necessary	36.00 FL	*- FL
25	1		*REAR EXHAUST BOX ASSY	Not Necessary	1,521.60 FL	*- FL
26	1		*REAR EXHAUST BOX HEAT SHIELD	Not Necessary	199.20 FL	*- FL
27	2		*REAR EXHAUST BOX MOUNTING	Not Necessary	100.00 FL	*- FL
28	1		*FRONT BUMPER	Distorted	1,558.80 FL	*1,558.80 FL
29	8		*FRONT BUMPER CLIPS	Necessary	36.00 FL	*36.00 FL
30	1		*RADIATOR OUTER CHROME MOULDING	Cracked	328.80 FL	*328.80 FL
31	2		*RADIATOR OUTSIDE SIDE CHROME MOULDING	Scratched	314.00 FL	*314.00 FL
32	1		*RADIATOR GRILLE	Cracked	358.80 FL	*358.80 FL
33	1		*FRONT BUMPER FOAM IMPACT SENSOR	Not Necessary	459.00 FL	*- FL
34	2		*HEADLAMPS	Cracked	1,972.80 FL	*1,972.80 FL
35	1		*RADIATOR GRILLE EMBLEM BADGE	Scratched	90.00 FL	*90.00 FL
36	1		*FRONT BUMPER REINFORCEMENT	Bent	550.80 FL	*550.80 FL
37	1		*FRONT BUMPER FOAM	Torn	128.40 FL	*128.40 FL
38	2		*TAILLAMP BRACKET	Not Necessary	144.00 FL	*- FL
39	6		*FRONT BUMPER PARKING SENSOR	Shorted 2pcs Only	1,476.00 FL	*492.00 FL
40	1		*FRONT LICENCE PLATE	Cracked	50.00 FS	*40.00 FS
41	1		*REAR LICENCE PLATE	Cracked	50.00 FS	*40.00 FS
42	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
43	1		*REAR WINDSCREEN INNER SPONGE SEAL	Necessary	120.00 FS	*30.00 FS
44	1		*REAR BUMPER REINFORCEMENT	Distorted	399.60 FL	*399.60 FL
45	1		*REAR BUMPER TOP BEAM	Cracked	293.20 FL	*293.20 FL
46	1		*REAR END PANEL KEYLESS SENSOR	Cracked / Shorted	189.60 FL	*189.60 FL
47	1		*FRONT SUPPORT PANEL TOP GARNISH	Torn	287.70 FL	*287.70 FL
48	1		*FRONT BUMPER TOP GARNISH	Cracked	252.40 FL	*252.40 FL
49	1		*FRONT BUMPER TOP BEAM	Bent	493.20 FL	*493.20 FL
50	1		*FRONT AIR DUCT	Cracked	386.70 FL	*386.70 FL
51	2		*FRONT AIR GUIDE	Torn	67.20 FL	*67.20 FL
52	2		*HEADLAMP LOWER BRACKET	Cracked	115.20 FL	*115.20 FL
53	2		*FRONT BUMPER REINFORCEMENT SIDE BRACKET	Cracked	108.80 FL	*108.80 FL
54	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	112.80 FL	*- FL
55	1		*BONNET LOCK	Twisted	103.20 FL	*103.20 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	2		*FRONT SAFETY BELT	Activated	1,732.80 FL	*1,732.80 FL
57	2		*REAR SAFETY BELT	Activated	1,732.80 FL	*1,442.00 FL
58	2		*FRONT SAFETY BELT BUCKLE	Activated	919.20 FL	*919.20 FL
59	2		*REAR SAFETY BELT BUCKLE	Not Necessary	919.20 FL	*- FL
					Sub Total (\$)	27,640.40
						21,108.60
					- List Item Discount on L Items 10.00/10.00% (\$)	2,734.04
						2,095.86
					Total Parts (\$)	24,906.36
						19,012.74

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	100.00	30.00
2	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	300.00	60.00
3	TO PLACE VEHICLE ON JIG BENCH TO OBTAIN CROSS AND PARALLEL MEASUREMENT AND CORRECT TO MANUFACTURER SPECIFICATION WITH HYDRAULIC PNEUMATIC JACK.	New	300.00	0.00
4	TO DROP REAR EXHAUST BOX AND RENEW THE SAME.	New	80.00	0.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	New	120.00	120.00
6	TO REINSTALL OF REAR BUMPER PARKING SENSOR. }	New	80.00	50.00
7	TO REINSTALL OF FRONT BUMPER PARKING SENSOR. }	New	80.00	0.00
8	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	100.00	60.00
9	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.	New	100.00	80.00
10	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	1,600.00	1,000.00
11	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	1,400.00	1,300.00
12	TOWING CHARGES.	New	80.00	50.00
13	USING ONBOARD SCAN TOOL (OBD) PERFORM FULL ENGINE DIAGNOSTIC CHECK, TO CONFIGURE AND CLEAR, RESET SRS SERVICE LIGHT.	New	350.00	300.00
14	TO REMOVE AND INSTALL SEAT BELT AND SEAT BELT BUCKLE.	New	450.00	200.00
Gross Labour Cost (\$\$)			5,140.00	3,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >