

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

CHOO LIH WEI

BLK 206 JURONG EAST STREET 21

#05-223

S 600206

TP MS16

Yvonne

Date

Vehicle No

Make/Model

Accident date

:24.04.2020

:EE 17 S

:KIA CERATO K3

:30.03.2020

No	DESCRIPTION	Qty	Amount (\$\$)
<u>List Items</u>			
1	Front bumper <i>He m</i>	1	\$ 702.90 ✓
2	Front bumper side holder @ \$41.80 <i>net m</i>	2	\$ 83.60 ✓
3	Front bumper clips (1set) <i>He m</i>	1	\$ 70.00 ✓
4	Front RH fender <i>Dented</i>	1	\$ 357.50 ✓
5	Front RH fender inner shield	1	\$ 104.50 ✓
6	Front RH fender inner shield clips (1set) <i>NEC</i>	1	\$ 70.00 ✓
7	Front RH fender signal lamp <i>NEC</i>	1	\$ 74.80 ✓
8	Front RH fender quarter glass	1	\$ 141.50 ✓
9	Front RH door <i>Regis</i>	1	\$ 1096.50 ✓
10	Front RH door glass outer moulding <i>ut</i>	1	\$ 88.00 ✓
11	Front RH door side mirror assy <i>Broken</i>	1	\$ 418.00 ✓
12	Front RH door outer handle <i>ut</i>	1	\$ 132.70 ✓
13	Front RH shock absorber	1	\$ 308.00 ✓
14	Front RH drive shaft	1	\$ 880.00 ✓
15	Front RH lower arm <i>He m</i>	1	\$ 371.80 ✓
16	Front RH knuckle arm	1	\$ 385.00 ✓
17	Front RH knuckle arm bearing <i>Regis</i>	1	\$ 144.10 ✓
18	Rear windscreen rubber <i>He m</i>	1	\$ 68.20 ✓
19	Rear RH door <i>Regis</i>	1	\$ 1014.00 ✓
20	Rear RH door outer handle <i>He m</i>	1	\$ 121.70 ✓
21	Rear RH fender <i>Regis</i>	1	\$ 1279.30 ✓
22	Rear RH fender lower sticker <i>He m</i>	1	\$ 30.80 ✓
23	Rear RH shock absorber	1	\$ 276.10 ✓
24	Rear RH knuckle arm <i>He m</i>	1	\$ 479.60 ✓
25	Rear RH knuckle arm bearing	1	\$ 418.00 ✓
26	Rear axle assy <i>He m</i>	1	\$ 1134.10 ✓
			\$ 10250.70
Less 10% Disc			\$ 1025.07
Total			\$ 9225.63

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

CHOO LIH WEI
BLK 206 JURONG EAST STREET 21
#05-223
S 600206

Date :24.04.2020
Vehicle No :EE 17 S
Make/Model :KIA CERATO K3
Accident date :30.03.2020

No	DESCRIPTION	Qty	Amount (\$\$)
----	-------------	-----	---------------

Special Nett Items

1	Front RH sport rim <i>cut</i>		\$ 750.00 <i>850?</i>
2	Front RH tyre <i>new</i>	1100	\$ 380.00 <i>x</i>
3	Rear RH sport rim <i>cut</i>		\$ 750.00 <i>850</i>
4	Rear RH tyre <i>new</i>		\$ 380.00 <i>x</i>
Total			\$ 2260.00

Labour Cost

1	To check wheel alignment		\$ 100.00 <i>80</i>
2	To supply rear windscreen sealant		\$ 50.00 <i>x</i>
3	Remove & reinstall front and rear RH suspension		\$ 500.00 <i>220</i>
4	Remove & reinstall roof lining + cushion		\$ 150.00 <i>x</i>
5	Remove & reinstall rear windscreen	1500	\$ 150.00 <i>x</i>
6	Remove & reinstall door glass		\$ 150.00 <i>x</i>
7	Remove ,replace & repair consistent to the accident		\$ 1600.00 <i>800</i>
8	Respray painting		\$ 1400.00 <i>200</i>
9	Tuff kote		\$ 100.00 <i>x</i>
Total			\$ 4200.00

Grand Total \$ 15685.63

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 3653.99

4/s 29K

0ADays

29K