

22/03/2022

ASS. REC. BY:

REF: CS/CTI20004841 /

d3

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Tan Kah Leong

of

CTI

Date/Time: 24/2020 @ 5.02pm

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJZ 9681 U

Insured:

SKW 7885R

at Workshop m/s

Mylar Consultant

Tel:

8866 8832.

of

53 Ubi Avenue 1 # 01-33

Policy No:

Claim No:

8NM20D201590/SKW7885R/TKL

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

27/03/2020

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

5.05pm 24/2020

Person Contacted:

Hui Qin

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate
	SJZ 9681 U - X	
	SKW 7885R - CC6/AIG 16013813 / U26392	DOT: 21/07/2016
13.04.2020 1.52pm	Summer informed Kah Leong, according to repairer the owner had scrapped the vehicle without any arrangement on inspection. No inspection done, We will close file at our end. Celine 14.07.2021	