

TAX INVOICE

Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909
Attn: Motor Claims Dept

S1000003 /ICCI1

39010781

17/04/2020

Ms Wendy Tan Chen Chen
19 Yishun Close
#14-37 Symphony Suites
Singapore 768013

Mobile: 98312340

19 GFXSK E1 ACR50R 13/06/2019 SKW1108R 11929 20074 67/TP/SKW1108R

JTEGD56M107171823 2AZ1B06970 60 Sam San Joi 01/04/2020 17.15 17/04/2020 8.45

1	Z	BP-SUNDRY	SUNDRIES	TP CLAIM		30.00
		TP-GBE9019M		ACC DATE:31/03/2020		
		DRIVE IN:01/04/2020				
		DATE-IN:06/04/2020		DATE SURVEY:06/04/2020		
		NO OF REPAIR DAYS:6 DAYS				
		BY:ADRIAN LING(LKK)				
2	S	PSP PER PANE	LABOUR FOR PLATINUM SHINEPRO & SHINE	A000		183.18
		PER PANEL APPLICATION ON REAR ACCIDENT AREAS				
3	S	BP-SUBLET	INSTALL REAR WINDSCREEN GLASS 3M SOLAR FA000			400.00
		ILM				
4	B	BP-ECU2	TO RESET ECU AND REPROGRAMME	*		180.00
5	S	BP-SUBLET	DRILL HOLE & INSTALL REAR REVERSE SENSOR A000			180.00
6	S	BP-SUBLET	CHECK LIGHTING & CONDUCT WATER LEAK TEST A000			180.00
7	S	BP-SUBLET	SUPPLY SEALANT (NETT)- TAILGATE	A000		60.00
8	S	BP-SUBLET	REMOVE & INSTALL REAR COMPARTMENT CARPET A000			360.00
		,GARNISH A	TRIMMING TO ASSIST REPAIR			
9	S	BP-SUBLET	REMOVE & INSTALL REAR REVERSE CAMERA	A000		180.00
10	S	BP-SUBLET	REPLACE & INSTALL REAR WINDSCREEN GLASS	A000		462.00
11	S	BP-SUBLET	TRANSFER & INSTALL COMPONENTS TO NEW TAI A000			360.00
		LGATE				

PLEASE MAIL YOUR CHEQUE TO 2 PANDAN CRESCENT, LEVEL 10 INCHCAPE CENTRE, SINGAPORE 128462

17/04/2020
08:45

SKW1108R

TAX INVOICE

Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909
Attn: Motor Claims Dept

S1000003 /ICCI1

39010781

17/04/2020

Ms Wendy Tan Chen Chen
19 Yishun Close
#14-37 Symphony Suites
Singapore 768013

Mobile: 98312340

19 GFXSK E1 ACR50R 13/06/2019 SKW1108R 11929 20074 67/TP/SKW1108R

JTEGD56M107171823 2AZ1B06970 60 Sam San Joi 01/04/2020 17.15 17/04/2020 8.45

12	S	BP-SUBLET	REPLACE REAR ACCIDENT DAMAGED PARTS	A000		2160.00
			STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS			
13	S	BP-SUBLET	RESPRAY JOB ON REAR ACCIDENT AFFECTED AREA	A000		1770.00
			EAS			
14	1	T52159-28959	COVER, RR BUMPER AERAS	1.00	596.90	596.90
15	2	S52161-0K040	PIECE,RR BUMPER	10.00	4.10	41.00
16	3	T67005-28D10	PANEL ASSY, BACK DOOR	1.00	1753.60	1753.60
17	4	T68105-28680	GLASS, BACK DOOR	1.00	1291.30	1291.30
18	5	T04562-12010	DAM KIT, WINDOW GLASS	1.00	121.00	121.00
19	6	T21000-20	SIKA 210002-0 TACK GO! (BLACK) SG	2.00	108.00	216.00
20	7	T21000-22	SIKA 210002-2 G+P 207 ADHESIVE PRIME	1.00	200.00	200.00
21	8	T90975-02064	EMBLEM, SYMBOL	1.00	72.20	72.20
22	9	T75441-28730	PLATE, LUGGAGE	1.00	44.10	44.10
23	0	T75441-28720	PLATE, LUGGAGE	1.00	57.20	57.20

10,898.48

4,393.30 GST 7.00% 762.89

210.00

6,295.18 0.00

0.00

0.00

11,661.37

PLEASE MAIL YOUR CHEQUE TO 2 PANDAN CRESCENT, LEVEL 10 INCHCAPE CENTRE, SINGAPORE 128462

17/04/2020

08:45

SKW1108R