

HWA SENG SPRAY PAINTING CO
 160 Sin Ming Drive
 #05-11 Sin Ming Autocity
 SINGAPORE 575722
 (REGISTRATION NO.: 095744/00B)
 TEL: 64533100
 FAX: 62669932

Date of accident 31/03/2020
 Your Insured vehicle no. SHA 78HF
 Not Authored
 11 Days @ ?
 Paying After Repair
 4-5 days

ESTIMATE REPAIR COSTS TO HONDA INSIGHT REG. NO.: SKP 7326 A

			SS
1pc	Tailgate		R 928.20 ✓
2pcs	Tailgate Hinges	(S\$42.20/pc)	R 84.40 X
2pcs	Tailgate Absorber	(S\$124.80/pc)	Ln 249.60 X
1pc	Tailgate Garnish		Ln 305.80 X
1pc	Emblem 'INSIGHT'		na na 48.50 X
1pc	Logo Emblem		na 38.60 X
1pc	Emblem 'HYBRID'		na 52.50 X
1pc	Tailgate Upper Lock		na 282.20 ✓
1pc	Tailgate Lower Lock		R 42.00 X
1pc	Tailgate Handle		Ln 74.80 X
2pcs	Taillamp	(S\$576.00/pc)	Ln 1152.00 X
1pc	Tailgate Reflector		Ln 211.00 ✓
1pc	Rear Bumper		Ln 701.60 ✓
1pc	Rear Bumper Reinforcement		nn 385.00 7X
1pc	Rear Bumper Beam		nn 197.00 7X
2pcs	Rear Bumper Retainer	(S\$47.40/pc)	Ln 94.80 X
1pc	Rear Bumper Lower Garnish		na/na 189.00 ✓
2pcs	Rear Bumper Lower Garnish Reflector	(S\$44.20/pc)	na/na 88.40
1pc	End Panel bent		438.70 7 ✓
1pc	End Panel Garnish		nn 141.20 7X
1pc	Spare Tyre Panel		R 611.30 X
1pc	Spare Tyre Board		Ln 197.00 X

Less : 20%

6493.40

1298.68

5194.72

LABOUR & MISC CHARGES

Panel Knocking
 Spray Painting
 Wire Checking
 Labour to remove and install rear windscreen
 Sealant & Clip
 Inner Seal
 Labour to remove and install upholstery
 1 Set Reverse Sensor shorted
 1 set Number Plate with Holder

	1000.00	7600 ✓
	1200.00	600 ✓
	50.00	15 ✓
	180.00	120 ✓
NEC	80.00	60 ✓
NEC	60.00	30 ✓
	150.00	760 ✓
	230.00	7200 ✓
Ln	75.00	X

TOTAL

8199.72

HWA SENG SPRAY PAINTING COMPANY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

HWA SENG SPRAY PAINTING CO
160 Sin Ming Drive
#05-11 Sin Ming Autocity
SINGAPORE 575722
(REGISTRATION NO.: 095744/008)
TEL: 64533100
FAX: 62669932

ESTIMATE REPAIR COSTS TO HONDA INSIGHT REG. NO. : SKP 7328 A
S\$

SUPPLEMENTARY LABOUR

Remove, install & Reset Hybrid Battery

450.00

2501

HWA SENG SPRAY PAINTING COMPANY


