



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2100572
3 ANSON ROAD #16-00	INV Date	27/01/2021
SPRINGLEAF TOWER	Reference	CC6/CTI20004850/Kga3q2
SINGAPORE 079909	Code	CTI

### PROFESSIONAL SERVICE FEE

Vehicle No.	SLT 158G
Insured Veh.	GZ 6707K
Claim No.	SNM20D201607
Policy No.	DMPCSN1820381901
Accident Date	20/03/2020
Inspection Date	02/06/2020

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWERSINGAPORE 079909

Ref: CC6/CTI20004850/Kga3q2

Date: 27/01/2021

Code: CTI

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	GZ 6707K	<b>Veh. Inspected</b>	SLT 158G
<b>Policy No.</b>	DMPCSN1820381901	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	SNM20D201607	<b>Excess (\$)</b>	0.00
<b>Assign From</b>		<b>Assign Date</b>	02/06/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	HONDA SHUTTLE (A)	<b>c.c</b>	1496
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2020
<b>Chassis No.</b>	GK82101309	<b>Colour</b>	METALLIC GREY
<b>Odometer</b>	4631 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	205/50 R16	KUMHO	9 mm
<b>L/H Front Tyre</b>	205/50 R16	KUMHO	9 mm
<b>R/H Rear Tyre</b>	205/50 R16	KUMHO	9 mm
<b>L/H Rear Tyre</b>	205/50 R16	KUMHO	9 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S DOOR.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	20/03/2020	<b>Inspection Date</b>	02/06/2020
<b>Survey held at</b>	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 158G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	REAR LH DOOR	DENTED / WARPED	799.50	799.50
1	REAR LH DOOR FRAME TAPE	NECESSARY	18.50	18.50
	LESS 20% DISCOUNT		-163.60	-163.60
			654.40	654.40
	<b>LABOUR</b>			
	TO PUTTY & SPRAY PAINTING .		300.00	220.00
	TO TRANSFER DOOR FITTING.		50.00	50.00
	TO ANTI RUST .		50.00	30.00
	LABOUR CHARGES.		250.00	200.00
	PAINT TREATMENT.		450.00	100.00
			1,100.00	600.00
	<b>GRAND TOTAL</b>		<b>1,754.40</b>	<b>1,254.40</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>1,254.40</b>

Report Ref No. CC6/CTI20004850/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



# LKK Auto Consultants Pte Ltd






51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. SLT 158G

## INSPECTION








# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. SLT 158G**

**RE-INSPECTION**

