

VEHICLE TO REPAIR

VEHICLE NO. : SLT 158 G
 MAKE : HONDA
 MODEL : SHUTTLE 1.5G CVT SENSING
 YEAR : 2019
 CHASSIS NO : GK82101309

SURVEYOR NAME :	Kenneth (LKK)
DATE OF SURVEY :	06.06.2020
TIME OF SURVEY :	

DATE : 01-Apr-20
 DATE OF ACCIDENT : 20-Mar-20
 THIRD PARTY REF : GZ 6707 K / CHINA TAIPING

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear LH Door			<i>Redwork</i>	\$ 799.50 ✓
1 pc	Rear LH Door frame Tape				\$ 18.50 ✓
	Less 20%				\$ 818.00
					\$ 163.60
					\$ 654.40
	To Putty & Spray Painting			<i>08.00</i>	\$ 300.00 <i>220</i>
	To transfer Door Fitting			<i>153.60</i>	\$ 50.00 ✓
	To Anti Rust			<i>100.00</i>	\$ 50.00 <i>30</i>
	Labour Charges			<i>160.00</i>	\$ 250.00 <i>200</i>
	<i>Supplementary</i>				
	<i>Paint Treatment \$ 450</i> ✓			<i>Not Authen</i>	<i>2 days</i>
TG-TH/-	TOTAL				\$ 1,304.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

LTM Tan Motor Pte Ltd
 84, 170, Tanjong Pagar Road, Singapore 068521
 Tel: 65-64525693 Fax: 65-64525694 Email: admin@ltm.sg Website: www.ltm.sg
 Co. Reg No: 190012773 GST Reg No: M2-C019080-0
 Signature: _____ Date: _____