

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Dec 2019		15 May 2020 12:11 Edit Adj Rpt	S\$4,235.00 Edit Estimates	S\$4,235.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:	-, Co. Reg. No.: -								
Main Claimant:	LEE XUAN JUN, ID: S8939100H								
Vehicle Reg. No.:	SMJ561R	Date of Loss:	25/12/2019 14:00 - :59 [10 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D206129C02	Policy/Cover Note No.:	DMCVSN30415719011						
Vehicle Reg. No. (Insured):	GBG3112E	Policy No. (Claimant):	1900017209						
		Excess:	S\$500.00						
Repairer:	Cycle & Carriage France Pte Ltd (Pandan Gardens) (HQ) 209 PANDAN GARDENS, 609339 West Coast - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 27/05/2020]								
ASSOCIATED MAIL RECEIVED			View All Compose Case Mail						
There are no mail for this case.									
ALL ASSOCIATED TASKS			View All Search Tasks Create New Task Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMJ561R (SNM19D206129C02)**
[GBG3112E]

TP

LEE XUAN JUN

Dec 25 2019 2:00PM

[-]

Cycle & Carriage France Pte Ltd (Pandan Gardens)

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)
▼

Assessment Reports				
		1 per page ▼		☒
No	Finalized On	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)	Thumbnail	Print
1	26/12/19 15:28	Accident Statement	 Load HTM	

Photos/Images				
		3 per page ▼		☒
No	Finalized On	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)	Thumbnail	Print
1	26/12/19 15:26	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
2	26/12/19 15:26	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
3	26/12/19 15:26	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
4	26/12/19 15:26	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
5	26/12/19 15:26	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
6	26/12/19 15:26	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
7	26/12/19 15:26	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
8	26/12/19 15:26	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
9	26/12/19 15:26	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
10	26/12/19 15:26	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
11	26/12/19 15:26	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
12	26/12/19 15:26	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
13	26/12/19 15:26	Driving License [Linked Accident Report Documents]	 Load JPG	☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/05/20 13:24	General View	 Load JPG	☒
2	15/05/20 13:24	General View	 Load JPG	☒
3	15/05/20 13:24	General View	 Load JPG	☒
4	15/05/20 13:24	General View	 Load JPG	☒
5	15/05/20 13:24	General View	 Load JPG	☒
6	15/05/20 13:24	General View	 Load JPG	☒
7	15/05/20 13:24	General View	 Load JPG	☒
8	15/05/20 13:24	General View	 Load JPG	☒
9	15/05/20 13:24	General View	 Load JPG	☒
10	15/05/20 13:24	General View	 Load JPG	☒
11	15/05/20 13:24	General View	 Load JPG	☒
12	15/05/20 13:24	General View	 Load JPG	☒
13	15/05/20 13:24	General View	 Load JPG	☒
14	15/05/20 13:24	General View	 Load JPG	☒
15	15/05/20 13:24	General View	 Load JPG	☒
16	15/05/20 13:24	General View	 Load JPG	☒
17	15/05/20 13:24	General View	 Load JPG	☒
18	15/05/20 13:24	General View	Load JPG	☒
19	15/05/20 13:24	General View	Load JPG	☒

Assessment Reports				1 per page ▼	✓
No	Finalized On	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)		Thumbnail	Print
20	15/05/20 13:24	General View		Load JPG	✓
21	15/05/20 13:24	General View		Load JPG	✓
22	15/05/20 13:24	General View		Load JPG	✓
23	15/05/20 13:24	General View		Load JPG	✓
24	15/05/20 13:24	General View		Load JPG	✓
25	15/05/20 13:24	General View		Load JPG	✓
26	15/05/20 13:24	General View		Load JPG	✓
27	15/05/20 13:24	General View		Load JPG	✓
28	15/05/20 13:24	General View		Load JPG	✓
29	15/05/20 13:24	General View		Load JPG	✓
30	15/05/20 13:24	General View		Load JPG	✓
31	15/05/20 13:24	General View		Load JPG	✓
32	15/05/20 13:24	General View		Load JPG	✓
33	15/05/20 13:24	General View		Load JPG	✓
34	15/05/20 13:24	General View		Load JPG	✓
35	15/05/20 13:30	Reinspection Photo		Load JPG	✓
36	15/05/20 13:30	Reinspection Photo		Load JPG	✓
37	15/05/20 13:30	Reinspection Photo		Load JPG	✓
38	15/05/20 13:30	Reinspection Photo		Load JPG	✓
39	15/05/20 13:30	Reinspection Photo		Load JPG	✓
40	15/05/20 13:30	Reinspection Photo		Load JPG	✓
Documentation				1 per page ▼	✓
No	Finalized On	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)		Thumbnail	Print
1	26/12/19 15:26	Sketch Plan [Linked Accident Report Documents]		Load JPG	✓
2	26/12/19 15:26	Sketch Plan #2 [Linked Accident Report Documents]		Load JPG	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	18/05/20 14:16	SUPPLEMENTARY		Load PDF	

Linked Accident Report Documents

Assessment Reports				View	View in Browser ▼
No	Finalized On	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)		Thumbnail	Print
1	26/12/19 15:28	Accident Statement		Load HTM	
Photos/Images				3 per page ▼	✓
No	Finalized On	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)		Thumbnail	Print
1	26/12/19 15:26	Accident Photo		Load JPG	✓
2	26/12/19 15:26	Accident Photo		Load JPG	✓
3	26/12/19 15:26	Accident Photo		Load JPG	✓
4	26/12/19 15:26	Accident Photo		Load JPG	✓
5	26/12/19 15:26	Accident Photo		Load JPG	✓
6	26/12/19 15:26	Accident Photo		Load JPG	✓
7	26/12/19 15:26	Accident Photo		Load JPG	✓
8	26/12/19 15:26	Accident Photo		Load JPG	✓
9	26/12/19 15:26	Accident Photo		Load JPG	✓
10	26/12/19 15:26	Accident Photo		Load JPG	✓
11	26/12/19 15:26	Accident Photo		Load JPG	✓
12	26/12/19 15:26	Accident Photo		Load JPG	✓
13	26/12/19 15:26	Driving License		Load JPG	✓
Documentation				1 per page ▼	✓
No	Finalized On	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)		Thumbnail	Print

Assessment Reports				1 per page ▼	
No	Finalized On	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)		Thumbnail	Print
1	26/12/19 15:26	Sketch Plan		Load JPG	
2	26/12/19 15:26	Sketch Plan #2		Load JPG	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI19022872/R1TF3S2-1**Date:** 18/05/2020REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30415719011
Claimant Vehicle No :	SMJ561R	Insured Vehicle No :	GBG3112E
Date of Loss:	25/12/2019	Nature of Claim:	TP
		Claim No:	SNM19D206129C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ561R	Engine No:	G3LCJP150390
Make & Model:	KIA STONIC, 998cc DCT (A)	Chassis No:	KNAD6811VK6251905
Reg. Date:	21/02/2019 (Man. Year: 2018)	Odometer:	21840 km
Colour:	Yellow		
Engine Capacity:	998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R17	Rear Tyre Size:	205/55 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,500.00	1,805.00	695.00	27.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,160.00	2,430.00	730.00	23.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	5,660.00	4,235.00	1,425.00	25.18
+ GST 7.00/7.00% (\$\$)	396.20	296.45	99.75	25.18
Nett Amount (\$\$)	6,056.20	4,531.45	1,524.75	25.18

INSPECTION

Date of Assignment:	15/05/2020	
Date Inspected:	02/04/2020 Inspected At:	Cycle & Carriage France Pte Ltd (Pandan Gardens) (HQ) 209 PANDAN GARDENS Singapore 609339
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD RASUL**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 May 2020)
Parts:	143	KIA STONIC 998cc DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMJ561R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER-RR BUMPER LWR	Deformed	366.00 FS	*366.00 FS
2	1		*SKID PLATE-RR BUMPER	Deformed	122.00 FS	*122.00 FS
3	1		*ULTRASONIC SENSOR ASSY - BWS	Serviceable	189.00 FS	*- FS
4	1		*BEAM-RR BUMPER	Serviceable	419.00 FS	*- FS
5	1		*STAY-RR BUMPER LH	Serviceable	55.00 FS	*- FS
6	1		*ANTENNA ASSY - SMARTKEY	Serviceable	32.00 FS	*- FS
7	1		*PANEL ASSY-TAIL GATE	Bent	1,010.00 FS	*1,010.00 FS
8	1		*LOGO ASSY-KIA SUB	Necessary	51.00 FS	*51.00 FS
9	1		*EMBLEM - STONIC	Necessary	26.00 FS	*26.00 FS
10	1		*C&C LOGO	Necessary	40.00 FS	*40.00 FS
11	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
12	1		*EMBLEM - TURBO G.D.I	Necessary	38.00 FS	*38.00 FS
13	1		*GARNISH - T/GATE UPR, RH	Cracked	66.00 FS	*66.00 FS
14	1		*GARNISH - T/GATE UPR, LH	Cracked	66.00 FS	*66.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	2,500.00	1,805.00
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW REAR BUMPER, TAILGATE	New	1,650.00	1,100.00
2	REMOVE & INSTALL PARKING SENSOR.	New	60.00	60.00
3	REMOVE & INSTALL TAILGATE GLASS.	New	300.00	240.00
4	APPLY SEALANT FOR TAILGATE GLASS.	New	80.00	80.00
5	SPRAY PAINT FOR TAILGATE.	New	500.00	420.00
6	CHECK WIRING & ELECTRICAL SYSTEM.	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.	New	200.00	200.00
8	APPLY SEALANT FOR ACCIDENT PORTION.	New	40.00	40.00
9	REMOVE & INSTALL TAILGATE TRIMS.	New	300.00	260.00
Gross Labour Cost (\$\$)			3,160.00	2,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >