



陳林淨呀私人有限公司
TAN LIM MOTOR PTE LTD

MS FCIL Insured's Veh No : SHA4610M

Date of Accident : 21 March 2020

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Mr Lee Eng Hwee

Date : 31 March 2020

Estimate To Repair SMN9950X - Mitsubishi ATTRAGE 1.2 CVT

Chassis No : MMBSTA13AKH002621

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	rear bumper	\$ 659.00
02	2 ps	rear bumper side retainers @ \$22.00	\$ 44.00
03	10 ps	rear bumper clips @ \$3.50	\$ 35.00
04	1 pc	rear end panel	\$ 402.00
			\$ 1,140.00
		Less 10 %	\$ 114.00
			\$ 1,026.00
		<u>SPECIAL NETT ITEMS</u>	
05	1 pc	rear bumper lower assy	\$ 850.00
06	1 set	rear bumper parking sensor	\$ 350.00
			\$ 1,200.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To reinstall of rear bumper parking sensor.	\$ 120.00
02		To check electrical lighting concerned.	\$ 80.00
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 400.00
04		Putty and spray painting of the affected portion.	\$ 500.00
			\$ 1,100.00
		Total	\$ 3,326.00