



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



### TAX INVOICE

NTUC INCOME INSURANCE CO-OPERATIVE LTD INV No. NA2002813

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSE

SINGAPORE 189556

INV Date 30/04/2020

Reference NS/INC20004869/Ftf3n2

Code INC4



### PROFESSIONAL SERVICE FEE

Vehicle No. SHC 1879P

Insured Veh. SLU 5358H

Claim No. MT/1090468-002

Policy No. 5106049188-01

Accident Date 01/04/2020

Inspection Date 02/04/2020

Description	Total
Survey Inspection	160.00
Resurvey Inspection	
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>160.00</b>
<b>GST (7%)</b>	<b>11.20</b>
<b>Grand Total</b>	<b>171.20</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'National Assessment Centre Services'

National Assessment Centre Services

*HYN*




## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC20004869/Ftf3n2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 30-04-2020	
Code: INC4				
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLU 5358H	Veh. Inspected	SHC 1879P	
Policy No.	5106049188-01	Coverage (\$)	0.00	
Claim No.	MT/1090468-002	Excess (\$)	0.00	
Assign From		Assign Date	02/04/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HYUNDAI IONIQ	c.c	1580	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	KMHC851CVLU190282	Colour	BLUE	
Odometer	18869	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	DAVANTI	8 mm	
L/H Front Tyre	195/65 R15	DAVANTI	8 mm	
R/H Rear Tyre	195/65 R15	DAVANTI	8 mm	
L/H Rear Tyre	195/65 R15	DAVANTI	8 mm	
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR AND REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
Accident Date	01/04/2020	Inspection Date	02/04/2020	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1879P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	IONIQVC COVER-RR BUMPER	DEFORMED	459.40	459.40
1	IONIQVC BRACKET ASSY-RR B	NOT NECESSARY	55.80	-
10	HYUNDAI BUMPER COVER CLIP	NECESSARY	22.00	22.00
1	IONIQV2 MOULDING ASSY-RR	SCRATCHED	451.25	451.25
1	IONIQVC GUARD-REAR WHEEL	NOT NECESSARY	73.60	-
	LESS 20% DISCOUNT		-212.41	-186.53
			849.64	746.12
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	IONIQVC PROTECTOR MAT (SN)	NECESSARY	50.00	50.00
			50.00	50.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING.(REPAIR RR FENDER RH).		500.00	480.00
	SPRAYPAINT ON AFFECTED AREA.		450.00	400.00
	TUFF COAT ON AFFECTED PARTS.		50.00	30.00
	REMOVE/REFIX REVERSE SENSOR.		80.00	60.00
			1,080.00	970.00
	<b>GRAND TOTAL</b>		<b>1,979.64</b>	<b>1,766.12</b>
	<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>			<b>1,766.12</b>

Report Ref No. NS/INC20004869/Ftf3n2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

PHOTOGRAPHS FOR VEHICLE NO. SHC 1879P

INSPECTION





## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

PHOTOGRAPHS FOR VEHICLE NO. SHC 1879P

RE-INSPECTION

