

SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 91993103 / 97825292 Fax: (65) 68163103

Email : Sinyusin@hotmail.com

31 March 2020

QUOTATION FOR ACCIDENT REPAIR OF SMM4743R TOTOTA NOAH

THIRD PARTY INSURER: AXA

S/No.	Parts List	Qty	Amount (\$)
1.	Rear tailgate	1 1649.00	\$ 1715.50 ✓
2.	Rear tailgate "Hybrid Synergy Drive" emblem	1	\$ 75.00 ✓
3.	Rear tailgate weather strip	1	\$ 371.80 ✓
4.	Rear tailgate mechanism lock	1	\$ 531.40 ✓
5.	Rear tailgate lock striker	1	\$ 101.00 X
6.	Rear tailgate inner trim	1	\$ 731.40 X
7.	Rear tailgate inner trim clip	8 8.50	\$ 68.00 X
8.	Rear tailgate keyless sensor	1	\$ 158.20 X
9.	Rear bumper	1 1025.00	\$ 1217.80 ✓
10.	Rear bumper side retainer L/R	2 60	\$ 120.00 X
11.	Rear end panel (outer)	1	\$ 561.60 ✓
12.	Rear end panel (inner)	1	\$ 781.30 X
13.	Rear end panel garnish	1 245.30	\$ 271.30 ✓
Subtotal before discount			\$ 6704.30
Discount 25%			\$ 1676.07
Subtotal 1			\$ 5028.22

S/NETT	Parts List	Qty	Amount (\$)
1.	Rear bumper clip	1	\$ 30 ✓
2.	Rear tailgate windscreen sealant	1	\$ 100 40
3.	Rear reverse sensor	1 set	\$ 350 200
4.	Rear end panel sealant	1	\$ 50 ✓
S/Nett Total			\$ 530

p- 4459.10
 25%
 p- 3344.32
 S.W- 320.00
 L- 1690.00
 5344.32
 20%
 6243

not Admit
 1/5 \$ 4200
 Take pmt. At Hkay
 4 days.
 3/4/20

1/5 \$ 4200

SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 91993103 / 97825292 Fax: (65) 68163103

Email : Sinyusin@hotmail.com

31 March 2020

QUOTATION FOR ACCIDENT REPAIR OF SMM4743R TOTOTA NOAH

THIRD PARTY INSURER: AXA

Labour

To check wiring and rectify electrical faults where necessary	\$ 60	20
To transfer rear tailgate component parts to new rear tailgate	\$ 100	60
To remove and reinstall rear windscreen glass	\$ 120	✓
To apply anti-rush undercoat	\$ 150	60
To remove and reinstall rear interior trims, garnishes, seats, etc. for necessary repairs	\$ 150	80
To remove, replace and reinstall rear reverse sensor	\$ 120	50
To remove, replace and reinstall rear reverse camera	\$ 100	
To straighten, repair, realign on front affected area and replace damaged parts	\$ 1000	600
To spray painting on affected area	\$ 1000	700
Total Labour Cost		\$ 2800

Total Cost Of Repairs (Total cost of parts + Total labour cost)

\$ 8358.22

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: