



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM20004896/Uga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 17-07-2020



ATTN:KIAN CHUAN

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGX 6068G	Veh. Inspected	SKX 4278H
Policy No.	P2381791	Coverage (\$)	0.00
Claim No.	S0M02KRN	Excess (\$)	0.00
Assign From		Assign Date	03/04/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HARRIER (A)	c.c	1986
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	ZSU600064042	Colour	PURPLE
Odometer	48712	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/65 R17	FALKEN	6 mm
L/H Front Tyre	225/65 R17	FALKEN	6 mm
R/H Rear Tyre	225/65 R17	FALKEN	6 mm
L/H Rear Tyre	225/65 R17	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	02/04/2020	Inspection Date	03/04/2020
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------