

ASS. REC. BY:

REF:

CS/AIG20004905/Kel3

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____ Aero

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: PnG 77454 Yr Regn: 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Pioner c.c. 1496

Colour: M. Black A/C: Insured / Std / NI / NA

Sp. Reading: 66987 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: M/HF 2 2814 31000 59934

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD / A/Rlm or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 1/11

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 / File pass to

3/3 10:46am Confirmed LS \$4100f with Heng Yap Seng. (Red 7811f, 65%)

Date/Time, File Pass to?

☐: Prell. Report☒: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐: Site Insp (\$☐: Interview (\$☐: Tech Invs (\$☐: Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Report Format: TP

Lump Sum / I.B.I: (\$4100f)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	129M
Vehicle Details	
Vehicle No.:	SMG7745Y
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Jan 2021
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA STANDARD (AUTO)
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	2NRX397779
Chassis No.:	MHFZ28H3100059934
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$17,664.00
Original Registration Date:	31 Dec 2018
First Registration Date:	31 Dec 2018
Transfer Count:	0
Actual ARF Paid:	\$17,664.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Dec 2028
PARF Rebate Amount:	\$13,248.00
Intended COE Rebate Details	
COE Expiry Date:	30 Dec 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$25,556.00
COE Rebate Amount:	\$20,245.00
Total Rebate Amount:	\$33,493.00

The information contained herein is correct as at 28 Jan 2021

OK

KJ

AERO GARAGE PTE LTD

Blk 160, Sin Ming Drive, #08-07 Sin Ming AutoCity, Singapore 575722

Tel : 6266 9511 Fax : 6266 9512

Vehicle No : SMG7745Y
Vehicle Model : Toyota Sienta

Not Authorized
11 Sep @ 4100h
Resurvey After Paint 6 days

Estimate Repair Cost

No.	Qty	Parts List Items	
1	1	Rear bumper (LH+CENTRE+RH) 1053.50	Buc \$ 807.10 ✓
2	2	Rear bumper retainers	\$ Sn 85.30 X
3	2	Rear bumper brackets	\$ R 110.20 X
4	2	Rear bumper reflectors	\$ Sn 106.90 X
5	1 set	Rear bumper clips	\$ Sn 40.00 ✓
6	1	Rear tailgate 1180	Bt \$ 1,040.40 ✓
7	1	Rear tailgate centre logo	\$ Sn 45.90 ✓
8	1	Rear tailgate outer chrome handle	wap \$ 108.30 ✓
9	1	Rear tailgate lock	\$ Rd 359.50 ✓
10	2	Rear tailgate hinges	\$ R 133.60 X
11	2	Rear tailgate dampers	\$ Sn 209.10 X
12	1	Rear tailgate weatherstrip	Dd/Kus 168.50 ✓
13	1	Rear tailgate "G" emblem	\$ Sn 43.20 ✓
14	1	Rear tailgate "SIENTA" emblem	\$ Sn 78.10 ✓
15	1	Rear tailgate wiper arm	\$ Sn 201.90 X
16	1	Tail lamp (outer) 380	my sm 350.90 ✓
17	1	Tail lamp (inner)	\$ Sn 241.10 ✓
18	1	Rear end panel 689.75	\$ R 617.40 ✓
19	1	Rear end panel top garnish	my \$ 219.90 ✓
20	1	Rear floor panel	\$ R 706.30 X
21	1	Rear spare tyre top board	\$ Sn 599.40 X
22	1	Rear exhaust silencer	R \$ 1,012.10 X
23	1	Rear exhaust silencer mounting	\$ Sn 85.90 X
			Total \$ 7,371.00

258

Parts Special Nett Items

24	1	Rear number plate	\$ Sn 60.00 X
25	1 set	Reverse sensor	Dd/Shog \$ 300.00 2ccsa
26	1	Reverse camera	\$ Sn 250.00 X
			\$ 610.00
			Total Parts \$ 7,981.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Labour

1	Labour charge to remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	\$	1,500.00	800/
2	To putty and respray painting on affected areas.	\$	1,200.00	800/
3	To remove, replace rear tailgate fittings to facilitate repair.	\$	350.00	60/
4	To remove, replace rear windscreen glass.	\$	200.00	120/
5	To remove, replace reverse camera.	\$	200.00	40/
6	To remove, replace reverse sensor.	\$	150.00	30/
7	To remove, replace rear exhaust silencer.	<i>in</i> \$	250.00	X
8	To check wiring and lightings.	\$	80.00	20/

Total Labour	\$	3,930.00
--------------	----	----------

Total Parts and Labour	\$	11,911.00
------------------------	----	-----------