

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG20004909/T1TF3E2**Date:** 05/07/2021REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001365224
Claimant Vehicle No :	SGR4071R	Insured Vehicle No :	GBK2142D
Date of Loss:	02/04/2020	Nature of Claim:	TP
		Claim No:	242234

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGR4071R		
Make & Model:	HONDA FREED HYBRID, 1.5 G (A)	Engine No:	LEB5615663
Reg. Date:	08/03/2019 (Man. Year: 2018)	Chassis No:	GB71079515
Colour:	White	Odometer:	23196 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/45 R17	Rear Tyre Size:	205/45 R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,449.36	2,817.60	2,631.76	48.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,810.00	1,280.00	530.00	29.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,259.36	4,097.60	3,161.76	43.55
+ GST 7.00/7.00% (S\$)	508.16	286.83	221.33	43.56
Nett Amount (S\$)	7,767.52	4,384.43	3,383.09	43.55

INSPECTION

Date of Assignment:	06/04/2020	
Date Inspected:	03/04/2020 Inspected At:	Woon Meng Motor Pte Ltd (Bukit Batok) 50 Bukit Batok Street 23,, #01-06 Midview Building Singapore 659578
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Jun 2021)
Parts:	M1-MPV	HONDA FREED HYBRID 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGR4071R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Bent	1,993.10 FL	*1,417.30 FL
2	2		*REAR BOOTLID HINGE	Repair	280.80 FL	*- FL
3	1		*REAR BOOTLID LOCK	Bent	286.20 FL	*186.60 FL
4	1		*REAR BOOTLID INNER TRIM	Not Necessary	310.50 FL	*- FL
5	2		*REAR BOOTLID ABSORBER	Not Necessary	416.80 FL	*- FL
6	1		*REAR EMBLEM	Necessary	65.50 FL	*65.50 FL
7	2		*REAR BOOTLID INNER LAMP	Not Necessary	715.00 FL	*- FL
8	1		*REAR LAMP O/S	Cracked	629.10 FL	*530.50 FL
9	1		*REAR WINDSCREEN GLASS	Cracked	1,028.40 FL	*928.40 FL
10	1		*REAR WINDSCREEN MOULDING	Necessary	65.60 FL	*65.60 FL
11	1		*REAR RUBBER	Not Necessary	216.70 FL	*- FL
12	1		*REAR END PANEL TOP GARNISH	Not Necessary	145.80 FL	*- FL
13	1		*REAR BOOTLID OUTER HANDLE	Deformed	278.10 FL	*278.10 FL
14	1		*REAR WIPER MOTOR	Not Necessary	270.20 FL	*- FL
15	1		*REAR WIPER ARM	Not Necessary	59.90 FL	*- FL
16	2		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,801.70	3,512.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,352.34	694.40
Total Parts (\$\$)	5,449.36	2,817.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REPAIR, REPLACE & INSTALL FRONT DAMAGED PARTS	New	800.00	500.00
2	TO R & R REAR WINDSCREEN GLASS	New	150.00	120.00
3	TO R & R LIGHT WIRING	New	60.00	30.00
4	TO R & R CAMERA WIRING	New	100.00	30.00
5	TO PUTTY & SPRAY PAINTING	New	700.00	600.00
Gross Labour Cost (\$\$)			1,810.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >