

The logo for mbm wheelpower, featuring a stylized wheel with a red center and a black and white patterned rim, positioned above the text "mbm wheelpower".

Not Authorized

1. B. 1. 6/1/87

~~4-5491~~

Date:	6/4/2020
From:	Eryx
Fax:	64525333
Contact:	93288668
Make / Model:	HONDA SHUTTLE HYBRID 1.5
Chassis No.:	GP71213372
Engine No.:	LEB6556249
Year of Make:	2018
Accident Date:	3 April 2020

List Price

REAR WINDSCREEN MOULDING	1	\$ 120	166.00	-
TAIL GATE	1	\$ 1193	1,432.00	-
TAIL GATE WEATHERSTRIP	1	\$	220.00	-
TAIL GATE LOCK	1	\$	308.00	X
TAIL GATE "SHUTTLE" EMBLEM	1	\$	76.00	-
TAIL GATE "HYBRID" EMBLEM	1	\$	92.00	-
TAIL GATE "HONDA" LOGO	1	\$	70.00	-
TAIL GATE CHROME TRIM	1	\$	420.00	X
TAIL GATE INNER MOULDING	1	\$	350.00	X
TAIL GATE LAMP LH	1	\$	480.00	X
TAIL GATE LAMP RH	1	\$	480.00	X
TAIL LAMP LH	1	\$	550.00	X
TAIL LAMP RH	1	\$ 460 cut	550.00	✓
REAR BUMPER	1	\$ 1150.20	1,390.00	-
REAR BUMPER CLIPS	10	\$	50.00	-
REAR BUMPER RH REFLECTOR PLATE	1	\$	75.00	X
REAR BUMPER LH REFLECTOR PLATE	1	\$	75.00	X
REAR BUMPER RH REFLECTOR	1	\$	187.00	X
REAR BUMPER LH REFLECTOR	1	\$	187.00	X
REAR BUMPER RH TOW COVER	1	\$	40.00	X
END PANEL CENTRE	1	\$	160.00	X

KKK Auto Consultants hence **potify**
the **Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Accepted for publication: _____
Signature: _____
Date: _____

Mbm wheelpower pte ltd
160 SIN MING DRIVE
#06-02
SIN MING AUTOCITY
t 62628888 f 64525333
ation Number : 200204110W

END PANEL LH
END PANEL RH
END PANEL TOP GARNISH

1	\$	n	650.00	x
1	\$	n	160.00	x
1	\$	sn	180.00	x
Total: \$			8,348.00	
LESS 20% \$			(1,669.60)	
Parts Total: \$			6,678.40	

SPECIAL NETT

BODY SEALANT
REVERSE SENSORS
WINDSCREEN SEALANT

1	\$	na	80.00	x
1 SET	\$	na	400.00	✓
1	\$	na	80.00	

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO
KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.
TO REMOVE AND RE-FIT REAR WINDSCREEN
TO DISMANTLE & TRANSFER TAIL GATE FITTINGS & MECHANISM TO NEW
TAILGATE / FACILITATE REPAIR
TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS
TO REMOVE & REPLACE BUMPER SENSORS
TO CHECK & RECONNECT ALL NECESSARY WIRING
TO SPRAY PAINT ON THE AFFECTED AREAS

	\$	50d	1,200.00	
	\$	12d	150.00	
	\$	6d	80.00	
	\$	6d	150.00	
	\$		40.00	✓
	\$	2d	80.00	
	\$	56d	600.00	
Total: \$			9,538.40	
7% GST: \$			667.69	
Grand Total: \$			10,206.09	