

mbm wheelpower

Our Ref: SMA9134D

CC

Fax

Date:	6/4/2020
From:	Eryx
Fax:	64525333
Contact:	93288668
Make / Model:	HONDA SHUTTLE HYBRID 1.5
Chassis No.:	GP71213372
Engine No.:	LEB6556249
Year of Make:	2018
Accident Date:	3 April 2020

ESTIMATE FOR VEHICLE NO. : SMA9134D

DESCRIPTION	QTY		List Price
REAR WINDSCREEN MOULDING	1	\$	166.00 ✓
TAIL GATE	1	\$	1,432.00 ✓
TAIL GATE WEATHERSTRIP	1	\$	220.00 ✓
TAIL GATE LOCK	1	\$	308.00 X
TAIL GATE "SHUTTLE" EMBLEM	1	\$	76.00 ✓
TAIL GATE "HYBRID" EMBLEM	1	\$	92.00 ✓
TAIL GATE "HONDA" LOGO	1	\$	70.00 ✓
TAIL GATE CHROME TRIM	1	\$	420.00 X
TAIL GATE INNER MOULDING	1	\$	350.00 X
TAIL GATE LAMP LH	1	\$	480.00 ✓
TAIL GATE LAMP RH	1	\$	480.00 X
TAIL LAMP LH	1	\$	550.00 X
TAIL LAMP RH	1	\$	550.00 X
REAR BUMPER	1	\$	1,390.00 ✓
REAR BUMPER CLIPS	10	\$	50.00 ✓
REAR BUMPER RH REFLECTOR PLATE	1	\$	75.00 X
REAR BUMPER LH REFLECTOR PLATE	1	\$	75.00 X
REAR BUMPER RH REFLECTOR	1	\$	187.00 X
REAR BUMPER LH REFLECTOR	1	\$	187.00 X
REAR BUMPER RH TOW COVER	1	\$	40.00 X
END PANEL CENTRE	1	\$	160.00 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

LKK Auto Consultants hence **potify**
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledgement: Repairer
Signal:
Date:

Mbm wheelpower pte ltd
160 SIN MING DRIVE
#06-02
SIN MING AUTOCITY
t 62628888 f 64525333
ation Number : 200204110W

END PANEL RH
END PANEL TOP GARNISH

1	\$	180.00	?
Total: \$		8,348.00	
LESS 20% \$		(1,669.60)	
Parts Total: \$		6,678.40	

SPECIAL NETT

BODY SEALANT	1	\$		80.00	?
REVERSE SENSORS	1 SET	\$	<i>nd</i>	<i>320ln</i> 400.00	✓
WINDSCREEN SEALANT	1	\$	<i>nd</i>	<i>40ln</i> 80.00	

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.	\$	1,200.00	?
TO REMOVE AND RE-FIT REAR WINDSCREEN	\$	<i>120l</i> 150.00	
TO DISMANTLE & TRANSFER TAIL GATE FITTINGS & MECHANISM TO NEW TAILGATE / FACILITATE REPAIR	\$	<i>60l</i> 80.00	
TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS	\$	<i>60l</i> 150.00	
TO REMOVE & REPLACE BUMPER SENSORS	\$		40.00 ✓
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	<i>20l</i> 80.00	
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	<i>560l</i> 600.00	
Total: \$		9,538.40	
7% GST: \$		667.69	
Grand Total: \$		10,206.09	