



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV No. AC2004963  
INV Date 12/08/2020  
Reference CC4/FCI20004926/Kba3q2  
Code FCI2



#### PROFESSIONAL SERVICE FEE

Vehicle No. GBH 4972C  
Insured Veh. SHB 2330D  
Claim No. D20001764MFSH  
Policy No. D-20094921MFSH  
Accident Date 01/04/2020  
Inspection Date 03/04/2020

Description	Total
Third Party Express Settlement	350.00
<b>Subtotal</b>	<b>350.00</b>
<b>GST (7%)</b>	<b>24.50</b>
<b>Grand Total</b>	<b>374.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CC4/FCI20004926/Kba3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 12-08-2020		
		Code : FCI2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHB 2330D	Veh. Inspected	GBH 4972C	
Policy No.	D-20094921MFSH	Coverage (\$)	0.00	
Claim No.	D20001764MFSH	Excess (\$)	0.00	
Assign From	RACHEL WU	Assign Date	03/04/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	ISUZU NH	c.c	1898	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JAANHR87EJ7100107	Colour	WHITE	
Odometer	91938	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195 R15X8	MICHELIN	8 mm	
L/H Front Tyre	195 R15X8	MICHELIN	8 mm	
R/H Rear Tyre	155 R13X8 (D)	CONDOR	7/7 mm	
L/H Rear Tyre	155 R13X8 (D)	CONDOR	7/7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	01/04/2020	Inspection Date	03/04/2020	
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 Sector C SINGAPORE 575643.			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>2 Working Days</b>		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 4972C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER (DENTED)	NOT CONSISTENT WITH THE IMPACT	377.00	-
1	FRONT BUMPER BRACKET RH	TO REPAIR SEE LABOUR	92.00	-
1	CORNER LAMP RH	SERVICEABLE	84.00	-
1	STEP BOARD RH	SERVICEABLE	128.00	-
1	DIESEL TANK	DENTED	651.10	651.10
1	DIESEL TANK BRACKET	TO REPAIR SEE LABOUR	63.00	-
1	REAR RH MUDGUARD	BENT	185.00	185.00
	LESS 15% DISCOUNT		-237.02	-125.41
			1,343.08	710.69
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT DOOR BODY LETTERING (SN)	NOT NECESSARY	35.00	-
1	FRONT DOOR STICKER (SN)	NOT NECESSARY	38.00	-
			73.00	-
	<b><u>LABOUR</u></b>			
	TO REMOVE AND INSTALL OF PETROL TANK .		150.00	60.00
	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ACCIDENT PARTS.INCLUSIVE OF THE FRONT BUMPER BRACKET RH AND DIESEL TANK BRACKET .		400.00	100.00
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		600.00	120.00
	TOWING CHARGE.	NOT NECESSARY	120.00	-
			1,270.00	280.00
	<b>GRAND TOTAL</b>		<b>2,686.08</b>	<b>990.69</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>990.69</b>

Report Ref No. CC4/FCI20004926/Kba3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBH 4972C

INSPECTION







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBH 4972C

RE-INSPECTION

