

12/03/2017

ASS. REC. BY:

REF: CS3 / MSG 20003606 / Etf3/

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): Chhia Hui Rui

of MSG

Date/Time: 4.3.2020 17:20 p.m.

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: YQ 1030X

Insured: YP 1125 L

at Workshop m/s Carport Auto Service

Tel: 62685390

of B1K 3 Pioneer Road North #101-X

Policy No: 100293489

Claim No: 239838

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 2.3.2020

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 5/3/2020 11:30 a.m.

Person Contacted: Ah ong

Vehicle: IN / OUT

Date/Time	Action/Instruction (X) Estimate
	YQ 1030X - X
	YP 1125 L - NA / NC 18002434 / 13 DOA - 06/02/2013
	Submit PRS report.

Birajur Steve


REF: MS14

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP-RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Velt: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: YQ 1030X Yr Regn: 24/6/19
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: ISUZU NPR85 C.C. 2999
 Colour: White AC: Insured / Std / NI / NA
 Sp. Reading: 35/99 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: JAANPR85HJ7100659
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Locked / Burnt or
 Brake: In order / Jammed / Locked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/85R16 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Hankook

Front		Rear	
R/Bal. 5	mm	R/Bal. 5	mm
L/Bal. 5	mm	L/Bal. 5	mm
D.O.A. 2/3/20		D.O.A. 5/3/20	

Survey held at Car Port Auto

Des. of Damages (Frt) / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV-80K PRS Repair (4K-5K)
 5 days

RECEIVED 17 MAR 2020

Date/Time, File Pass to?

1) 13/3/2020

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

PRS

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$
☐ Interview (\$
☐ Tech Insp (\$
☐ Weekend (\$

Survey Fee: 120

Transportation:

5 + RS. 51

Break

Others

TOTAL

151