

ASS. REC. BY:

Ram

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 8133L Yr Regn: 19/05/201

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai 140 c.c 1685Colour: blue A/C: Insured / Std / NI / NASp. Reading 671962 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHLBA1UMGU089752

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Han Kook

Front

Rear

R/Bal. 6 mm R/Bal. 7 mmL/Bal. 6 mm L/Bal. 7 mmD.O.A. 1/04/2020 D.O.I. 3/4/2020Survey held at Compo. id. d. g. (Loyang)Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?



Prel. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Report Format: _____

Lump Sum / LPH: (\$)

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:
CTPL

EQ Insurance Company Ltd (HQ)

Singapore

LKe

EQ 1A

PARTICULARS OF CLAIM

Claim Type: THIRD PARTY
Policy No:
Vehicle Reg. No.: SHC8133L
Party At Fault: UNKNOWN

Ref. No:
Date of Loss: 01/04/2020
Driveable?

Make/Model: HYUNDAI I40, 1.7 D CRDI (A)
Vehicle Colour: BLUE
Engine No: D4FDFU609194
Odometer: 0 KM

Vehicle Reg. Date: 19/05/2016
Chassis No: KMHLB41UMGU089752

Paint Type:
List Item Discount: 20.00 %
Total Loss? NO
Est. Duration of Repair (day) 3

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS

	Amount
Parts	1,298.98
Miscellaneous Items	0.00
Labour	680.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (S\$)	1,978.98
+ GST 7.00% (S\$)	138.53
Nett Amount (S\$)	2,117.51

This claim is handled by: LIM KWOK ENG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 02 Apr 2020)**Parts:** 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHC8133L/02/04/2020 16:54**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER COVER <i>cut / DEF</i>	20.00	0.00	*1,106.00 FL
2	10		*REAR BUMPER CLIPS <i>rec</i>	20.00	0.00	*22.00 FL
3	1		*REAR BUMPER UNDER COVER <i>sc</i>	20.00	0.00	*228.00 FL
4	1		*REAR BUMPER SIDE BRACKET LH <i>xw</i>	20.00	0.00	*35.60 FL
5	1		*REAR BUMPER REVERSE SENSOR <i>?</i>	0.00	0.00	*135.70 F
6	1		*REAR BUMPER RUBBER MAT <i>rec</i>	0.00	0.00	*50.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	1,577.30
- List Item Discount on L Items (\$\$)	278.32
Total Parts (\$\$)	1,298.98

ComfortDelGro Engineering Pte Ltd/SHC8133L/02/04/2020 16:54. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	350.00 \$
2	SPRAY PAINTING CHARGE	New	250.00 \$
3	REMOVE/REFIX REVERSE SENSOR	New	80.00 \$
Gross Labour Cost (S\$)			680.00

ComfortDelGro Engineering Pte Ltd/SHC8133L/02/04/2020 16:54. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

acknowledged by Repairer

Signature:

Date:

Ram (LKK)
3/4/2020 1515
Ram@lkkauto.com
88622778
ad + repair list
LS
Super day