



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

SUPPLEMENTARY

6/4/2020

SLD4477T

HONDA VEZEL

RU1-1112217

No.	Description	Unit	Unit Price	Amount
	PARTS REPLACEMENT			
1	REAR TAILGATE INNER TRIM BOARD	1	\$ 157.00	\$ 157.00
	/ cut			/
				\$ 157.00
			LESS 20%	\$ 31.40
				\$ 125.60
	S / NETT			/
1	REAR TAILGATE INNER TRIM BOARD CLIPS	1	\$ 50.00	\$ 50.00
	/ Nec			30
				\$ 50.00
	PARTS REPLACEMENT AMOUNT :			\$ 175.60

$$P = 1,701.12$$

$$S = 125.60$$

$$N = 100$$

$$L = 1,780$$

$$3,306.72$$

$$- 209,$$

$$2,645.38$$

4 S

\$ 2,650

4 days.