

ASS REQ BY: PRAN

REF:

8886

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ CD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MVTo Inspect Vehicle No: XE 549SLat Workshop m/s BORNEO MOTORof 2, Pandan CassiaInsured: CTI

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: 1500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 145K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs _____ days Res.: Yes or No

Lum Sum _____ % 3 Val.: Yes or No

CA / ☒ REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: XE 549SL Yr Equip: 2020 Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

☒ Truck / Trailer orMake: HINO FS1EKN 28TON 6X4 MT 12913Colour: WHITE A/C: Insured / Std / NI / NA

Sp Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHD FS1EKN XXX10048Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: ☒ Nil / S/Rim / STD A/Rim orTyre Size: F: 295/80R22.5R: 4"☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 21/03/2020Survey held at BORNEO MOTOR

Rear

R/Bal. 8/8 mmL/Bal. 8/8 mmD.O.A. 06/04/2020

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT O/S

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time _____ Action / Instruction _____

Disposal Fee Paid to?

1)

Disposal Fee Paid to?

2)

Rep. Form:

Lump Sum / Rep. Fee:

☐

Prel. Report

☐

Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp. (\$)

☐

Interview (\$)

☐

Tech. Insp. (\$)

☐

Travel Exp. (\$)

Survey Fee:

Transportation

GPS

Photos

Notes

Total

TOYOTA

Reg No : 196700086Z
Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:

www.toyota.com.sg

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1188

Account Detail

Account No

S1000003 / ICCI1

Document No

0

Document Date

03/04/2020

Customer Detail

M/S Double-Trans Pte Ltd
4 Sungei Kadut Street 2
Sungei Kadut Industrial Estate
Singapore 729226

Work: 64812518

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909
Attn: Motor Claims Dept

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	KAS	FS1EKND	23/01/2020	XE5495L	0	54615	72/OD/XE5495L
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:DMCVSNA00005742000 ACC DATE:21.03.2020 TOW IN:31.03.2020 EXCESS: DATE-IN:03.04.2020 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				50 100.00
2	S	BP-SUBLET SUPPLY JOINT PANEL SEALANT				300 400.00
3	S	BP-SUBLET REPLACE AND REFOCUS HEADLAMP				149.60
4	S	BP-SUBLET REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR				880.00
5	S	BP-SUBLET R/I DASHBOARD ASSY TO FAC REPAIR				1760.00
6	S	BP-SUBLET REPLACE FRONT WINDSCREEN GLASS				880.00
7	S	BP-SUBLET CHECK WIRING AND CONDUCT WATER TEST				149.60
8	S	BP-SUBLET R/I AC CON BLOWER ASSY TO FAC REPAIR & R EGAS				880.00
9	S	BP-SUBLET R/I WIRE HARNESS ASSY TO FAC REPAIR				880.00
10	S	BP-SUBLET R/I BRAKE BOOSTER SYSTEM TO FAC REPAIR				880.00
11	S	BP-SUBLET REMOVE AND TRANSFER DOOR COMPONENT ONTO NEW DOOR				1760.00
12	S	BP-SUBLET REPLACE STEERING GEAR ASSY				1760.00
13	S	BP-SUBLET R/I ROOF LINING TO FAC REPAIR				

Repair
Hp 90010068
14 days
06/04/2020
@ 1645
EXCESS: 1500
Reset
Res before paint

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

Let Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

Acknowledged by Repairer

DATE 03/04/2020
TIME 19:09

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO XE5495L

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape

CUSTOMER

Hi, kindly arrange for survey. Thank you!! 62247175

4234442

4234442

TOYOTA

Borneo Motors (Singapore) Pte Ltd

Online Service Booking

www.toyota.com.sg

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1188

Reg No : 1967000862

T Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909
Attn: Motor Claims Dept

Account No

S1000003/ICCI1

Document No

0

Document Date

03/04/2020

Customer Detail

M/S Double-Trans Pte Ltd
4 Sungai Kadut Street 2
Sungei Kadut Industrial Estate
Singapore 729226

Works: 64812518

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	KAS	FS1EKWD	23/01/2020	XE5495L	0	54615	72/OD/XE5495L
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JHD5F1EKWXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
14	S	BP-SUBLET REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS				4400 6160.00
15	S	BP-SUBLET RESPRAY ACC AFFECTED AREAS				3300 9620.00
16	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00
17	Z	BP-BKT SUPPLY IU BRACKET				26.00
18	Z	TW TOWING CHARGES				150.00
19	S	BP-INTERIOR REMOVE INTERIOR SHATTED GLASS				220.00
20	1	HS4716-03311 VALVE ASSY, AIR BRAKE	1.00	1186.10		1186.10
21	2	H47307-E0351 CONNECTOR SUB-ASSY,	1.00	37.30		37.30
22	3	H47307-E0310 CONNECTOR SUB-ASSY,	1.00	40.50		40.50
23	4	H81110-E0682 HEADLAMP ASSY	1.00	750.30		750.30
24	5	H81150-E0682 HEADLAMP ASSY, LH	1.00	750.30		750.30
25	6	HS5563-12181 HOUSING, INSTR CLUSTER	1.00	1193.60		1193.60
26	7	H55413-E0041 PANEL, INSTR CLUSTER	1.00	515.00		515.00
27	8	H55412-E0030 PANEL, INSTRUMENT CL	1.00	355.40		355.40
28	9	HS5542-E0030 PANEL, INSTR CLUSTER	1.00	320.00		320.00
29	0	HS5541-E0020 PANEL, INSTR CLUSTER	1.00	207.80		207.80
30	1	H83800-E1170 METER ASSY, COMBINATION	1.00	2224.60		2224.60
31	2	HS8501-E0020 LINK SUB-ASSY, FR WI	1.00	157.90		157.90

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4234443

4234443

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO XE5495L

DATE 03/04/2020
TIME 19:09

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape

CUSTOMER

TOYOTA

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:

www.toyota.com.sg

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1188

Reg No : 196700086Z

Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail		Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICC11	M/S Double-Trans Pte Ltd 4 Sungai Kadut Street 2 Sungai Kadut Industrial Estate Singapore 729226
		Document No	Work: 64812518
		0	
		Document Date	
		03/04/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	KAS	FS1EKND	23/01/2020	XE5495L	0	54615	72/OD/XE5495L
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JKEFS1EKXXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
32	3	HS8502-E0030 LINK SUB-ASSY, FR WI ?	1.00	205.80		205.80
33	4	H85210-E0100 ARM & BLADE ASSY, FR bro	1.00	399.20		399.20
34	5	H85070-E0100 MOTOR & BRACKET ASSY ?	1.00	664.90		664.90
35	6	H44110-E0050 GEAR ASSY, POWER STE ?	1.00	8347.90		8347.90
36	7	HS1661-02030 TANK ASSY, RESERVE ?	1.00	429.10		429.10
37	8	H86301-E0020 POLE SUB-ASSY, ANTEN ?	1.00	44.50		44.50
38	9	H81240-E0090 LAMP ASSY, DOME X	1.00	49.80		49.80
39	0	H86300-E0020 ANTENNA ?	1.00	79.70		79.70
40	1	HS8630-11250 FEEDER SUB ASSY, ANTE ?	1.00	45.00		45.00
41	2	HS8135-01051 LAMP ASSY, STEP ?	1.00	29.30		29.30
42	3	H81510-E0091 LAMP ASSY, FR TURN S bro	1.00	156.40		156.40
43	4	H85301-E0030 INLET SUB-ASSY, WASH ?	1.00	101.90		101.90
44	5	H87915-E0041 COVER, OUTER MIRROR, X	1.00	18.50		18.50
45	6	H87945-E0011 COVER, OUTER MIRROR, X	1.00	18.50		18.50
46	7	HS87A0-E0020 MOTER ASSY, POWER ST X	1.00	755.30		755.30
47	8	H81730-E0081 LAMP ASSY, SIDE TURN X	1.00	93.20		93.20
48	9	H81239-E0020 SWITCH, COURTESY X	1.00	23.80		23.80
49	0	H74657-E0010 BRACKET, HAND RAIL ?	1.00	17.80		17.80
50	1	H74656-E0020 COVER, HAND RAIL BAR ?	1.00	10.80		10.80
51	2	HS7420-61780 GRIP SUB ASSY, INSIDE ?	1.00	258.80		258.80

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 03/04/2020
TIME 19:09

VEHICLE NO XE5495L

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape

4234444

4234444

TOYOTA

Reg No : 196700086Z
 Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking
 www.toyota.com.sg
 Toyota Bodycare Centre
 No. 2 Pandan Crescent
 Singapore 128462
 Tel no.: 6631 1188

ESTIMATE

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226
	Document No	Work: 64812518
	Document Date	
	03/04/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	KAS	FS1EKND	23/01/2020	XE5495L	0	54615	72/OD/XE5495L
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JHDFS1EKXXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00 --/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
52	3	H74620-E0010 GRIP ASSY, ASSIST, RR RH X	1.00	60.00		60.00
53	4	H74734-E0020 COVER, HAND GRIP, NO X	1.00	5.50		5.50
54	5	H74733-E0020 COVER, HAND GRIP, NO X	1.00	23.30		23.30
55	6	H74603-E0030 GRIP SUB-ASSY, ASSIS ?	1.00	156.40		156.40
56	7	H74604-E0030 GRIP SUB-ASSY, INSTR ?	1.00	139.20		139.20
57	8	H62311-E0012 WEATHERSTRIP, FR DOO re	1.00	292.30		292.30
58	9	H62312-E0012 WEATHERSTRIP, FR DOO X	1.00	292.30		292.30
59	0	H62210-E0040 GARNISH ASSY, FR PILLAR, RH ?	1.00	98.20		98.20
60	1	H62511-E0091 BOARD, QUARTER TRIM, ?	1.00	236.80		236.80
61	2	HSZ950-39335 RETAINER re	1.00	32.00		32.00
62	3	H73135-E0050 COVER, SHOULDER BELT X	1.00	17.80		17.80
63	4	H73135-E0040 COVER, SHOULDER BELT X	1.00	17.80		17.80
64	5	H56121-E0031 MOULDING re	1.00	457.10		457.10
65	6	H56111-E0120 WINDSHIELD bo	1.00	2356.40		2356.40
66	7	T21000-20 SIKA 182010 SIKA TACK GO! (BLA re	2.00	108.00		216.00
67	8	T21000-22 SIKA 207- G+P ADHESIVE PRIMER re	2.00	200.00		400.00
68	9	HS8794-E0020 BRACKET, OUTER MIRRO re	1.00	43.00		43.00
69	0	H87915-E0030 COVER, OUTER MIRROR, com	1.00	12.80		12.80
70	1	HS8792-E0010 BRACKET, OUTER MIRRO re	1.00	30.30		30.30
71	2	H87093-E0140 STAY SUB-ASSY, OUT R H	1.00	333.70		333.70

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4234445

4234445

TO SECURITY GUARD

DATE 03/04/2020
 TIME 19:09

PLEASE ALLOW THE UNDERMENTIONED
 VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO XE5495L

SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape

CUSTOMER

TOYOTA

Reg No : 196700086Z
 Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota Mf account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking
 www.toyota.com.sg
 Toyota Bodycare Centre
 No. 2 Pandan Crescent
 Singapore 128462
 Tel no. 6531 1188

Account Detail

China Taiping Insurance (S) Pte Ltd
 3 Anson Road
 #16-00 Springleaf Tower
 Singapore 079909
 Attn: Motor Claims Dept

Account No.

S1000003 / ICC11

Document No.

0

Document Date

03/04/2020

Customer Detail

M/S Double-Trans Pte Ltd
 4 Sungai Kadut Street 2
 Sungai Kadut Industrial Estate
 Singapore 729226

Works: 64812510

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	KAS	FS1EKND	23/01/2020	XE5495L	0	54615	72/OD/XE5495L

Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On
JHDFS1EKNNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
72	3	H87919-E0010 BRACKET, OUTER MIRROR	1.00	45.50		45.50
73	4	H87093-E0030 STAY SUB-ASSY, OUT R	1.00	96.70		96.70
74	5	H87910-E0071 MIRROR ASSY, OUTER R	1.00	135.70		135.70
75	6	H75315-EW040 ORNAMENT, RADIATOR G	1.00	276.30		276.30
76	7	H75338-E0030 ORNAMENT, HOOD, LWR	1.00	185.10		185.10
77	8	H75425-E0580 ORNAMENT, FR DOOR, R	2.00	239.80		479.60
78	9	H75353-E0160 ORNAMENT, FR FENDER,	2.00	113.70		227.40
79	0	H53814-E0460 EXTENSION, FR FENDER	1.00	648.00		648.00
80	1	HS5571-41010 PANEL, FR CORNER, LWR	1.00	14.50		14.50
81	2	H53804-E0010 REINFORCE SUB-ASSY,	1.00	261.80		261.80
82	3	H55712-E0390 PANEL, COWL TOP, OUT	1.00	677.60		677.60
83	4	H53813-E0650 EXTENSION, FR FENDER	1.00	630.40		630.40
84	5	HS2950-39050 RETAINER	1.00	1.40		1.40
85	6	H53803-E0010 REINFORCE SUB-ASSY,	1.00	261.80		261.80
86	7	H53601-E0010 LEVER SUB-ASSY, HOOD	1.00	33.00		33.00
87	8	HS8741-51680 CABLE, CONTROL	1.00	103.40		103.40
88	9	HS5339-01010 STRIKER ASSY, HOOD P	2.00	17.30		34.60
89	0	HS7918-01331 LOCK ASSY, LID	2.00	90.70		181.40
90	1	HS7918-21010 HANDLE, LID LOCK	2.00	24.00		48.00
91	2	H53540-E0010 LEVER ASSY, AUXILIAR	1.00	70.20		70.20

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4234446

SECURITY GUARD

4234446

PLEASE ALLOW THE UNDERMENTIONED
 VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 03/04/2020
 TIME 19:09

VEHICLE NO XE5495L

SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape

TOYOTA

No : 196700086Z
No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
Line Taiping Insurance (S) Pte Ltd Anson Road 6-00 Springleaf Tower Singapore 079909 Motor Claims Dept	S1000003 / ICCI1	M/S Double-Trans Pte Ltd 4 Sungai Kadut Street 2 Sungai Kadut Industrial Estate Singapore 729226
	Document No	Work: 64812518
	0	
	Document Date	
	03/04/2020	

Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
KAS	FS1EKND	23/01/2020	XB5495L	0	54615	72/OD/XB5495L
Assis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On	
FS1EKXXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/---- 0.00

Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
3	HS7639-01051 STAY ASSY, DUMPER ?	1.00	151.60		151.60
4	HS5337-81400 MEMBER, HOOD ?	1.00	50.50		50.50
5	HS7682-11310 WEATHERSTRIP, FR CORN ?	1.00	82.70		82.70
6	HS7686-11010 SEAL, FR PANEL, LWR RH <i>ca</i>	1.00	103.40		103.40
7	HS7426-21140 CAP <i>ms</i>	1.00	9.80		9.80
8	HS5300-E0010 GRIP ASSY, FR PANEL, <i>ca</i>	1.00	298.00		298.00
9	HS7653-11460 EMBLEM <i>ca</i>	1.00	211.60		211.60
10	HS3111-E0130 GRILLE, RADIATOR <i>ca</i>	1.00	2121.70		2121.70
11	HSZ950-39069 RETAINER <i>ca</i>	20.00	1.10		22.00
12	HS7630-71010 REINFORCEMENT SUB AS ?	1.00	107.40		107.40
13	HSZ159-40001 SCREW, W/WASHER <i>ca</i>	5.00	1.80		9.00
14	HS7682-11300 WEATHERSTRIP, FR CORN ?	1.00	226.60		226.60
15	HS7681-11160 WEATHERSTRIP, FR CRNE ?	1.00	54.20		54.20
16	HS5246-E0010 SEAL, FR PANEL, LWR <i>ca</i>	1.00	99.90		99.90
17	HSZ950-39307 RETAINER <i>ca</i>	1.00	2.80		2.80
18	HS8727-42250 HOSE, DEF ?	1.00	45.30		45.30
19	HS5990-E0030 NOZZLE ASSY, DEFROST ?	1.00	267.30		267.30
20	HS8727-42240 HOSE, DEF ?	1.00	45.30		45.30
21	HS5530-31290 GUSSET SUB ASSY, INST ?	1.00	54.20		54.20
22	HS5531-31430 BRACKET, INSTR PANEL ?	1.00	14.50		14.50

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4234447

TO SECURITY GUARD

4234447

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 03/04/2020
TIME 19:09

VEHICLE NO XB5495L

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

TOYOTA

No : 1967000862
g No : MR-8500000-9

ad "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyota.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
Line Taiping Insurance (S) Pte Ltd Aneon Road 6-00 Springleaf Tower Singapore 079909 ctn: Motor Claims Dept	S1000003 / ICC11 Document No 0 Document Date 03/04/2020	M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226 Work: 64812518

Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
KAS	FS1EKND	23/01/2020	XE5495L	0	54615	72/OD/XE5495L
ssis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On	
FS1EKNDXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/---- 0.00

Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
3	HS5530-31330 GUSSET SUB ASSY, INST ?	1.00	41.30		41.30
4	H55535-E0010 COVER, SPEAKER HOLE, ?	1.00	54.20		54.20
5	HS8615-31150 COVER, SPEAKER ?	1.00	50.50		50.50
6	HS8724-31050 DUCT, HEATER TO FOOT ?	1.00	48.50		48.50
7	HS8724-21120 DUCT, HEATER TO FOOT ?	1.00	54.30		54.30
8	H55835-E0070 DUCT, HEATER TO REGI ?	1.00	253.30		253.30
9	H55843-E0020 DUCT, HEATER TO REGI ?	1.00	99.70		99.70
0	H55108-E0011 BRACE SUB-ASSY, PEDAL SUPPORT TO CC ?	1.00	532.30		532.30
1	HS5530-12091 PANEL SUB ASSY, INSTR ?	1.00	1240.80		1240.80
2	HSZ950-24048 CLIP	4.00	2.20		8.80
3	HSZ950-24049 CLIP	1.00	4.80		4.80
4	HSZ950-39183 RETAINER	4.00	8.80		35.20
5	H67831-E0010 COVER, FR DOOR SERVI ?	1.00	7.80		7.80
6	H69810-E0051 REGULATOR ASSY, DOOR ?	1.00	821.20		821.20
7	HS6946-01150 STRIKER ASSY, DOOR, m	1.00	29.50		29.50
8	H69310-E0032 LOCK ASSY, FR DOOR, bf	1.00	228.10		228.10
9	HS6942-11620 LINK, DOOR LOCK X	1.00	14.80		14.80
0	H69210-E0030 HANDLE ASSY, FR DOOR X	1.00	115.40		115.40
1	HS6911-E0020 BRACKET, INSIDE HAND X	1.00	17.30		17.30
2	H69205-E0010 HANDLE SUB-ASSY, FR X	1.00	55.00		55.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4234448

TO SECURITY GUARD

4234448

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 03/04/2020
TIME 19:09

VEHICLE NO XE5495L

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape

TOYOTA

No : 196700086Z
No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking
www.toyota.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
na Taiping Insurance (S) Pte Ltd Anson Road 5-00 Springleaf Tower Singapore 079909 Motor Claims Dept	S1000003 / ICCI1	M/S Double-Trans Pte Ltd 4 Sungai Kadut Street 2 Sungai Kadut Industrial Estate Singapore 729226
	Document No	Work: 64812518
	0	
	Document Date	
	03/04/2020	

Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
KAS	FS1EKND	23/01/2020	XE5495L	0	54615	72/OD/XE5495L
Sis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On	
S1EKXXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/---- 0.00

Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
3	HSZ950-39242 RETAINER X	5.00	4.00		20.00
4	HS6921-01091 LINK ASSY, DOOR CHECK	1.00	93.50		93.50
5	HSZ950-39242 RETAINER	1.00	4.00		4.00
6	H74630-E0020 GRIP ASSY, DOOR ASS	1.00	118.90		118.90
7	H74210-E0010 ARMREST ASSY, DOOR	1.00	47.50		47.50
8	H67605-E0150 PANEL SUB-ASSY, FR D	1.00	643.70		643.70
9	H74645-E0010 ESCUTCHEON, DOOR ASS	1.00	8.80		8.80
0	H74231-E0010 PANEL, FR DOOR ARMRE	1.00	125.40		125.40
1	H84810-E0070 SWITCH ASSY, POWER W	1.00	177.90		177.90
2	H74201-E0021 PANEL SUB-ASSY, FR A	1.00	75.20		75.20
3	H74103-E0020 DOOR SUB-ASSY, FR AS	1.00	111.20		111.20
4	H67605-E0150 PANEL SUB-ASSY, FR D	1.00	643.70		643.70
5	H68171-E0040 WEATHERSTRIP, DOOR G	1.00	152.90		152.90
6	HS6845-01632 GLASS ASSY, DOOR WIND	1.00	495.80		495.80
7	H67403-E0020 FRAME SUB-ASSY, FR D	1.00	46.80		46.80
8	H67875-E0010 WEATHERSTRIP, FR DOOR, NO.4 RH ?	1.00	81.00		81.00
9	HS6840-11240 OSCILLATOR-PROOF SUB	1.00	77.80		77.80
0	H67485-E0010 SEAL, RR DOOR DIVISI	1.00	27.30		27.30
1	H67861-E0010 WEATHERSTRIP, FR DOO	1.00	217.60		217.60
2	HS6801-E0040 GARNISH SUB-ASSY, DO	1.00	250.00		250.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4234449

TO SECURITY GUARD

4234449

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 03/04/2020
TIME 19:09

VEHICLE NO XE5495L

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

TOYOTA

Borneo Motors (Singapore) Pte Ltd

g No : 196700086Z
eg No : MR-8500000-9

ESTIMATE

Online Service Booking
www.toyota.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

load "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No S1000003/ICCI1	Customer Detail
China Taiping Insurance (S) Pte Ltd Aneon Road 16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	Document No 0	M/S Double-Trans Pte Ltd 4 Sungai Kadut Street 2 Sungai Kadut Industrial Estate Singapore 729226
	Document Date 03/04/2020	Works: 64812518

Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
KAS	FS1EKND	23/01/2020	XE5495L	0	54615	72/OD/XE5495L
assis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On	
FS1EKXXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/---- 0.00

Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
3	H67123-E0010 BRACKET, FR DOOR OUT ?	1.00	149.90		149.90
4	H53831-E0110 PANEL, FR FENDER SID de	1.00	521.00		521.00
5	HS5370-52460 BRACKET SUB ASSY, FR ?	1.00	142.90		142.90
6	HS530C-E0010 SUPPORT SUB-ASSY, ST ?	1.00	339.20		339.20
7	H53875-E0020 BRACKET, AIR DUCT CL ?	1.00	116.40		116.40
8	HS5370-51270 BRACKET SUB ASSY, FR ?	1.00	57.70		57.70
9	H76911-E0010 MUDGUARD, SIDE, RH su	1.00	240.10		240.10
9	HSZ950-39274 RETAINER m	10.00	1.70		17.00
0	H76621-E0041 MUDGUARD, FR FENDER, ?	1.00	81.20		81.20
1	HS5835-34810 SPLASHBOARD, SIDE ?	1.00	141.70		141.70
2	H53738-E0120 PLATE, FR APRON TO C ?	1.00	139.40		139.40
3	HS5830-81080 SPLASHBOARD SUB ASSY ?	1.00	213.60		213.60
4	H51772-E0020 PLATE, STEP, LH ?	1.00	257.80		257.80
5	H51771-E0050 BRACKET, TILT CAB ST BX	1.00	285.00		285.00
6	HS5832-11090 COVER, STEP LWR, RH ?	1.00	135.40		135.40
7	H57035-E0010 REINFORCEMENT SUB-AS ?	1.00	355.40		355.40
8	HS5703-E0010 SUPPORT SUB-ASSY, FR ?	1.00	322.00		322.00
9	HS5571-51010 STAY, FR CORNER PANEL ?	1.00	19.00		19.00
0	H51773-E0140 COVER, STEP PLATE, R ?	1.00	332.00		332.00
1	HSZ950-39187 RETAINER ?	3.00	2.10		6.30

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4234450

4234450

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 03/04/2020
TIME 19:09

VEHICLE NO XE5495L

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

TOYOTA

Borneo Motors (Singapore) Pte Ltd

Reg No : 196700086Z
ST Reg No : MR-8500000-9

ESTIMATE

Online Service Booking:
www.toyota.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail		Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Aneon Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	M/S Double-Trans Pte Ltd 4 Sungai Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226
		Document No	
		0	
		Document Date	
		03/04/2020	Work: 64812518

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	KAS	FS1EKND	23/01/2020	XE5495L	0	54615	72/OD/XE5495L
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JHD FS1EKNDXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
172	3	HS2950-39347 RETAINER ?	4.00	3.30		13.20
173	4	H61453-E0130 COVER, FR STEP, RH <i>3 see</i>	1.00	410.60		410.60
174	5	HS2950-39347 RETAINER <i>m</i>	1.00	3.30		3.30
175	6	H67913-E0020 PLATE, DOOR SCUFF, R <i>ca</i>	1.00	52.50		52.50
176	7	H61415-E0011 EXTENSION, ROCKER, O ?	1.00	260.50		260.50
177	8	H61135-E0030 REINFORCEMENT, FR BODY PILLAR, UPR ?	1.00	80.50		80.50
178	9	H61108-E0012 REINFORCEMENT SUB-ASSY, FR PLR, LWR ?	1.00	239.30		239.30
179	0	H61131-E0120 PILLAR, FR BODY, UPR ?	1.00	603.40		603.40
180	1	H61611-E0030 PANEL, QUARTER, RH ?	1.00	1046.30		1046.30
181	2	H65621-E0010 PANEL, SIDE GATE ?	1.00	107.40		107.40
182	3	H61106-E0021 PILLAR SUB-ASSY, FR, RH ?	1.00	260.50		260.50
183	4	H67001-E0380 PANEL SUB-ASSY, FR DOOR, RH <i>due</i>	1.00	2875.20		2875.20
184	5	HS6927-01310 HINGE ASSY, DOOR, <i>bt</i>	1.00	189.90		189.90
185	6	HS6927-01310 HINGE ASSY, DOOR, <i>bt</i>	1.00	189.90		189.90
186	7	H55701-E0040 PANEL SUB-ASSY, COWL ?	1.00	1130.70		1130.70
187	8	H52211-E0010 CUSHION, BODY MOUNT ?	1.00	8.80		8.80
188	9	HS6114-51010 GUSSET, FR BODY PILL ?	1.00	57.50		57.50
189	0	HS6118-11010 BRACKET, INSTRUMENT ?	1.00	8.80		8.80
190	1	H61235-E0030 BRACKET, ASSIST GRIP ?	1.00	31.50		31.50
191	2	H61163-E0031 PILLAR, FR BODY, LWR INNER RH ?	1.00	316.20		316.20

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4234451

TO SECURITY GUARD

4234451

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 03/04/2020
TIME 19:09

VEHICLE NO XE5495L

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

TOYOTA

Page 10 of 12
Borneo Motors (Singapore) Pte Ltd

Online Service Booking:

www.toyota.com.sg

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1188

ESTIMATE

Reg No : 196700086Z
Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail		Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226
		Document No	
		0	
		Document Date	Work: 64812518
		03/04/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	KAS	FS1EKND	23/01/2020	XE5495L	0	54615	72/OD/XE5495L
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00 --/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
192	3	H55101-E0100 PANEL SUB-ASSY, DASH ?	1.00	1970.30		1970.30
193	4	H55700-E0120 COWL bt	1.00	2385.90		2385.90
194	5	HS6114-61010 GUSSET, FR BODY PILL ?	1.00	57.50		57.50
195	6	HS6118-21010 BRACKET, INSTRUMENT ?	1.00	8.80		8.80
196	7	H61164-E0011 PILLAR, FR BODY, LWR ?	1.00	316.20		316.20
197	8	HS51QD-E0032 APRON, STEP, RH ?	1.00	146.20		146.20
198	9	HS51QH-E0130 MUDGUARD, STEP ?	1.00	47.50		47.50
199	0	HS7622-12050 HOLDER MUDGUARD ?	1.00	33.00		33.00
200	1	HS510U-E0140 SUPPORT SUB-ASSY, ST ?	1.00	721.30		721.30
201	2	HS5065-E0071 STAY SUB-ASSY, STEP, ?	1.00	155.40		155.40
202	3	HS5066-E0071 STAY SUB-ASSY, STEP, ?	1.00	155.40		155.40
203	4	HS510V-E0100 SUPPORT SUB-ASSY, ST ?	1.00	711.60		711.60
204	5	HS506J-E0121 LID SUB-ASSY, STEPO ?	1.00	71.00		71.00
205	6	HS51Q1-E0222 COVER, STEP, RH ?	1.00	384.70		384.70
206	7	H51771-E0050 BRACKET, TILT CAB ST ?	1.00	285.00		285.00
207	8	HS5107-72381 STAY SUB ASSY, STEP ?	1.00	94.70		94.70
208	9	H53102-E0060 GRILLE SUB-ASSY, RAD ?	1.00	1023.10		1023.10
209	0	HS5218-21010 REINFORCE, FR BUMPER ?	1.00	267.00		267.00
210	1	HS5219-81120 BRACKET, GRILLE ?	1.00	29.50		29.50
211	2	HS5110-E0121 MEMBER, ENGINE COVER ?	1.00	895.90		895.90

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4234452

TO SECURITY GUARD

4234452

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 03/04/2020
TIME 19:09

VEHICLE NO XE5495L

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

TOYOTA

Borneo Motors (Singapore) Pte Ltd

No : 196700086Z
Reg No : MR-8500000-9

ESTIMATE

Online Service Booking:
www.toyota.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1100

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail		Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	M/S Double-Trans Pte Ltd 4 Sungai Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226
		Document No	
		0	
		Document Date	Work: 64812518
		03/04/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	KAS	FS1EKND	23/01/2020	XE5495L	0	54615	72/OD/XE5495L
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
212	3	HS5052-E0160 STAY SUB-ASSY, FR UN ?	1.00	282.30		282.30
213	4	H52712-E0020 MOULDING, FR BUMPER A ✓	1.00	17.00		17.00
214	5	H52713-E0010 MOULDING, FR BUMPER X	1.00	17.00		17.00
215	6	HS5218-71100 GARNISH, BUMPER, RH ?	1.00	172.60		172.60
216	7	HS5218-81100 GARNISH, BUMPER, LH X	1.00	154.90		154.90
217	8	HS5218-81090 GARNISH, BUMPER, LH X	1.00	172.10		172.10
218	9	H53035-E0070 BRACKET SUB-ASSY, HE ?	1.00	202.60		202.60
219	0	HS8112-E0020 STAY, HEADLAMP, NO.2 ?	1.00	49.30		49.30
220	1	HS8116-E0010 STAY, HEADLAMP, NO.2 ?	1.00	49.30		49.30
221	2	H53036-E0050 BRACKET SUB-ASSY, HE ?	1.00	202.60		202.60
222	3	H52101-E0K21 BUMPER SUB-ASSY, FR bt	1.00	2265.00		2265.00
223	4	H52102-E0640 EXTENSION SUB-ASSY, FR BUMPER, RH bt	1.00	237.10		237.10
224	5	H52103-E0460 EXTENSION SUB-ASSY, FR BUMPER, LH X	1.00	237.10		237.10

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	88,525.00
	Please acknowledge receipt of vehicle	Parts 65,809.80	GST 7.00%	6,196.75
		Labour 456.00	Less	0.00
		Materials 22,259.20		
		Lubrication/Fluid 0.00		
		Others 0.00		
			Amount Due	94,721.75

PLEASE TEAR ALONG PERFORATED LINE

4234453

TO SECURITY GUARD

4234453

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 03/04/2020
TIME 19:09

VEHICLE NO XE5495L

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



YISHUN TOWING PTE LTD

Blk 4015 Ang Mo Kio Industrial Park 1, #01-502, Singapore 569631

Tel: 6458 8480 HP: 9628 8480 Fax: 6288 8480

Website: www.yishuntowing.com

Reg. No. 200106908W GST No. 200106908W

ms Borneo motor **WORK ORDER**

No. 307811

Order By:

AT

1830

D/T.

1500

Date:

31-3-20

車牌
Vehicle No.

XE 5495L

車型
Model

700 tipper

From:

459 Kadut St

To:

2 pandan over-

Remarks:

Accident.

Day/Night

Customer Signature & Company Stamp

Authorised Signature

Tow Truck No.:

XB 846A

All business transactions with Yishun Towing Pte Ltd are subject to its Standard Conditions in so far as these Conditions are applicable. Copies of these conditions may be obtained upon request. Note: Please see terms & conditions on the reverse side



Atty. viki

8612 3163

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1 Please report correctly the details of the accident to speed up the claims process.
- 2 This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3 Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation.
- 6 This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 23/03/2020 12:20
Date Of Accident 21/03/2020 07:10
Exact Location Of Accident SLE TWDS TPE B4 WOODLANDS AVE12 EXIT(LAMP POST544)
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number XE5495L
Insured/Policyholder
Name Of Registered Owner DOUBLE-TRANS PTE LTD
Co Reg No 1XXXXX888E
Email Address NOEMAIL
Mobile Phone No
Alternative Phone No OFFICE-86123163

Vehicle Particulars

Manufacturer HINO
Model FS1EKND28TON 6X4MT

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number DMCVSNA00005742000
Cover Note Number

Driver

Name of Driver MAYAVAN RAJENDIRAN
Passport No/FIN GXXXX640X
Date Of Birth 10/02/1983
Occupation OUTDOOR
Date Of Driving Pass 26/10/2016
Driving Experience 3 YEARS AND 4 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-98618830
Fax Number
Contact Number
Email Address NOEMAIL

Address 4 SUNGEI KADUT STREET 2
 Postcode 729226
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YP347U
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver BAI YONGBO
 NRIC/Passport Number GXXXXX905K
 Contact Number 62894933
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time:


20/03/2020
10.15 AM

Reporting Centre Personnel's Signature
Name: Teo Hong Eng
NRIC/FIN No.: S1100072/2

SKETCH PLAN

AXE 5495 L

B: YP347U



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident Date & Time : 21/03/2020 at 07.10 Am

Accident Location: SLE towards TPE, before Woodlands Ave 12 Exit
(Lamp Post 544).

On 21/03/2020 at 07.10 AM, I was driving my vehicle XE5495L along SLE towards TPE. I was at Lane 4
Vehicle B (YP3474) came out from Woodlands Ave 2 and change lane to my lane 4 and suddenly stop.
I try to avoid the accident, so I steer my steering to the left side but my vehicle front right side still hit onto the rear left side of Vehicle B (YP3474).
No one was injured in this accident.

☐ Reporting Only ☐ Own Damage ☐ Third Party ☐ Claim at other workshop (OD/TP)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

*** IMPORTANT NOTE:**

IMPORTANT NOTE:
You had been advised by the workshop that in the event that you wish to claim against your own policy (Own Damage Claim), there is a **FOURTEEN (14) days** clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.

Policyholder's Signature

Date & Time

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Date & Time: 23/03/2020 10.15.Am

Reporting Centre Personnel's Signature

Name: TEO HONG ENG

NRIC/FIN No.: 540007217

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	888E

Vehicle Details

Vehicle No.:	XE5495L
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Apr 2020
Vehicle Make:	HINO
Vehicle Model:	FS1EKND 28 TON 6X4 MT
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	E13CAT10536
Chassis No.:	JHDFS1EKNXXX10048
Maximum Power Output:	-
Open Market Value:	\$94,676.00
Original Registration Date:	23 Jan 2020
First Registration Date:	23 Jan 2020
Transfer Count:	0
Actual ARF Paid:	\$4,734.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	22 Jan 2030
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$12,519.00
COE Rebate Amount:	\$12,269.00
Total Rebate Amount:	\$12,269.00

The information contained herein is correct as at 03 Apr 2020

OK