

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Tan Kah Leong

Date: 07 Apr 2020

**Preliminary Advice**

Vehicle No	: XE5495L	Accident Date	: 21/03/2020
Make	: HINO FS1EKND	Policy No.	: DMCVSNA00005742000
Assignment Date	: 04/04/2020	Excess	: S\$1,500.00
Date of Inspection	: 06/04/2020	Est. Duration of Repair	: 14 days
Inspection At	: Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	88,525.00
Revised Amount	:S\$	34,921.00
Check Items (Estimated)	:S\$	45,151.30
Total	:S\$	80,072.30

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	145,000.00
COE / PARF Rebate	:S\$	12,269.00
Salvage Value	:S\$	
Margin for Repair	:S\$	132,731.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :