

TOYOTA

No : 1967000862
Reg No : MR-8500000-9

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:

www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

ESTIMATE

Load "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail

Account No

S1000003 / ICCI1

Document No

0

Document Date

03/04/2020

Customer Detail

M/S Double-Trans Pte Ltd
4 Sungei Kadut Street 2
Sungei Kadut Industrial Estate
Singapore 729226

Work: 64812518

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	KAS	FS1EKND	23/01/2020	XE5495L	0	54615	72/OD/XE5495L
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.: DMCVSNA00005742000 ACC DATE: 21.03.2020 TOW IN: 31.03.2020 EXCESS: DATE-IN: 03.04.2020 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				100.00
2	S	BP-SUBLET SUPPLY JOINT PANEL SEALANT				400.00
3	S	BP-SUBLET REPLACE AND REFOCUS HEADLAMP				149.60
4	S	BP-SUBLET REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR				880.00
5	S	BP-SUBLET R/I DASHBOARD ASSY TO FAC REPAIR				1760.00
6	S	BP-SUBLET REPLACE FRONT WINDSCREEN GLASS				880.00
7	S	BP-SUBLET CHECK WIRING AND CONDUCT WATER TEST				149.60
8	S	BP-SUBLET R/I AC CON BLOWER ASSY TO FAC REPAIR & R EGAS				880.00
9	S	BP-SUBLET R/I WIRE HARNESS ASSY TO FAC REPAIR				880.00
10	S	BP-SUBLET R/I BRAKE BOOSTER SYSTEM TO FAC REPAIR				880.00
11	S	BP-SUBLET REMOVE AND TRANSFER DOOR COMPONENT ONTO NEW DOOR				880.00
12	S	BP-SUBLET REPLACE STEERING GEAR ASSY				1760.00
13	S	BP-SUBLET R/I ROOF LINING TO FAC REPAIR				1760.00

Repair
Hp 900/1000
14 days
06/04/2020
@ 1645
EXCESS: 1500
Repair
Res before paint

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
Amount Due			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

TO SECURITY GUARD

Acknowledged by Repairer

PLEASE ALLOW THE UNDERMENTIONED

VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE
TIME

03/04/2020
19:09

PLEASE TEAR ALONG PERFORATED LINE

Attn: Motor Claim department
4234442

Hi, kindly arrange for 4234442

Survey. Thank you!! 62247175

VEHICLE NO XE5495L

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

TOYOTA

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:

www.toyota.com.sg

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1188

ESTIMATE

Load "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226
	Document No 0	Work: 64812518
	Document Date 03/04/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	KAS	FS1EKND	23/01/2020	XE5495L	0	54615	72/OD/XE5495L
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
14	S	BP-SUBLET REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS				4400 6260.00
15	S	BP-SUBLET RESPRAY ACC AFFECTED AREAS				3300 4620.00
16	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00
17	Z	BP-BKT SUPPLY IU BRACKET				26.00
18	Z	TW TOWING CHARGES				150.00
19	S	BP-INTERIOR REMOVE INTERIOR SHATTED GLASS				220.00
20	1	HS4716-03311 VALVE ASSY, AIR BRAKE	1.00	1186.10		1186.10
21	2	H47307-E0351 CONNECTOR SUB-ASSY, ? x su	1.00	37.30		37.30
22	3	H47307-E0310 CONNECTOR SUB-ASSY, ? x su	1.00	40.50		40.50
23	4	H81110-E0682 HEADLAMP ASSY, ? x su	1.00	750.30		750.30
24	5	H81150-E0682 HEADLAMP ASSY, LH ? x su	1.00	750.30		750.30
25	6	HS5563-12181 HOUSING, INSTR CLUSTER ? x su	1.00	1193.60		1193.60
26	7	H55413-E0041 PANEL, INSTR CLUSTER ? x su	1.00	515.00		515.00
27	8	H55412-E0030 PANEL, INSTRUMENT CL ? x su	1.00	355.40		355.40
28	9	HS5542-E0030 PANEL, INSTR CLUSTER ? x su	1.00	320.00		320.00
29	0	HS5541-E0020 PANEL, INSTR CLUSTER ? x su	1.00	207.80		207.80
30	1	H83800-E1170 METER ASSY, COMBINATION ? x su	1.00	2224.60		2224.60
31	2	HS8501-E0020 LINK SUB-ASSY, FR WI ? x su	1.00	157.90		157.90

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4234443

TO SECURITY GUARD

DATE 03/04/2020

TIME 19:09

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

4234443

VEHICLE NO XE5495L

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape

TOYOTA

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:

www.toyota.com.sg

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1188

ESTIMATE

No : 196700086Z
Reg No : MR-8500000-9

Load "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail		Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226
		Document No	Work: 64812518
		Document Date	
		03/04/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	KAS	FS1EKND	23/01/2020	XE5495L	0	54615	72/OD/XE5495L
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
32	3	HS8502-E0030 LINK SUB-ASSY, FR WI ? x su	1.00	205.80		205.80
33	4	H85210-E0100 ARM & BLADE ASSY, FR bro	1.00	399.20		399.20
34	5	H85070-E0100 MOTOR & BRACKET ASSY ? x su	1.00	664.90		664.90
35	6	H44110-E0050 GEAR ASSY, POWER STE ? x su	1.00	8347.90		8347.90
36	7	HS1661-02030 TANK ASSY, RESERVE ? x su	1.00	429.10		429.10
37	8	H86301-E0020 POLE SUB-ASSY, ANTEN ? x su	1.00	44.50		44.50
38	9	H81240-E0090 LAMP ASSY, DOME X su	1.00	49.80		49.80
39	0	H86300-E0020 ANTENNA ? x su	1.00	79.70		79.70
40	1	HS8630-11250 FEEDER SUB ASSY, ANTE ? x su	1.00	45.00		45.00
41	2	HS8135-01051 LAMP ASSY, STEP ? x su	1.00	29.30		29.30
42	3	H81510-E0091 LAMP ASSY, FR TURN s bro	1.00	156.40		156.40
43	4	H85301-E0030 INLET SUB-ASSY, WASH ? x su	1.00	101.90		101.90
44	5	H87915-E0041 COVER, OUTER MIRROR, X su	1.00	18.50		18.50
45	6	H87945-E0011 COVER, OUTER MIRROR, X su	1.00	18.50		18.50
46	7	HS87A0-E0020 MOTER ASSY, POWER ST X su	1.00	755.30		755.30
47	8	H81730-E0081 LAMP ASSY, SIDE TURN X su	1.00	93.20		93.20
48	9	H81239-E0020 SWITCH, COURTESY X su	1.00	23.80		23.80
49	0	H74657-E0010 BRACKET, HAND RAIL ? x su	1.00	17.80		17.80
50	1	H74656-E0020 COVER, HAND RAIL BAR ? x su	1.00	10.80		10.80
51	2	HS7420-61780 GRIP SUB ASSY, INSIDE ? do	1.00	258.80		258.80

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4234444

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 03/04/2020
TIME 19:09

4234444

VEHICLE NO XE5495L

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape

Rep
Lump Sum / L.B.F. (\$

Add Fee: ☐

No. of Trip:

TOYOTA

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:

www.toyota.com.sg

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1188

ESTIMATE

Had "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226
	Document No 0	Work: 64812518
	Document Date 03/04/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	KAS	FS1EKND	23/01/2020	XE5495L	0	54615	72/OD/XE5495L
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
52	3	H74620-E0010 GRIP ASSY, ASSIST, RR RH <i>X sue</i>	1.00	60.00		60.00
53	4	H74734-E0020 COVER, HAND GRIP, NO <i>X sue</i>	1.00	5.50		5.50
54	5	H74733-E0020 COVER, HAND GRIP, NO <i>X sue</i>	1.00	23.30		23.30
55	6	H74603-E0030 GRIP SUB-ASSY, ASSIS <i>X sue</i>	1.00	156.40		156.40
56	7	H74604-E0030 GRIP SUB-ASSY, INSTR <i>X sue</i>	1.00	139.20		139.20
57	8	H62311-E0012 WEATHERSTRIP, FR DOO <i>X sue</i>	1.00	292.30		292.30
58	9	H62312-E0012 WEATHERSTRIP, FR DOO <i>X sue</i>	1.00	292.30		292.30
59	0	H62210-E0040 GARNISH ASSY, FR PILLAR, RH <i>X sue</i>	1.00	98.20		98.20
60	1	H62511-E0091 BOARD, QUARTER TRIM, <i>X sue</i>	1.00	236.80		236.80
61	2	HS2950-39335 RETAINER <i>ne</i>	1.00	32.00		32.00
62	3	H73135-E0050 COVER, SHOULDER BELT <i>X sue</i>	1.00	17.80		17.80
63	4	H73135-E0040 COVER, SHOULDER BELT <i>X sue</i>	1.00	17.80		17.80
64	5	H56121-E0031 MOULDING <i>ne</i>	1.00	457.10		457.10
65	6	H56111-E0120 WINDSHIELD <i>bro</i>	1.00	2356.40		2356.40
66	7	T21000-20 SIKI 182010 SIKI TACK GO! (BLA <i>ne</i>	2.00	108.00		216.00
67	8	T21000-22 SIKI 207. G+P ADHESIVE PRIMER <i>ne</i>	2.00	200.00		400.00
68	9	HS8794-E0020 BRACKET, OUTER MIRRO <i>ne</i>	1.00	43.00		43.00
69	0	H87915-E0030 COVER, OUTER MIRROR, <i>ne</i>	1.00	12.80		12.80
70	1	HS8792-E0010 BRACKET, OUTER MIRRO <i>ne</i>	1.00	30.30		30.30
71	2	H87093-E0140 STAY SUB-ASSY, OUT R <i>H</i>	1.00	333.70		333.70

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4234445

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 03/04/2020
TIME 19:09

4234445

VEHICLE NO XE5495L

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape

TOYOTA

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:

www.toyota.com.sg

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1188

No : 196700086Z
No : MR-8500000-9

ESTIMATE

Load "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail

Account No

Customer Detail

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909
Attn: Motor Claims Dept

S1000003 / ICCI1

Document No

0

Document Date

03/04/2020

M/S Double-Trans Pte Ltd
4 Sungai Kadut Street 2
Sungei Kadut Industrial Estate
Singapore 729226

Work: 64812518

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	KAS	FS1EKND	23/01/2020	XE5495L	0	54615	72/OD/XE5495L
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
72	3	H87919-E0010 BRACKET, OUTER MIRROR	1.00	45.50		45.50
73	4	H87093-E0030 STAY SUB-ASSY, OUT R	1.00	96.70		96.70
74	5	H87910-E0071 MIRROR ASSY, OUTER R	1.00	135.70		135.70
75	6	H75315-EW040 ORNAMENT, RADIATOR G	1.00	276.30		276.30
76	7	H75338-E0030 ORNAMENT, HOOD, LWR	1.00	185.10		185.10
77	8	H75425-E0580 ORNAMENT, FR DOOR, R	2.00	239.80		479.60
78	9	H75353-E0160 ORNAMENT, FR FENDER	2.00	113.70		227.40
79	0	H53814-E0460 EXTENSION, FR FENDER	1.00	648.00		648.00
80	1	HS5571-41010 PANEL, FR CORNER, LWR	1.00	14.50		14.50
81	2	H53804-E0010 REINFORCE SUB-ASSY,	1.00	261.80		261.80
82	3	H55712-E0390 PANEL, COWL TOP, OUT	1.00	677.60		677.60
83	4	H53813-E0650 EXTENSION, FR FENDER	1.00	630.40		630.40
84	5	HSZ950-39050 RETAINER	1.00	1.40		1.40
85	6	H53803-E0010 REINFORCE SUB-ASSY,	1.00	261.80		261.80
86	7	H53601-E0010 LEVER SUB-ASSY, HOOD	1.00	33.00		33.00
87	8	HS8741-51680 CABLE, CONTROL	1.00	103.40		103.40
88	9	HS5339-01010 STRIKER ASSY, HOOD P	2.00	17.30		34.60
89	0	HS7918-01331 LOCK ASSY, LID	2.00	90.70		181.40
90	1	HS7918-21010 HANDLE, LID LOCK	2.00	24.00		48.00
91	2	H53540-E0010 LEVER ASSY, AUXILIAR	1.00	70.20		70.20

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4234446

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 03/04/2020
TIME 19:09

4234446

VEHICLE NO XE5495L

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Inchcape

Borneo Motors

Rep
Lump Sum / L.R. /

Add
No. of T

TOYOTA

Borneo Motors (Singapore) Pte Ltd

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:

www.toyota.com.sg

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1189

ESTIMATE

Load "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail

Account No

Customer Detail

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909
Attn: Motor Claims Dept

S1000003 / ICCI1

Document No

0

Document Date

03/04/2020

M/S Double-Trans Pte Ltd
4 Sungei Kadut Street 2
Sungei Kadut Industrial Estate
Singapore 729226

Work: 64812518

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	KAS	FS1EKND	23/01/2020	XE5495L	0	54615	72/OD/XE5495L
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
92	3	HS7639-01051 STAY ASSY, DUMPER ? xsv	1.00	151.60		151.60
93	4	HS5337-81400 MEMBER, HOOD ? xsv	1.00	50.50		50.50
94	5	HS7682-11310 WEATHERSTRIP, FR CORN ? am x	1.00	82.70		82.70
95	6	HS7686-11010 SEAL, FR PANEL, LWR RH ca	1.00	103.40		103.40
96	7	HS7426-21140 CAP ms	1.00	9.80		9.80
97	8	HS5300-E0010 GRIP ASSY, FR PANEL, cat	1.00	298.00		298.00
98	9	HS7653-11460 EMBLEM ca	1.00	211.60		211.60
99	0	HS3111-E0130 GRILLE, RADIATOR ca	1.00	2121.70		2121.70
100	1	HSZ950-39069 RETAINER ca	20.00	1.10		22.00
101	2	HS7630-71010 REINFORCEMENT SUB AS ? xsv	1.00	107.40		107.40
102	3	HSZ159-40001 SCREW, W/WASHER ca	5.00	1.80		9.00
103	4	HS7682-11300 WEATHERSTRIP, FR CORN ? xsv	1.00	226.60		226.60
104	5	HS7681-11160 WEATHERSTRIP, FR CRNE ? xsv	1.00	54.20		54.20
105	6	H55246-E0010 SEAL, FR PANEL, LWR ca	1.00	99.90		99.90
106	7	HSZ950-39307 RETAINER ca	1.00	2.80		2.80
107	8	HS8727-42250 HOSE, DEF ? xsv	1.00	45.30		45.30
108	9	H55990-E0030 NOZZLE ASSY, DEFROST ? cat	1.00	267.30		267.30
109	0	HS8727-42240 HOSE, DEF ? xsv	1.00	45.30		45.30
110	1	HS5530-31290 GUSSET SUB ASSY, INST ? xsv	1.00	54.20		54.20
111	2	HS5531-31430 BRACKET, INSTR PANEL ? xsv	1.00	14.50		14.50

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4234447

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 03/04/2020
TIME 19:09

4234447

VEHICLE NO XE5495L

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape

TOYOTA

No : 196700086Z
g No : MR-8500000-9

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyota.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

ESTIMATE

Load "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226
	Document No 0	Work: 64812518
	Document Date 03/04/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	KAS	FS1EKND	23/01/2020	XE5495L	0	54615	72/OD/XE5495L
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
112	3	HS5530-31330 GUSSET SUB ASSY, INST ? x su	1.00	41.30		41.30
113	4	HS5535-E0010 COVER, SPEAKER HOLE, ? x su	1.00	54.20		54.20
114	5	HS8615-31150 COVER, SPEAKER ? x su	1.00	50.50		50.50
115	6	HS8724-31050 DUCT, HEATER TO FOOT ? cm	1.00	48.50		48.50
116	7	HS8724-21120 DUCT, HEATER TO FOOT ? x su	1.00	54.30		54.30
117	8	HS5835-E0070 DUCT, HEATER TO REGI ? cm	1.00	253.30		253.30
118	9	HS5843-E0020 DUCT, HEATER TO REGI ? x su	1.00	99.70		99.70
119	0	HS5108-E0011 BRACE SUB-ASSY, PEDAL SUPPORT TO CC ? bt	1.00	532.30		532.30
120	1	HS5530-12091 PANEL SUB ASSY, INSTR ? bt	1.00	1240.80		1240.80
121	2	HSZ950-24048 CLIP	4.00	2.20		8.80
122	3	HSZ950-24049 CLIP	1.00	4.80		4.80
123	4	HSZ950-39183 RETAINER	4.00	8.80		35.20
124	5	H67831-E0010 COVER, FR DOOR SERVI ? x su	1.00	7.80		7.80
125	6	H69810-E0051 REGULATOR ASSY, DOOR ? bt	1.00	821.20		821.20
126	7	HS6946-01150 STRIKER ASSY, DOOR, ?	1.00	29.50		29.50
127	8	H69310-E0032 LOCK ASSY, FR DOOR, bt	1.00	228.10		228.10
128	9	HS6942-11620 LINK, DOOR LOCK X su	1.00	14.80		14.80
129	0	H69210-E0030 HANDLE ASSY, FR DOOR X su	1.00	115.40		115.40
130	1	HS6911-E0020 BRACKET, INSIDE HAND X su	1.00	17.30		17.30
131	2	H69205-E0010 HANDLE SUB-ASSY, FR X su	1.00	55.00		55.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4234448

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 03/04/2020
TIME 19:09

4234448

VEHICLE NO XE5495L

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Rep
Lump Sum / L.P.F. (2)

Add Fee: []

No. of Trip:

TOYOTA

No : 196700086Z
 Reg No : MR-8500000-9

ESTIMATE

Load "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyota.com.sg
 Toyota Bodycare Centre
 No. 2 Pandan Crescent
 Singapore 128462
 Tel no.: 6631 1188

Account Detail

China Taiping Insurance (S) Pte Ltd
 3 Anson Road
 #16-00 Springleaf Tower
 Singapore 079909
 Attn: Motor Claims Dept

Account No

S1000003 / ICCI1

Document No

0

Document Date

03/04/2020

Customer Detail

M/S Double-Trans Pte Ltd
 4 Sungei Kadut Street 2
 Sungei Kadut Industrial Estate
 Singapore 729226

Work: 64812518

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	KAS	FS1EKND	23/01/2020	XE5495L	0	54615	72/OD/XE5495L
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
132	3	HSZ950-39242 RETAINER <i>X sva</i>	5.00	4.00		20.00
133	4	HS6921-01091 LINK ASSY, DOOR CHECK <i>bt</i>	1.00	93.50		93.50
134	5	HSZ950-39242 RETAINER <i>mu</i>	1.00	4.00		4.00
135	6	H74630-E0020 GRIP ASSY, DOOR ASSI <i>? bt</i>	1.00	118.90		118.90
136	7	H74210-E0010 ARMREST ASSY, DOOR <i>? xsv</i>	1.00	47.50		47.50
137	8	H67605-E0150 PANEL SUB-ASSY, FR D <i>de</i>	1.00	643.70		643.70
138	9	H74645-E0010 ESCUTCHEON, DOOR ASS <i>mu</i>	1.00	8.80		8.80
139	0	H74231-E0010 PANEL, FR DOOR ARMRE <i>? xsv</i>	1.00	125.40		125.40
140	1	H84810-E0070 SWITCH ASSY, POWER W <i>? xsv</i>	1.00	177.90		177.90
141	2	H74201-E0021 PANEL SUB-ASSY, FR A <i>? bt</i>	1.00	75.20		75.20
142	3	H74103-E0020 DOOR SUB-ASSY, FR AS <i>? xsv</i>	1.00	111.20		111.20
143	4	H67605-E0150 PANEL SUB-ASSY, FR D <i>X sva</i>	1.00	643.70		643.70
144	5	H68171-E0040 WEATHERSTRIP, DOOR G <i>mu</i>	1.00	152.90		152.90
145	6	HS6845-01632 GLASS ASSY, DOOR WIND <i>bro</i>	1.00	495.80		495.80
146	7	H67403-E0020 FRAME SUB-ASSY, FR D <i>? xsv</i>	1.00	46.80		46.80
147	8	H67875-E0010 WEATHERSTRIP, FR DOOR <i>NO.4 RH ? mu</i>	1.00	81.00		81.00
148	9	HS6840-11240 OSCILLATOR-PROOF SUB <i>? xsv</i>	1.00	77.80		77.80
149	0	H67485-E0010 SEAL, RR DOOR DIVISI <i>? xsv</i>	1.00	27.30		27.30
150	1	H67861-E0010 WEATHERSTRIP, FR DOO <i>mu</i>	1.00	217.60		217.60
151	2	HS6801-E0040 GARNISH SUB-ASSY, DO <i>? xsv</i>	1.00	250.00		250.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4234449

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
 VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 03/04/2020
 TIME 19:09

4234449

VEHICLE NO XE5495L

CUSTOMER

SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Rep
 Lurip Sum / f.e.

Adm
 NO. OF T

TOYOTA

No : 196700086Z
g No : MR-8500000-9

ESTIMATE

Load "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Page 8 of 12
Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyota.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909
Attn: Motor Claims Dept

Account No

S1000003 / ICCI1

Document No

0

Document Date

03/04/2020

Customer Detail

M/S Double-Trans Pte Ltd
4 Sungei Kadut Street 2
Sungei Kadut Industrial Estate
Singapore 729226

Work: 64812518

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	KAS	FS1EKND	23/01/2020	XE5495L	0	54615	72/OD/XE5495L
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
152	3	H67123-E0010 BRACKET, FR DOOR OUT ? XSV	1.00	149.90		149.90
153	4	H53831-E0110 PANEL, FR FENDER SID de -	1.00	521.00		521.00
154	5	HS5370-52460 BRACKET SUB ASSY, FR ? XSV bt	1.00	142.90		142.90
155	6	HS530C-E0010 SUPPORT SUB-ASSY, ST ? bt	1.00	339.20		339.20
156	7	H53875-E0020 BRACKET, AIR DUCT CL ? XSV	1.00	116.40		116.40
157	8	HS5370-51270 BRACKET SUB ASSY, FR ? XSV	1.00	57.70		57.70
158	9	H76911-E0010 MUDGUARD, SIDE, RH sc	1.00	240.10		240.10
159	0	HS2950-39274 RETAINER m	10.00	1.70		17.00
160	1	H76621-E0041 MUDGUARD, FR FENDER, ? XSV	1.00	81.20		81.20
161	2	HS5835-34810 SPLASHBOARD, SIDE ? XSV	1.00	141.70		141.70
162	3	H53738-E0120 PLATE, FR APRON TO C ? XSV	1.00	139.40		139.40
163	4	HS5830-81080 SPLASHBOARD SUB ASSY ? XSV	1.00	213.60		213.60
164	5	H51772-E0020 PLATE, STEP, LH ? XSV	1.00	257.80		257.80
165	6	H51771-E0050 BRACKET, TILT CAB ST ? XSV	1.00	285.00		285.00
166	7	HS5832-11090 COVER, STEP LWR, RH ? XSV	1.00	135.40		135.40
167	8	H57035-E0010 REINFORCEMENT SUB-AS ? PANEL SUB ASS, FR S bt	1.00	355.40		355.40
168	9	HS5703-E0010 SUPPORT SUB-ASSY, FR ? bt	1.00	322.00		322.00
169	0	HS5571-51010 STAY, FR CORNER PANEL ? ne	1.00	19.00		19.00
170	1	H51773-E0140 COVER, STEP PLATE, R ? Cra	1.00	332.00		332.00
171	2	HS2950-39187 RETAINER ? XSV Nec	3.00	2.10		6.30

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO XE5495L

CUSTOMER

DATE 03/04/2020
TIME 19:09

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Rep
Lump Sum / 100

4234450

4234450

Online Service Booking:

www.toyota.com.sg

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1188

TOYOTA

No : 196700086Z
Bg No : MR-8500000-9

ESTIMATE

Load "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909
Attn: Motor Claims Dept

Account No

S1000003 / ICCI1

Document No

0

Document Date

03/04/2020

Customer Detail

M/S Double-Trans Pte Ltd
4 Sungei Kadut Street 2
Sungei Kadut Industrial Estate
Singapore 729226

Work: 64812518

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	KAS	FS1EKND	23/01/2020	XE5495L	0	54615	72/OD/XE5495L
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
172	3	HSZ950-39347 RETAINER ? 3.30 Nec ✓	4.00	3.30		13.20
173	4	H61453-E0130 COVER, FR STEP, RH 3.30	1.00	410.60		410.60
174	5	HSZ950-39347 RETAINER	1.00	3.30		3.30
175	6	H67913-E0020 PLATE, DOOR SCUFF, RCH	1.00	52.50		52.50
176	7	H61415-E0011 EXTENSION, ROCKER, O ? bt	1.00	260.50		260.50
177	8	H61135-E0030 REINFORCEMENT, FR BODY PILLAR, UPR ? bt	1.00	80.50		80.50
178	9	H61108-E0012 REINFORCEMENT SUB-ASSY, FR PLR, LWF ? bt	1.00	239.30		239.30
179	0	H61131-E0120 PILLAR, FR BODY, UPR ? bt	1.00	603.40		603.40
180	1	H61611-E0030 PANEL, QUARTER, RH ? bt	1.00	1046.30		1046.30
181	2	H65621-E0010 PANEL, SIDE GATE ? bt	1.00	107.40		107.40
182	3	H61106-E0021 PILLAR SUB-ASSY, FR, RH ? bt	1.00	260.50		260.50
183	4	H67001-E0380 PANEL SUB-ASSY, FR DOOR, RH Due	1.00	2875.20		2875.20
184	5	HS6927-01310 HINGE ASSY, DOOR, bt	1.00	189.90		189.90
185	6	HS6927-01310 HINGE ASSY, DOOR, bt	1.00	189.90		189.90
186	7	H55701-E0040 PANEL SUB-ASSY, COWL ? xsu	1.00	1130.70		1130.70
187	8	H52211-E0010 CUSHION, BODY MOUNT ? xsu	1.00	8.80		8.80
188	9	HS6114-51010 GUSSET, FR BODY PILL ? xsu	1.00	57.50		57.50
189	0	HS6118-11010 BRACKET, INSTRUMENT ? xsu	1.00	8.80		8.80
190	1	H61235-E0030 BRACKET, ASSIST GRIP ? xsu	1.00	31.50		31.50
191	2	H61163-E0031 PILLAR, FR BODY, LWR INNER RH ? bt	1.00	316.20		316.20

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4234451

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 03/04/2020
TIME 19:09

4234451

VEHICLE NO XE5495L

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Rep
Lump Sum / L.R.f. (t

Add F
NO. of Tri

TOYOTA

No : 196700086Z
Ag No : MR-8500000-9

Load "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

ESTIMATE

Page 11 of 12
Borneo Motors (Singapore) Pte Ltd

Page 10 of 12
Borneo Motors (Singapore) Pte Ltd

Online Service Booking:

www.toyota.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909
Attn: Motor Claims Dept

Account No

S1000003 / ICCI1

Document No

0

Document Date

03/04/2020

Customer Detail

M/S Double-Trans Pte Ltd
4 Sungei Kadut Street 2
Sungei Kadut Industrial Estate
Singapore 729226

Work: 64812518

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	KAS	FS1EKND	23/01/2020	XE5495L	0	54615	72/OD/XE5495L
Chassis No		Engine No	Terms	Service Engineer	Vehicle In	Collected On	
JHDFS1EKNXXX10048		E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
192	3	H55101-E0100 PANEL SUB-ASSY, DASH ? x sue	1.00	1970.30		1970.30
193	4	H55700-E0120 COWL btr ? x sue	1.00	2385.90		2385.90
194	5	HS6114-61010 GUSSET, FR BODY PILL ? x sue	1.00	57.50		57.50
195	6	HS6118-21010 BRACKET, INSTRUMENT ? x sue	1.00	8.80		8.80
196	7	H61164-E0011 PILLAR, FR BODY, LWR ? x sue	1.00	316.20		316.20
197	8	HS51QD-E0032 APRON, STEP, RH ? x sue	1.00	146.20		146.20
198	9	HS51QH-E0130 MUDGUARD, STEP ? x sue	1.00	47.50		47.50
199	0	HS7622-12050 HOLDER MUDGUARD ? x sue	1.00	33.00		33.00
200	1	HS510U-E0140 SUPPORT SUB-ASSY, ST ? x sue	1.00	721.30		721.30
201	2	HS5065-E0071 STAY SUB-ASSY, STEP, ? x sue	1.00	155.40		155.40
202	3	HS5066-E0071 STAY SUB-ASSY, STEP, ? x sue	1.00	155.40		155.40
203	4	HS510V-E0100 SUPPORT SUB-ASSY, ST ? x sue	1.00	711.60		711.60
204	5	HS506J-E0121 LID SUB-ASSY, STEPO ? x sue	1.00	71.00		71.00
205	6	HS51Q1-E0222 COVER, STEP, RH ? x sue	1.00	384.70		384.70
206	7	H51771-E0050 BRACKET, TILT CAB ST ? x sue	1.00	285.00		285.00
207	8	HS5107-72381 STAY SUB ASSY, STEP ? x sue	1.00	94.70		94.70
208	9	H53102-E0060 GRILLE SUB-ASSY, RAD ? x sue	1.00	1023.10		1023.10
209	0	HS5218-21010 REINFORCE, FR BUMPER ? x sue	1.00	267.00		267.00
210	1	HS5219-81120 BRACKET, GRILLE ? x sue	1.00	29.50		29.50
211	2	HS5110-E0121 MEMBER, ENGINE COVER ? x sue	1.00	895.90		895.90

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4234452

TO SECURITY GUARD

4234452

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 03/04/2020
TIME 19:09

VEHICLE NO XE5495L

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape

TOYOTA

Page 11 of 12
Borneo Motors (Singapore) Pte Ltd

No : 196700086Z
No : MR-8500000-9

ESTIMATE

Online Service Booking:
www.toyota.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1100

Load "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICC11	M/S Double-Trans Pte Ltd 4 Sungei Kadut Street 2 Sungei Kadut Industrial Estate Singapore 729226
	Document No 0	Work: 64812518
	Document Date 03/04/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	KAS	FS1EKND	23/01/2020	XE5495L	0	54615	72/OD/XE5495L
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JHDFS1EKNXXX10048	E13CAT10536	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
212	3	HS5052-E0160 STAY SUB-ASSY, FR UN ? x sue	1.00	282.30		282.30
213	4	H52712-E0020 MOULDING, FR BUMPER M ✓	1.00	17.00		17.00
214	5	H52713-E0010 MOULDING, FR BUMPER X sue	1.00	17.00		17.00
215	6	HS5218-71100 GARNISH, BUMPER, RH ? x sue	1.00	172.60		172.60
216	7	HS5218-81100 GARNISH, BUMPER, LH X sue	1.00	154.90		154.90
217	8	HS5218-81090 GARNISH, BUMPER, LH X sue	1.00	172.10		172.10
218	9	H53035-E0070 BRACKET SUB-ASSY, HE ? x sue	1.00	202.60		202.60
219	0	HS8112-E0020 STAY, HEADLAMP, NO.2 ? x sue	1.00	49.30		49.30
220	1	HS8116-E0010 STAY, HEADLAMP, NO.2 ? x sue	1.00	49.30		49.30
221	2	H53036-E0050 BRACKET SUB-ASSY, HE ? x sue	1.00	202.60		202.60
222	3	H52101-E0K21 BUMPER SUB-ASSY, FR bt	1.00	2265.00		2265.00
223	4	H52102-E0640 EXTENSION SUB-ASSY, FR BUMPER, RH bt	1.00	237.10		237.10
224	5	H52103-E0460 EXTENSION SUB-ASSY, FR BUMPER, LH X sue	1.00	237.10		237.10

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 65,809.80	88,525.00
		Labour 456.00	GST 7.00%
		Materials 22,259.20	6,196.75
		Lubrication/Fluid 0.00	Less 0.00
		Others 0.00	Amount Due 94,721.75

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 03/04/2020
TIME 19:09

VEHICLE NO XE5495L

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

4234453

4234453